EASA AD No.: 2015-0007

AD No.: 2015-0007 Date: 15 January 2015 Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation. This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

Design Approval	Holder's Name :	Type/Model designation(s) :			
Design Approval Holder's Name : DASSAULT AVIATION		Fan Jet Falcon, Mystère-Falcon 200, Mystère-Falcon 20-(x)5 and Mystère-Falcon 50 aeroplane			
TCDS Numbers:	France No. 103 (incl. b	is and ter) and EASA.A.062			
Foreign AD :	Not applicable				
Supersedure :	None				
ATA 52	Doors – Crew / Passenger Door – Inspection / Adjustment / Operational Test				
Manufacturer(s):	Dassault Aviation				
Applicability:	Fan Jet Falcon (FJF) aeroplanes, all models, all serial numbers (S/N). Mystère-Falcon (MF) 200 and MF20GF aeroplanes, all S/N. MF20-C5, -D5, -E5 and -F5 aeroplanes, all S/N. MF50 aeroplanes, all S/N.				
Reason:	During approach for landing, a Mystère-Falcon 20-X5 lost the main entrance door at an altitude of 7 000 feet. The flight crew maintained control of the aeroplane to land uneventfully. The results of the preliminary technical investigations concluded that the cause of this event could be either a broken cable, or an unlocked safety catch, associated with one or two deficient micro switches.				
	This condition, if not detected and corrected, could lead to in-flight opening and/or detachment of the Crew / Passenger door, possibly resulting in loss of control of the aeroplane, and/or injury to persons on the ground.				
	To address this potential unsafe condition, Dassault Aviation issued Service Bulletins (SB) F20-789, F200-133 and MF50-531, providing instructions for inspection / adjustment, as well as an operational test of the Crew / Passenger door closure.				
	For the reasons described above, this AD requires a one-time accomplishment of a functional test/check of the MED closure/warning system. It also requires are inspection and operational test of the Crew / Passenger door and, depending on				

EASA AD No.: 2015-0007

	findings	, applicable co	rrective actions.				
Effective Date:	29 January 2015						
Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: (1) Within 65 days after the effective date of this AD, unless accomplished within 6 months preceding the effective date of this AD, accomplish the maintenance procedure (MP) described in Table 1 of this AD, as applicable. The instructions as contained in the applicable Aircraft Maintenance Manual (AMM) task, or Work Card (WC), as referenced in Table 1 of this AD, as applicable, are acceptable to accomplish this MP. Before next flight after accomplishment of the MP, depending on findings, accomplish the applicable corrective actions. Table 1						
	Δ	eroplane(s)	rintion	Document Ref.			
	FJF and MF20 (all models)		MP Description Passenger/Crew Door Warning System Functional Test		AMM task 52-70-1 page block 301		
	М	F200	Door Locking Indicator System Check		WC 702.0 §1e		
	MI	F50	Door Lock India	cation Check	AMM task 52-10-00-610-801-05		
	operational test of the Crew / Passenger door, and depending on findings, accomplish the applicable corrective actions in accordance with the instructions of the applicable Dassault Aviation SB, as specified in Table 2 of this AD, as applicable. Table 2						
		. , , , , , , , , , , , , , , , , , , ,			le Dassault SB		
		FJF and MF20 (all models)		F20-789			
		MF200		F200-133 MF50-531			
		MF50		IVIFO	0-531		
Ref. Publications:	Dassault Aviation SB F20-789 dated 09 December 2014. Dassault Aviation SB F200-133 dated 09 December 2014.						
	Dassaul	It Aviation SB F	-200-133 dated (9 December 2	014.		
	Dassaul Dassaul	It Aviation SB F	F200-133 dated (MF50-531 dated	09 December 2	014. 2014.		
	Dassaul Dassaul The use	It Aviation SB F It Aviation SB N of later approv	F200-133 dated (MF50-531 dated	09 December 2 09 December 2 hese documer	014.		
	Dassaul Dassaul The use complia	It Aviation SB F It Aviation SB N of later appro- nce with the re	F200-133 dated (MF50-531 dated ved revisions of the second secon	09 December 2 09 December 2 hese documer s AD.	014. 2014.		
	Dassaul The use complia Dassaul	It Aviation SB It Aviation SB It Aviation SB It of later approvance with the restrict AMI	F200-133 dated (MF50-531 dated wed revisions of the quirements of the	December 2 09 December 2 hese documer is AD. 52.	014. 2014.		
	Dassaul The use complia Dassaul	It Aviation SB In Aviation SB In Aviation SB In It Aviation SB In It Aviation SB In It Aviation AMINITED IN IT IN	F200-133 dated (MF50-531 dated ved revisions of the factor	December 2 09 December 2 hese documer is AD. 52. 45007.	014. 2014.		
	Dassaul The use complia Dassaul Dassaul Dassaul	It Aviation SB F It Aviation SB N It of later approvance with the re It-Aviation AMN It-Aviation AMN	F200-133 dated (MF50-531 dated ved revisions of the full F20: DMD 117 M F20-(x)5: DMD	December 2 09 December 2 hese documer is AD. 52. 45007.	014. 2014.		
Remarks :	Dassaul The use complia Dassaul Dassaul Dassaul Dassaul	It Aviation SB In Aviation SB In Aviation SB In State of later approximate with the result-Aviation AMINIT-Aviation AMINITALITY (A Prince of the Aviation AMINITALITY)	F200-133 dated (MF50-531 dated ved revisions of the quirements of the MF20: DMD 117 MF20-(x)5: DMD 14 MF200: DMD 14 MF50: DMD 14 MF50: DMD 14	December 2 09 December 2 hese documer is AD. 52. 45007. 29214-3.	014. 2014.		

EASA AD No.: 2015-0007

until 30 December 2014. No comments were received during the consultation period.

- 3. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu.
- 4. For any question concerning the technical content of the requirements in this AD, please contact your **Dassault Falcon Technical Center**:
 - For Europe, Middle East and Africa based operators:
 (33) 1 47 11 37 37 / Fax: (33) 1 47 11 89 49
 - For USA, Canada and Mexico based operators:
 (1) 800-2FALCON (2325266) / Fax: (1) 201 541 4740
 - · All other areas:

(1) 201 541 4747 / Fax: (1) 201 541 4740