GSAC

# **AIRWORTHINESS DIRECTIVE**

# released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1999-222(A) R1 In case of any difficulty, reference should be made to the French original issue.

## **CAP AVIATION**

#### **CAP 10 B airplanes**

Airspeed limitation for Snap (Flick) manoeuvres (ATA 57)

#### 1. <u>APPLICABILITY</u> :

CAP 10 B, all serial number.

## 2. COMPLIANCE :

Further to a failure in flight of a CAP 10 B wings, the following measures are made mandatory at the effective date of this Airworthiness Directive.

# 3. ACTIONS :

A) The airspeed for positive and negative snap (flick) manoeuvres must never exceed 180 kph IAS (97 kts).

The present Airworthiness Directive will be revised soon in order to prescribe a revision of the airplane flight manual and the display of a placard in the cockpit.

Before the next flight, proceed to a spar inspection, as described in Avions Mudry & Cie SB No. 15 (BS CAP 10 B-57-003) and to a coating inspection as described in Cap Aviation SB 990501. Neverthless a ferry flight (no acrobatic manoeuvres allowed) may be performed to go to the place where the inspection is to be carried out.

If during these inspection :

- a) No cracks of the spar or unsticking of the coating are discovered, return, the airplane to service, with the limitations defined hereabove in A)
- b) A crack of the spare, or unsticking of the coating are discovered, before the next flight, contact the manufacturer in order to define a repair method which will have to be DGAC approved.

..../....

n/JB

