| | AIRWORTHINESS DIRECTIVE | | Distribution: | Issue date: | Page: | | |
|--|---|--|--|--------------------------------------|--|-----|--|
| | No F-2003-432 | | | В | December 10, 2003 | 1/2 | |
| Direction générale de l'aviation civile France | This Airworthiness Directive is published by the DGAC: On behalf of EASA, the Primary Airworthiness Authority for taffected product as the Registration Airworthiness Authority for the affected aircraft | | | Authority for the | Translation of "consigne de navigabilité" of same number. In case of difficulty, reference should be made to the French text. | | |
| GSAC publication | No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry. | | | | | | |
| Corresponding foreign Airworthiness Directive(s): | | | Airwor | Airworthiness Directive(s) replaced: | | | |
| Not applicable | | | 2002-043-65, cancelled by its revision 1 | | | | |
| Person in charge of airworthiness: | | | Type(| s): | | | |
| ATR | | | ATR 72 aircraft | | | | |
| Type certificate(s) No. 176 | | | | | | | |
| TCDS No. 176 | | | | • | | | |
| ATA chapter(s | | | | | | | |
| Equipment/furnishings - The | | | | mal/acoust | ical insulation materials | | |

1. **EFFECTIVITY**:

ATR 72 -102, -202, -212 and -212A aircraft models, all serial numbers, on which:

- at least one of ATR modifications 3890 or 4204 has been embodied,

but,

- none of ATR modifications 5117 or 5322 (Service Bulletin (SB) ATR 72-25-1074 Revision 1) has been embodied.

2. REASONS:

After some incidents initiated by electrical short circuit behind side wall, in which the flammability characteristics of thermal/acoustical insulation material made from metallized polyethyleneteraphthalate (MPET) may have been a contributing factor, the Certification Authority decided to improve flammability standards for thermal/acoustical insulation materials.

As consequence, new requirements have been created and the MPET (also called metallized MYLAR) shall be replaced on all aeroplanes.

Although no incident has never been experienced on ATR aeroplanes equipped with MPET, the actions mandated by the present Airworthiness Directive (AD) are intended to improve the fire safety standard of the insulation blankets installed on ATR aircraft.

This AD mandates embodiement of SB ATR 72-25-1074 Revision 1 which introduces replacement of new thermal/acoustical insulation materials.



AIRWORTHINESS DIRECTIVE No F-2003-432

Distribution:

Issue date:

December 10, 2003

Page: **2/2**

3. MANDATORY ACTIONS AND COMPLIANCE TIMES:

In order to comply with the requirements, the following measures are rendered mandatory from the effective date of this AD:

During the next "eight year calendar check" and at the latest before May 31, 2009, remove the MPET insulation blankets and replace them with the new ones in accordance with the instructions given by SB ATR 72-25-1074 Revision 1.

Aircraft on which SB ATR 72-25-1074 has been embodied at the original issue must be put in conformity with Revision 1 of SB ATR 72-25-1074 before May 31, 2009.

4. REFERENCE PUBLICATION:

Service Bulletin ATR 72-25-1074 Revision 1 Any later approved revision of this SB is acceptable.

5. **EFFECTIVE DATE**:

December 20, 2003

6. REMARK:

For questions concerning the technical contents of this AD's requirements, contact:

ATR - Yves OTTOGALI - Fax : 33 5 62216718

7. APPROVAL:

This AD is approved under EASA reference No 1434 dated December 02, 2003.