



SERVIÇO PÚBLICO FEDERAL

DEPARTAMENTO DE AVIAÇÃO CIVIL

BRAZILIAN AIRWORTHINESS DIRECTIVE

EFFECTIVE DATE

30 Oct. 2004

AD No.:

2004-10-02

The following Airworthiness Directive (AD), issued by the Departamento de Aviação Civil (DAC) in accordance with provisions of Chapter IV, Title III of Código Brasileiro de Aeronáutica - Law No. 7,565 dated 19 December 1986 - and Regulamento Brasileiro de Homologação Aeronáutica (RBHA) 39, applies to all aircraft registered in the Registro Aeronáutico Brasileiro. No person may operate an aircraft to which this AD applies, unless it has previously complied with the requirements established herein.

AD No. 2004-10-02 - EMBRAER - Amendment 39-1042.

APPLICABILITY:

This Airworthiness Directive is applicable to all Embraer ERJ-170() aircraft models in operation.

CANCELLATION / REVISION:

Not applicable.

REASON:

It has been found the occurrence of cases of failure of the engine fire handle internal circuit, which can result on non-closure of the fuel shut-off valves and failure of the extinguisher agent discharge in case of engine fire indication.

Since this condition may occur in other airplanes of the same type and affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit without prior notice.

REQUIRED ACTION:

Inspection and replacement, if needed, of the engine fire handles.

COMPLIANCE:

Required as indicated below, unless already accomplished.

- (a) Within the next 600 flight hours or 180 calendar days, whichever occurs first, after the effective date of this AD, inspect the engine fire handles to verify the P/N installed.
 - (1) If the handles installed are of P/N 1-7054-2 or 2-7054-2, replace them before next flight with new ones bearing P/N 1-7054-1 or 2-7054-1, respectively.
 - (2) If the handles installed are not of P/N 1-7054-2 or 2-7054-2, no further action is required.
- (b) After the effective date of this AD, it is not allowed to install the engine fire handles P/N 1-7054-2 or 2-7054-2 on any Embraer ERJ-170() aircraft model.

The detailed instructions and procedures to accomplish this AD are described in the Embraer Service Bulletin No. 170-26-0001, original issue, or further revisions approved by the CTA.

Record compliance with this AD in the applicable maintenance log book.

CONTACT:

For additional technical information, contact:

Centro Técnico Aeroespacial - CTA
Instituto de Fomento e Coordenação Industrial - IFI
Divisão de Certificação de Aviação Civil - CAVC
Praça Mal. Eduardo Gomes, 50 - Vila das Acácias
Caixa Postal 6001
Fax: 55 (12) 3941-4766
12231-970 - São José dos Campos - SP, BRAZIL.
e-mail: pds@ifi.cta.br

For acquisition, contact:

Departamento de Aviação Civil - DAC
Seção de Publicações do DAC (4GAB-4)
R. Santa Luzia, 651, 2º Mezanino, Centro
Fax: 55 (21) 3814-6929
20030-040 - Rio de Janeiro - RJ, BRAZIL.
e-mail: publicacoes@dac.gov.br

APPROVAL:

CLÁUDIO PASSOS SIMÃO - Ten Cel Eng
Chief of the Civil Aviation Certification Division
IFI/CTA

VENÂNCIO ALVARENGA GOMES - Cel Eng
Director of the Industrial Coordination and Fostering Institute
CTA

NOTE: Original in Portuguese language signed and available in the files of the Registro Geral de Aeronavegabilidade (RGA/TE-1/STE) of the Departamento de Aviação Civil.