

AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL - BRAZIL

BRAZILIAN AIRWORTHINESS DIRECTIVE

AD No.: 2006-05-08R1 Effective Date: 25 Feb. 2008

The following Brazilian Airworthiness Directive (AD), issued by the Agência Nacional de Aviação Civil (ANAC) in accordance with provisions of Chapter IV, Title III of Código Brasileiro de Aeronáutica - Law No. 7,565 dated 19 December 1986 - and Regulamento Brasileiro de Homologação Aeronáutica (RBHA) 39, applies to all aircraft registered in the Registro Aeronáutico Brasileiro. No person may operate an aircraft to which this AD applies, unless it has previously complied with the requirements established herein.

AD No. 2006-05-08R1 - EMBRAER - Amendment 39-1227.

APPLICABILITY:

This Airworthiness Directive is applicable to all Embraer ERJ-190 aircraft models in operation, equipped with Air Data Smart Probes (ADSP) P/N 2015G2H2H-4(), 2015G2H2H-5(), 2015G2H2H-6() or 2015G2H2H-7().

CANCELLATION / REVISION:

This AD cancels and supersedes the AD No. 2006-05-08 original issue – Amdt 39-1137, dated 19 June 2006, and is being issued to present a terminating action for the repetitive inspections.

REASON:

It has been found the occurrence of moisture in the pneumatic passage between the pitot port and the pressure sensors in the ADSP. That moisture may freeze and block the sensors, causing erroneous information to the Air Data System.

Since this condition affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit.

REQUIRED ACTION:

Inspection of the pitot drain hole and removal of moisture in the ADSP pressure lines.

COMPLIANCE:

Required as indicated below, unless already accomplished.

- (a) Within the next 600 flight hours after 19 June 2006, the effective date of the original issue of this AD, and thereafter at intervals that do not exceeds 600 flight hours, carry out a detailed inspection (DET) on the four ADSPs drain hole and, if it is the case, remove the accumulated moisture.
- (b) The installation of ADSP P/N 2015G2H2H-8() in accordance with the procedures detailed in the Embraer Service Bulletin No. 190-34-0008 original issue, or further revisions approved by ANAC, constitutes terminal action to the repetitive inspections foreseen in the item (a) above.
- **NOTE 1:** It is forbidden the reinstallation of ADSPs P/N 2015G2H2H-4(), 2015G2H2H-5(), 2015G2H2H-6() or 2015G2H2H-7() after installation of ADSPs P/N 2015G2H2H-8().
- **NOTE 2:** For the purpose of this AD, a detailed inspection (DET) is: "An intensive examination of a specific item, installation or assembly to detect damage, failure or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirrors, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate access procedures may be required."

The detailed instructions and procedures to accomplish this AD are described in the Embraer Service Bulletins Nos. 190-34-0003 original issue, or 190-34-0008 original issue, as applicable, or in its respective further revisions approved by the ANAC.

Record compliance with this AD in the applicable maintenance log book.

CONTINUATION OF AD No.: 2006-05-08R1 - AMENDMENT 39-1227

CONTACT:

For additional technical information, contact:

National Civil Aviation Agency (ANAC)

Aeronautical Products Certification Branch (GGCP)

Av. Cassiano Ricardo, 521, Bloco B, 2º andar, Parque Residencial Aquarius

Fax: 55 (12) 3797-2330

12246-870 – São José dos Campos - SP, BRAZIL.

E-mail: pac@anac.gov.br

For acquisition, contact:

National Civil Aviation Agency (ANAC)

Publications Branch

R. Santa Luzia, 651, 2º Mezanino, Centro

Fax: 55 (21) 3814-6929

20030-040 - Rio de Janeiro - RJ, BRAZIL.

E-mail: publicacoes@anac.gov.br

APPROVAL:

CLÁUDIO PASSOS SIMÃO General Manager GGCP

SOLANGE PAIVA VIEIRA Director-President ANAC

NOTE: Original in Portuguese language signed and available in the files of the Aeronautical Products Certification Branch (GGCP) of the National Agency of Civil Aviation (ANAC).

PAGE No.: 2/2