

[Federal Register, Volume 91 Number 36 (Tuesday, February 24, 2026)]

[Rules and Regulations]

[Pages 8721-8723]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2026-03613]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2026-1334; Project Identifier AD-2025-01336-E; Amendment 39-23269; AD 2026-04-09]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Engines

AGENCY:

Federal Aviation Administration (FAA), DOT.

ACTION:

Final rule; request for comments.

SUMMARY:

The FAA is adopting a new airworthiness directive (AD) for certain General Electric Company (GE) Model GEnx-1B64, GEnx-1B64/P1, GEnx-1B64/P2, GEnx-1B67, GEnx-1B67/P1, GEnx-1B67/P2, GEnx-1B70, GEnx-1B70/75/P1, GEnx-1B70/75/P2, GEnx-1B70/P1, GEnx-1B70/P2, GEnx-1B70C/P1, GEnx-1B70C/P2, GEnx-1B74/75/P1, GEnx-1B74/75/P2, GEnx-1B76/P2, Genx-1B76A/P2, GEnx-2B67, GEnx-2B67/P, and GEnx-2B67B engines. This AD was prompted by a report of a quality escape for certain high-pressure compressor (HPC) stage 5 blisks manufactured from a single forged ingot with a nonconforming indication. This AD requires replacement of certain HPC stage 5 blisks with parts eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

DATES:

This AD is effective March 11, 2026.

The FAA must receive comments on this AD by April 10, 2026.

ADDRESSES:

You may send comments, using the procedures found in [14 CFR 11.43](#) and [11.45](#), by any of the following methods:

- *Federal eRulemaking Portal*: Go to *regulations.gov*. Follow the instructions for submitting comments.
- *Fax*: (202) 493-2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2026-1334; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Itanza Young, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (206) 482-6306; email: itanza.n.young@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA-2026-1334; Project Identifier AD-2025-01336-E” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in [14 CFR 11.35](#), the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) ([5 U.S.C. 552](#)), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Itanza Young, 2200 South 216th Street, Des Moines, WA 98198. Any

commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received a report of a quality escape on certain HPC stage 5 blisks that are installed on certain GE Model GEnx-1B64, GEnx-1B64/P1, GEnx-1B64/P2, GEnx-1B67, GEnx-1B67/P1, GEnx-1B67/P2, GEnx-1B70, GEnx-1B70/75/P1, GEnx-1B70/75/P2, GEnx-1B70/P1, GEnx-1B70/P2, GEnx-1B70C/P1, GEnx-1B70C/P2, GEnx-1B74/75/P1, GEnx-1B74/75/P2, GEnx-1B76/P2, GEnx-1B76A/P2, GEnx-2B67, GEnx-2B67/P, and GEnx-2B67B engines. A manufacturer investigation revealed that a nonconforming indication was discovered in a single forged ingot used to manufacture the affected parts, potentially making them susceptible to failure earlier than previously determined. The FAA is issuing this AD to prevent fracture and subsequent uncontained release of certain HPC stage 5 blisks. This condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the airplane. The FAA is issuing this AD to address the unsafe condition on these products.

FAA's Determination

The FAA is issuing this AD because the agency determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires replacement of certain HPC stage 5 blisks with parts eligible for installation.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) ([5 U.S.C. 551 et seq.](#)) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

The FAA justifies waiving notice and comment prior to adoption of this rule because no domestic operators are affected by this AD. It is unlikely that the FAA will receive any adverse comments or useful information about this AD from any U.S. operator.

Accordingly, notice and opportunity for prior public comment are unnecessary, pursuant to [5 U.S.C. 553\(b\)](#). In addition, for the foregoing reason(s), the FAA finds that good cause exists pursuant to [5 U.S.C. 553\(d\)](#) for making this amendment effective in less than 30 days.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to [5 U.S.C. 553](#) to adopt a rule without prior notice and comment. Because FAA has

determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace HPC stage 5 blisk	8 work-hours × \$85 per hour = \$680	\$260,951 (prorated)	\$261,631	\$0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under [Executive Order 13132](#). This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under [Executive Order 12866](#), and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in [14 CFR Part 39](#)

- Air transportation
- Aircraft
- Aviation safety
- Incorporation by reference

- Safety

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends [14 CFR part 39](#) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: [49 U.S.C. 106\(g\)](#), [40113](#), [44701](#).

§.39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2026-04-09 General Electric Company: Amendment 39-23269; Docket No. FAA-2026-1334; Project Identifier AD-2025-01336-E.

(a) Effective Date

This airworthiness directive (AD) is effective March 11, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company Model GEnx-1B64, GEnx-1B64/P1, GEnx-1B64/P2, GEnx-1B67, GEnx-1B67/P1, GEnx-1B67/P2, GEnx-1B70, GEnx-1B70/75/P1, GEnx-1B70/75/P2, GEnx-1B70/P1, GEnx-1B70/P2, GEnx-1B70C/P1, GEnx-1B70C/P2, GEnx-1B74/75/P1, GEnx-1B74/75/P2, GEnx-1B76/P2, GEnx-1B76A/P2, GEnx-2B67, GEnx-2B67/P, and GEnx-2B67B engines with a high-pressure compressor (HPC) stage 5 blisk having part number (P/N) 2357M35P02 installed and a serial number (S/N) referenced in paragraphs (c)(1) through (3) of this AD:

(1) S/N TMT214T8

(2) S/N TMT214T9

(3) S/N TMT218UA

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by a report of certain HPC stage 5 blisks manufactured from a single forged ingot with a nonconforming indication. The FAA is issuing this AD to prevent fracture and subsequent

uncontained release of certain HPC stage 5 blisks. The unsafe condition, if not addressed, could result in uncontained debris release, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purpose of this AD:

(1) A part “eligible for installation” is any HPC stage 5 blisk that does not have a P/N and S/N identified in paragraph (c) of this AD.

(2) A “piece-part exposure” is when the affected part is removed from the engine and completely disassembled.

(h) Required Actions

At the next piece-part exposure or before exceeding 7,700 cycles since new, whichever occurs first after the effective date of this AD, remove the affected HPC stage 5 blisk from service and replace with a part eligible for installation.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, AIR-520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in [14 CFR 39.19](#). In accordance with [14 CFR 39.19](#), send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the AIR-520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Itanza Young, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (206) 482-6306; email: itanza.n.young@faa.gov.

(k) Material Incorporated by Reference

None.

Issued on February 19, 2026.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[[FR Doc. 2026-03613](#) Filed 2-23-26; 8:45 am]

BILLING CODE 4910-13-P