

[Federal Register, Volume 91 Number 150 (Thursday, August 6, 2026)]
[Rules and Regulations]
[Pages 50698-50701]
From the Federal Register Online via the Government Publishing Office [www.gpo.gov]
[FR Doc No: 2026-15936]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-3985; Project Identifier AD-2025-00493-T; Amendment 39-23423; AD 2026-15-11]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY:

Federal Aviation Administration (FAA), DOT.

ACTION:

Final rule.

SUMMARY:

The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-8, 737-9, and 737-8200 airplanes. This AD was prompted by reports of cracks in the bear strap at the forward upper corner of the forward galley door cutout. This AD requires an inspection of the fuselage skin for existing repairs and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES:

This AD is effective September 10, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 10, 2026.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2025-3985; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The

address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2025-3985.

FOR FURTHER INFORMATION CONTACT:

Luis Cortez-Muniz, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3958; email: luis.a.cortez-muniz@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend [14 CFR part 39](#) by adding an AD that would apply to certain The Boeing Company Model 737-8, 737-9, and 737-8200 airplanes. The NPRM was published in the **Federal Register** on November 25, 2025 ([90 FR 53245](#)). The NPRM was prompted by reports of cracks in the bear strap at the forward upper corner of the forward galley door cutout. In the NPRM, the FAA proposed to require an inspection of the fuselage skin for existing repairs and applicable on-condition actions. The FAA is issuing this AD to address cracks in the fuselage skin and bear strap, which may lead to the inability of the principal structural element to sustain limit loads and adversely affect the structural integrity of the airplane.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from The Boeing Company who supported the NPRM without change.

The FAA received additional comments from two commenters, including The Foundation for Aviation Safety and United Airlines (United). The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Explain How the Root Cause Is Addressed

The Foundation for Aviation Safety asked what the FAA and Boeing are doing to address the root cause of the defect. The commenter also asked if a structural defect is important enough to immediately ground an airplane after it is detected, why is the inspection for defects not accomplished long before the proposed compliance time.

The FAA is issuing this AD to address the unsafe condition on in-service airplanes. The required compliance times for the initial inspection and on-condition repetitive inspections and repair were

established to ensure any crack is detected and repaired before the crack reaches critical length with multiple opportunities for detection. The rulemaking timeline was based on Boeing 737 fleet findings, supporting analysis, and the severity of the effect on the airplane (*i.e.*, safety consequences) if cracking propagates beyond a critical length. The FAA determined that the required actions and compliance times provide an acceptable level of safety. In addition, Boeing is introducing changes to the manufacturing process that address the root cause of the unsafe condition on in-production airplanes.

Request To Clarify Whether Certain Repairs Apply to Condition 1

United stated that Table 1, Condition 1 of the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024, specifies to contact Boeing for alternative inspection instructions for any repair found during the general visual inspection of the fuselage skin. The commenter noted that Boeing Alert Service Bulletin 737-53A1408, dated December 20, 2024, does not provide guidance for repairs accomplished per the structural repair manual (SRM) limits in 737-8 and 737-9 SRM 53-00-01, for fuselage skin blend out and bear strap blend out repair. United requested clarification on whether repairs performed within allowable damage limits should be considered “repairs found” for the purposes of Table 1, or if such repairs may be treated as unrepaired areas, “no repair found.”

The FAA notes that Condition 1 applies to any repair, which includes blend out repairs accomplished per the SRM within the allowable damage limits. Such blend out repairs need to be evaluated to determine whether the repetitive inspection interval specified in the service information provides an acceptable level of safety for those repairs. Depending on findings, it may be necessary to reduce the inspection interval. The FAA has not changed this AD in response to this comment.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under [1 CFR Part 51](#)

The FAA reviewed Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024. This material specifies procedures for an external general visual inspection of the fuselage skin for any repair and applicable on-condition actions. On-condition actions include repetitive detailed inspection for cracking of the fuselage skin; repetitive external surface high frequency eddy current (HFEC) inspections of the fuselage skin at certain fastener locations and the fuselage skin and bear strap along the edge of door corner radius for cracking; repetitive external subsurface low frequency eddy current (LFEC) inspection of the bear strap at certain fastener locations for cracking; and obtaining instructions from Boeing for alternative inspections or for crack repair.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 471 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
External general visual inspection for repairs	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$40,035.
External detailed and eddy current inspections for cracks	Up to 4 work-hours × \$85 per hour = \$340 per inspection cycle	0	Up to \$340	Up to \$160,140 per inspection cycle.

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs or for the alternative inspections specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under [Executive Order 13132](#). This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under [Executive Order 12866](#),
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in [14 CFR Part 39](#)

- Air transportation
- Aircraft
- Aviation safety
- Incorporation by reference
- Safety

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends [14 CFR part 39](#) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: [49 U.S.C. 106\(g\)](#), [40113](#), [44701](#).

[§.39.13](#) [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2026-15-11 The Boeing Company: Amendment 39-23423; Docket No. FAA-2025-3985; Project Identifier AD-2025-00493-T.

(a) Effective Date

This airworthiness directive (AD) is effective September 10, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-8, 737-9, and 737-8200 airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks in the bear strap at the forward upper corner of the forward galley door cutout. The FAA is issuing this AD to address cracks in the fuselage skin and bear strap, which may lead to the inability of the principal structural element to sustain limit loads and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-53A1408, dated December 20, 2024, which is referred to in Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024.

(h) Exceptions to Requirements Bulletin Specifications

(1) Where Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024, refer to the original issue date of Requirements Bulletin 737-53A1408 RB, this AD requires using the effective date of this AD.

(2) Where Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024, specifies contacting Boeing for repair instructions or for alternative inspections, this AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in [14 CFR 39.19](#). In accordance with [14 CFR 39.19](#), send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Additional Information

(1) For more information about this AD, contact Luis Cortez-Muniz, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3958; email: luis.a.cortez-muniz@faa.gov.

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under [5 U.S.C. 552\(a\)](#) and [1 CFR part 51](#).

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-53A1408 RB, dated December 20, 2024.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website *myboeingfleet.com*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on August 3, 2026.

Brian Knaup,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[[FR Doc. 2026-15936](#) Filed 8-5-26; 8:45 am]

BILLING CODE 4910-13-P