

CESSNA AIRCRAFT COMPANY
MODEL 172RG
SERVICE MANUAL

SUPPLEMENTAL INSPECTION NUMBER: 32-10-01

1. **TITLE:**
Main Landing Gear Retraction System Inspection

2. **EFFECTIVITY**
172RG0001 thru 172RG1191

INSPECTION COMPLIANCE

ALL USAGE:	INITIAL	3,000 Hours	or	10 Years (NOTE)
	REPEAT	500 Hours	or	5 Years (NOTE)

NOTE: Refer to Note 1, Section 2A-14-00.

3. **PURPOSE**
To ensure structural integrity of the main landing gear retraction system.

4. **INSPECTION INSTRUCTIONS**

- A. Check airplane records to verify that Service Kit SK172-151 has been installed. If not, install Service Kit SK172-151 with this inspection.
- B. Check airplane records to verify that SEB01-2 has been accomplished. If not, complete SEB01-2 with this inspection.
- C. Remove seats and carpeting as required to gain access to the plate above the actuator.
- D. Inspect the actuator, the actuator support assembly and the rod end bearings for cracks and corrosion.
 - (1) Clean area before inspecting if grime or debris is present.
 - (2) Conduct a surface eddy current inspection for cracks in the location indicated by Figure 1, Detail E on both sides of the main landing gear actuator body. Refer to Section 2A-13-01, Nondestructive Inspection Methods and Requirements, Eddy Current Inspection - Surface Inspection, for additional instructions.
- E. Inspect the actuator pins, gears and sectors for cracks and wear.
- F. Refer to Figure 1, Details B, C, and D. Inspect the main landing gear pivot assemblies for cracks and corrosion in the areas shown.
 - (1) Clean area before inspecting if grime or debris is present.
- G. Inspect the downlock support assembly for cracks or corrosion.
 - (1) Clean area before inspecting if grime or debris is present.
- H. Install parts removed for access.

5. **ACCESS AND DETECTABLE CRACK SIZE**

ACCESS/LOCATION

Main Landing Gear

DETECTABLE CRACK SIZE

Not Allowed

6. **INSPECTION METHOD**
Visual and Eddy Current

7. **REPAIR/MODIFICATION**

- A. If cracks are detected in the actuator, the actuator or actuator body must be replaced.
- B. If no cracks are detected in the actuator, rework in accordance with SEB01-2 Rev. 2 or latest revision.
- C. If cracks are detected in the pivot assembly, the pivot assembly must be replaced.


CESSNA AIRCRAFT COMPANY
MODEL 172RG
SERVICE MANUAL

- D. If no cracks are detected in the pivot assembly, rework in accordance with SEB90-1 Rev. 3, SK172-151.

8. COMMENTS

CESSNA AIRCRAFT COMPANY
MODEL 172RG
 SERVICE MANUAL

B18103



0510T1007


MAIN LANDING GEAR RETRACTION SYSTEM INSPECTION
 Figure 1 (Sheet 1)

CESSNA AIRCRAFT COMPANY
MODEL 172RG
SERVICE MANUAL


B18118

1820085-1
DEBURR TOOL
(REFERENCE)

CUTTING
EDGE



DEBURR THIS RADIUS
BEFORE INSPECTION
IF REQUIRED



DETAIL D


(PIVOT ASSEMBLY SHAFT AND
SPLINE WITH BUSHING REMOVED)

CONTINUOUS
EDGE

2.28 INCHES
DIAMETER BORE

1.00 INCH
DIAMETER BORE

INSPECTION
AREA



NOTE: INSPECT CONTINUOUS EDGE OF
SADDLE-SHAPED HOLE AND
CIRCUMFERENCE OF 2.28 INCHES
DIAMETER BORE AND STEP.

DETAIL E

MAIN LANDING GEAR RETRACTION SYSTEM INSPECTION
Figure 1 (Sheet 2)

D0541T1006
E0541T1005