EASA AD No.: 2012-0034R1

	EASA AIRWORTHINESS DIRECTIVE						
		AD No.: 2012-0034R1					
	***	Date: 24 September 2015  Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with					
		Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.					
	This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate						

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I. Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

L	EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].						
	<b>Design Approval</b> AIRBUS	Holder's Name :	Type/Model designation(s): A330 and A340 aeroplanes				
	TCDS Numbers:	EASA.A.004, EASA.A.015					
	Foreign AD:	Not applicable					
	Revision: This AD revises EASA AD 2012-0034 dated 29 February 2012.						
-	ATA 32	Landing Gear – Nose Landing Gear (NLG) Retraction Actuator – Overhaul					
	Manufacturer(s):	Airbus (formerly Airbus Industrie)					
	Applicability:	Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342 and A330-343 aeroplanes, all manufacturer serial numbers (MSN), and					
		Airbus A340-211, A340-212, A340-213, A340-311, A340-312 a aeroplanes, all MSN.					
	Reason:	An A330 aeroplane experienced an in-flight turn back due to inability to retract the NLG after take-off. The subsequent technical investigations revealed that the NLG retraction actuator eye-end fitting was detached from the retraction actuation rod, that both the eye-end male threads and piston rod female threads were almost completely stripped, and that there was evidence of significant corrosion on these parts. Further investigations have shown that corrosion caused the retraction actuator eye failure.					
			rected, could lead to NLG collapse after touchdown, nage to the aeroplane and injury to the occupants.				
	Consequently, EASA issued AD 2012-0034 to require replacement of NLG retraction actuator with a new or overhauled actuator. That AD defined the Time Between Overhaul (TBO) for the NLG retraction actual be 10 years.						

EASA AD No.: 2012-0034R1

	Since that AD was issued, the NLG retraction actuator overhaul tasks were							
		included in Revision 14 of A330 and A340 Maintenance Review Board Report (MRBR) (hereafter referred to as "the applicable MRBR" in this						
		For the reason described above, this AD is revised to allow replacement the NLG retraction actuator using the instructions and the compliance specified in the applicable MRBR task.						
	Effective Date:	Revi	Revision 1: 01 October 2015					
		Orig	Original issue: 14 March 2012					
		Req	equired as indicated, unless accomplished previously:					
	and Compliance Time(s):	(1) Within the compliance time indicated in Table 1 of this AD, and, thereafter, at intervals not to exceed 10 years (TBO) or within the compliance times specified in the applicable MRBR, replace the NLC retraction actuator with a new or overhauled part in accordance with instructions of Airbus Service Bulletin (SB) A330-32-3255 or SB A34 32-4291, as applicable to aeroplane type, or in accordance with the instructions of the applicable MRBR (Maintenance Significant Item 32.21.00).						
				Table 1 - Initial NLG Retract	tion Actuator overhaul			
			Compliance Time (whichever occurs later, A or B)					
			Before exceeding 10 years by the NLG retraction actuator since its first flight on an aeroplane, or since its first flight following its last overhaul, or within the compliance times specified in the applicable MRBR					
			В	If, on 14 March 2012 [the effective date of this AD at original issue], the NLG retraction actuator has accumulated more than 8 years and less than 14 years since its first flight on an aeroplane	Within 24 months after 14 March 2012 [the effective date of this AD at original issue] without exceeding 15 years since the NLG retraction actuator first flight on an aeroplane			
			If, on 14 March 2012 [the effective date of this AD at original issue], the NLG retraction actuator has accumulated 14 years or more since its first flight on an aeroplane	Within 12 months after 14 March 2012 [the effective date of this AD at original issue]				
	(2) After 14 March 2012 [the effective date of this AD at original is not install on an aeroplane any NLG retraction actuator, unless compliance with the requirements of this AD.							
	Ref. Publications :	Airbus SB A330-32-3255 original issue, dated 13 October 2011.						
		Airbus SB A340-32-4291 original issue, dated 13 October 2011.						
			Airbus A330 MRBR at Revision 14, published in June 2013.					
		Airbus A340 MRBR at Revision 14, published in June 2013.  The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.						

EASA AD No.: 2012-0034R1

## Remarks:

- 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
- The original issue of this AD was posted on 30 January 2012 as PAD 12-005 for consultation until 27 February 2012. No comments were received during the consultation period.
- 3. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu.
- For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS SAS –Airworthiness Office – EIAL, E- mail: <u>airworthiness.A330-A340@airbus.com</u>.