EASA AD No.: 2014-0170

AD No.: 2014-0170 Date: 17 July 2014 Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14/4) exemption].

Design Approva	l Holder's Name:	Type/Model designation(s):
PILATUS AIRCI	RAFT Ltd.	PC-12 aeroplanes
TCDS Number:	EASA.A.089	
Foreign AD:	Not applicable	
Supersedure:	This AD supersedes EASA AD	2013-0031 dated 18 February 2013.
ATA 05	Time Limits / Maintenance Checks – Airworthiness Limitation Section – Amendment / Implementation	
		/
Manufacturer(s):	Pilatus Aircraft Ltd.	
Applicability:	PC-12, PC-12/45, PC-12/47, and PC-12/47E aeroplanes, all manufacturer serial numbers.	
Reason:	The maintenance instructions and airworthiness limitations applicable to the Structure and Components of PC-12 aeroplanes are specified in the Aircraft Maintenance Manual (AMM) under Chapter 4, Airworthiness Limitation Sectio (ALS).	
	mandatory actions for contin	n the ALS document have been identified as ued airworthiness and failure to comply with thes ould potentially lead to an unsafe condition.
	for PC-12, PC-12/45 and PC issue 11 for PC-12/47E aero	issued Pilatus PC-12 AMM report 02049 issue 28 c-12/47 aeroplanes and PC-12 AMM report 02300 eplanes to incorporate new repetitive inspection drive arms because of the detection of cracked
	2013-0031, which is superse	ove, this AD retains the requirements of EASA Aleded, and requires implementation of the new and/or airworthiness limitations.
Effective Date:	31 July 2014	

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

- (1) From the effective date of this AD, accomplish the following actions, as detailed in Chapter 4 of the AMM report (the ALS document) specified in Table 1 of this AD, as applicable to aeroplane model:
 - (1.1) Replace each component before exceeding the applicable life limit, and
 - (1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.

The next inspection of the inboard flap drive arms must be accomplished within 150 flight hours or within three months, whichever occurs first after the effective date of this AD.

(2) In case of finding discrepancies (as defined in Chapter 4 of the AMM report specified in Table 1 of this AD, as applicable to aeroplane model) during accomplishment of any task as required by paragraph (1) of this AD, within the applicable compliance time specified in Chapter 4 of the relevant AMM report, accomplish the applicable maintenance procedures for corrective actions in accordance with the approved maintenance documentation. If no compliance time is identified in Chapter 4 of the relevant AMM report, accomplish the applicable corrective actions before next flight. If a detected discrepancy is not identified in Chapter 4 of the relevant AMM report, before next flight, contact Pilatus Aircraft Ltd. for approved instructions and accomplish those instructions accordingly.

Table 1 – Applicable AMM Report / ALS Document

Aeroplane Model	AMM Report / ALS Document
PC-12, PC-12/45, PC-12/47	Chapter 4 of AMM report 02049, issue 28, dated 31 May 2014
PC-12/47E	Chapter 4 of AMM report 02300, issue 11, dated 31 May 2014

- (3) Compliance with the requirements of paragraphs (1) and (2) of this AD can be demonstrated by:
 - (3.1) Revising as follows the approved Aircraft Maintenance Programme and standard practices on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane:

Incorporate all applicable maintenance instructions and associated airworthiness limitations specified in Chapter 4 of AMM report 02049 issue 28 or AMM report 02300 issue 11, dated 31 May 2014,

and

(3.2) Complying with the approved Aircraft Maintenance Programme described in paragraph (3.1) of this AD.

Ref. Publications:

Pilatus PC-12 Structural, Component and Miscellaneous – Airworthiness Limitations, Chapter 4 of AMM report 02049 issue 28 dated 31 May 2014, for PC-12, PC-12/45, PC-12/47 aeroplanes.

Pilatus PC-12 Structural, Component and Miscellaneous – Airworthiness Limitations, Chapter 4 of AMM report 02300 issue 11 dated 31 May 2014, for PC-12/47E aeroplanes.

The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.

EASA AD No.: 2014-0170

Remarks:

- 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
- 2. This AD was posted on 23 June 2014 as PAD 14-102 for consultation until 07 July 2014. No comments were received during the consultation period.
- 3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu.
- 4. For any question concerning the technical content of the requirements in this AD, please contact:

PILATUS AIRCRAFT LTD., Customer Support Manager, CH-6371 STANS, Switzerland.

Tel.: +41 (0)41 619 33 33 Fax: +41 (0)41 619 73 11.

E-mail: SupportPC12@pilatus-aircraft.com.

