

EASA	EMERGENCY AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2015-0068-E</p> <p>Date: 29 April 2015</p> <p>Note: This Emergency Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
<p>Design Approval Holder's Name: AIRBUS HELICOPTERS</p>	<p>Type/Model designation(s): AS 365 N3 helicopters</p>	
TCDS Number:	EASA.R.105	
Foreign AD:	Not applicable	
Supersedure:	None	
ATA 11	Placards and Markings – Installation / Replacement	
Manufacturer(s):	Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale)	
Applicability:	<p>AS 365 N3 helicopters, all serial numbers (s/n), without external life rafts installed, except helicopters modified in accordance with Airbus Helicopters modification (MOD) 0711B68, and</p> <p>AS 365 N3 helicopters all s/n, with external life rafts installed, except helicopters modified in accordance with Airbus Helicopters MOD 0711B67 and MOD 0711B68.</p>	
Reason:	<p>During helicopter delivery after manufacturing Airbus Helicopters identified that placards providing instructions for the jettison procedure of the cabin doors (emergency exit), was not systematically installed or not installed in a proper location.</p> <p>This condition, if not corrected, could prevent the timely evacuation of the helicopter in case of an emergency.</p> <p>To address this potential unsafe condition, Airbus Helicopters issued Alert Service Bulletin (ASB) No. AS365-11.00.02 to provide placard installation and replacement instructions.</p> <p>For the reasons described above, this AD requires installation or replacement of the affected internally located evacuation cabin door jettison procedure placards.</p>	
Effective Date:	01 May 2015	

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) Within 14 days after the effective date of this AD, determine the presence and/or location of the cabin door jettison procedure placards and, if missing install and, if incorrectly located, replace the placard(s) in accordance with the instructions of paragraph 3B of Airbus Helicopters ASB AS365-11.00.02 Revision 2. (2) Replacement and installation of placards, accomplished before the effective date of this AD, in accordance with the instructions of Eurocopter Service Bulletin (SB) AS365-11.00.02 original issue or Airbus Helicopters ASB No. AS365-11.00.02 Revision 1 is acceptable to comply with requirements of paragraph (1) of this AD.
<p>Ref. Publications:</p>	<p>Airbus Helicopters ASB No. AS365-11.00.02 Revision 1 dated 26 January 2015, or Revision 2 dated 22 April 2015.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p> <p>Eurocopter SB AS365-11.00.02 original issue dated 26 October 2011.</p>
<p>Remarks:</p>	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full public consultation process. 3. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact: Airbus Helicopters (EBSESB) – Aéroport de Marseille Provence 13725 Marignane Cedex, France Telephone +33 (4) 42 85 97 97, Facsimile +33 (4) 42 85 99 66 E-mail: contact.msm.ah@airbus.com.