



Airworthiness Directive

AD No.: 2016-0087

Issued: 03 May 2016

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

FINMECCANICA S.p.A.

Type/Model designation(s):

AB139 and AW139 helicopters

Effective Date: 10 May 2016

TCDS Number(s): EASA.R.006

Foreign AD: Not applicable

Supersedure: None

ATA 62 – Main Rotor – Main Rotor Damper – Inspection / Replacement

Manufacturer(s):

Finmeccanica S.p.A., Helicopter Division (FHD, formerly AgustaWestland S.p.A., Agusta S.p.A.), AgustaWestland Philadelphia Corporation (formerly Agusta Aerospace Corporation).

Applicability:

AB139 and AW139 helicopters, all serial numbers (s/n) except s/n 31004, s/n 31007 and s/n 41237, if equipped with Main Rotor (MR) damper Part Number (P/N) 3G6220V01351 or P/N 3G6220V01352.

Reason:

In-service failures have been reported of MR dampers P/N 3G6220V01351 and P/N 3G6220V01352 on AW139 helicopters. In some cases, these failures occurred at the eye end and body lugs with disconnection in flight of the damper. The results of preliminary investigations determined that a combination of several factors could lead to disconnection of a MR damper.

This condition, if not detected and corrected, could lead to loss of the lead-lag damping function of the MR blade, possibly resulting in damage to adjacent critical rotors components and consequent reduced control of the helicopter.

To initially address this issue, AgustaWestland published Mandatory Bollettino Tecnico (BT) 139-410 in 2015 and later FHD published BT 139-446, providing interim inspection instructions.



Since these BTs were issued, further investigations highlighted the need for a one-time non-destructive inspection (NDI) followed by repetitive detailed visual inspections to detect cracks on the MR damper rod end and body end.

Consequently, FHD issued Mandatory BT 139-450 that supersedes Mandatory BT 139-410 and Mandatory BT 139-446 incorporating the inspections contained in these two BTs and, in addition, providing instructions for a one-time dye penetrant inspection of a limited area of MR damper (rod end and body end) for cracks and repetitive detailed visual inspections for cracks in the same area.

For the reasons described above, this AD requires various one-time and repetitive inspections of the MR damper and a torque check and, depending on findings, accomplishment of applicable corrective action(s).

This AD is considered an interim action. If, as a result of the on-going investigation, a terminating action is later identified, further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection / Torque Check:

- (1) Within the compliance times defined in Table 1 of this AD, depending on the Flight Hours (FH) accumulated by each MR damper, as applicable, accomplish a one-time dye penetrant inspection of the rod end and body end of each MR damper in accordance with the instructions of Part I of FHD BT 139-450.

Table 1 – MR damper one-time dye penetrant inspection

FH accumulated (see Note 1 of this AD)	Compliance Time
Less than 300	Before exceeding 300 FH, or within 30 FH after the effective date of this AD, whichever occurs later
300 or more	Within 30 FH after the effective date of this AD, or at the first MR damper removal, whichever occurs first

Note 1: The number of FH specified in Table 1 of this AD are those accumulated by the MR damper since its first installation on a helicopter.

- (2) Following the inspection as required by paragraph (1) of this AD, each time a replacement rod end P/N M006-01H004-041 or P/N M006-01H004-045 not marked as per FHD BT 139-450 is installed, within 300 FH after installation of that rod end, accomplish a one-time dye penetrant inspection of that rod end of the MR damper in accordance with the instructions of Part II of FHD BT 139-450.
- (3) Following the inspection as required by paragraph (1) of this AD, before the first flight of each day, or after the last flight of each day, accomplish a detailed visual inspection of the rod end



and body end of each affected MR damper in accordance with the instructions of Part III of FHD BT 139-450.

- (4) Within 30 FH after the effective date of this AD and, thereafter, at intervals not to exceed 10 FH, inspect the rod end and body end bearings of each affected MR damper in accordance with the instructions of Part IV of FHD BT 139-450.
- (5) For a helicopter equipped with an affected MR damper, having a s/n specified in Part V of FHD BT 139-450: Within 30 FH after the effective date of this AD and, thereafter, at intervals not to exceed 20 FH, visually inspect the rod end broached ring nut of each affected MR damper, in accordance with the instructions of Part V of FHD BT 139-450. These repetitive inspections can be terminated when an affected MR damper accumulates 600 FH since first installation on a helicopter.
- (6) Within 50 FH after the effective date of this AD, or within 100 FH after the latest inspection in accordance with the instructions of FHD BT 139-446 Part I accomplished before the effective date of this AD, and, thereafter, at intervals not to exceed 100 FH, accomplish a bearing friction inspection of the body end and rod end bearings of each affected MR damper, and a detailed inspection of the anti-rotation block of each affected MR damper, in accordance with the instructions of Part VI of FHD BT 139-450.
- (7) For a helicopter equipped with an affected MR damper, having a s/n specified in Part VII of FHD BT 139-450: Within 50 FH after the effective date of this AD, accomplish a visual inspection of each affected MR damper rod end installation and a torque check of the MR damper broached ring nut, in accordance with the instructions of Part VII of FHD BT 139-450.

Corrective actions:

- (8) If, during the inspection as required by paragraph (7) of this AD, any special washer P/N 356220A05051 is found installed, before next flight, replace that special washer P/N 356220A05051 with a new washer P/N 356220A05052 in accordance with the instructions of Part VII of FHD BT 139-450.
- (9) If, during any inspection as required by paragraph (1), (2), (3) or (5) of this AD, as applicable, any crack or other damage is detected, before next flight, contact FHD in accordance with the instructions of FHD BT 139-450 and, if the discrepancy is confirmed, replace the affected part with a serviceable part.
- (10) If, during any inspection or torque check as required by paragraph (4), (6) or (7) of this AD, as applicable, any discrepancy as defined in FHD BT 139-450 is detected, before next flight, accomplish the applicable corrective action(s) as specified in, and in accordance with, the instructions of FHD BT 139-450.
- (11) Accomplishment of corrective action(s) on a helicopter, as required by paragraph (8), (9) or (10) of this AD, as applicable, does not constitute terminating action for any repetitive action as required by this AD for that helicopter.



Conditions for installation of parts on a helicopter:

- (12) From the effective date of this AD, installation of a MR Damper P/N 3G6220V01351 or P/N 3G6220V01352 on a helicopter is allowed, provided that the part has not exceeded 300 FH since its first installation on a helicopter, unless it has passed an inspection in accordance with the instructions of Part I of FHD BT 139-450, and provided that, following installation, the part is inspected as required by, and within the compliance times as specified in, this AD.
- (13) From the effective date of this AD, installation on a helicopter of an affected MR damper, having a s/n specified in Part VIII of FHD BT 139-450, is allowed, provided that, prior to installation, each broached ring nut of that MR damper has passed a torque check in accordance with the instructions of Part VIII of FHD BT 139-450.

Ref. Publications:

FHD BT 139-410 Rev. A dated 12 February 2016.

FHD BT 139-446 original issue dated 12 February 2016.

FHD BT 139-450 original issue dated 20 April 2016.

The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning the technical content of the requirements in this AD, please contact: Finmeccanica S.p.A., Helicopter Division. E-mail: CSE.AW139.AW@finmeccanica.com.

