



Emergency Airworthiness Directive

AD No.: 2016-0104-E

[Correction: 09 June 2016]

Issued: 02 June 2016

Note: This Emergency Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 332 L2 and EC 225 LP helicopters

Effective Date: 02 June 2016

TCDS Number(s): EASA.R.002

Foreign AD: Not applicable

Supersedure: None

FLIGHT PROHIBITION

Manufacturer(s):

Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale)

Applicability:

AS 332 L2 and EC 225 LP helicopters, all manufacturer serial numbers.

Reason:

Following a fatal accident that occurred in Norway to an EC 225 LP helicopter, indicating in-flight detachment of the main rotor hub from the main gearbox (MGB), EASA issued Emergency AD 2016-0089-E to require, as a precautionary measure, the accomplishment of one-time inspections. Investigation is on-going to identify the root cause of this accident.

The review of the data reported in accomplishing AD 2016-0089-E, revealed installation findings for the MGB upper deck fittings of the three MGB suspension bars. Prompted by these findings, EASA issued superseding AD 2016-0103-E for further inspection and replacement instructions for correct installation of the MGB suspension bars and attachment fittings.

Soon after EASA AD 2016-0103-E was issued, a second preliminary report from the investigation board indicated metallurgical findings of fatigue and surface degradation in the outer race of a



second stage planet gear of the MGB epi-cyclic module. At this time, it cannot be determined if this is a contributing causal factor or subsequent failure from another initiating factor.

Pending further investigation to determine the root cause(s) of the reported damage, and development of mitigating measures by Airbus Helicopters, EASA has decided, as an additional precautionary measure, to temporarily ground the fleet.

For the reason described above, this AD prohibits flight of the AS 332 L2 and EC 225 LP helicopters.

This AD is republished to clarify the note in the “Required Action(s) and Compliance Time(s)” section of this AD and to amend the contact details of Airbus Helicopters in the “Remarks” section of this AD.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously.

- (1) From the effective date of this AD, do not operate any AS 332 L2 and EC 225 LP helicopter, except as specified in paragraph (2) of this AD.
- (2) A single ferry flight without passengers is allowed to a maintenance location where the helicopter grounding, as required by paragraph (1) of this AD, can be accomplished in adequate storage conditions.

Note: Pursuant to Art.1 (2)(a) of Regulation (EC) 216/2008, defining the scope of EASA competences and its legal remit, the requirement of paragraph (1) of this AD does not apply to AS 332 L2 and EC 225 LP helicopters while carrying out military, customs, police, search and rescue, firefighting, coastguard or similar activities or services.

Ref. Publications:

None.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full consultation process.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning this AD, please contact:
Airbus Helicopters (Technical Support) – Aéroport de Marseille Provence 13725 Marignane Cedex, France. Telephone +33 (4) 42 85 97 97, Fax +33 (4) 42 85 99 66,
E-mail: TechnicalSupport.Helicopters@airbus.com.

