

Airworthiness Directive

AD No.: 2020-0061

Issued: 17 March 2020

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 332 L2 and EC 225 LP helicopters

Effective Date: 31 March 2020

TCDS Number(s): EASA.R.002

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2019-0107 dated 16 May 2019.

ATA 56 – Windows – Jettisoning System – Modification

Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale

Applicability:

AS 332 L2 helicopters, all serial numbers (s/n), except helicopters that have embodied AH modification (mod) 07 28630, mod 332P087142.00 or mod 332P087140.00.

EC 225 LP helicopters, all s/n, except helicopters that have embodied AH mod 07 28370, mod 332P087140.00, mod 332P087142.00, mod 332P087142.03, mod 332P087142.06, mod 332A087149.00 or mod 332A087149.03.

Definitions:

For the purpose of this AD, the following definitions apply:

The applicable ASB: AH Alert Service Bulletin (ASB) AS332-56.90.14, ASB AS332-56.00.16, ASB EC225-56A013 Revision 1, ASB EC225-56A015, ASB EC225-56A016 and ASB EC225-56A017, as applicable.

Groups: Group 1 helicopters are AS 332 L2 helicopters, s/n 2488, 2503, 2504, 2590, 2643 and 2646; and EC 225 LP helicopters, all s/n, except s/n 2663, 2666, 2670, 2673, 2678 and 2742.

Group 2 helicopters are all other helicopters.



Reason:

An occurrence was reported where difficulty was experienced in jettisoning a helicopter window requiring the application of an excessive pushing force. Subsequent investigation determined that the associated window seal was in a good condition with no indication of contamination with paint or hardening. However, excessive friction between the window seal and the helicopter airframe was identified to be the root cause of this failure mode.

This condition, if not corrected, could prevent the jettisoning of a window, possibly affecting the evacuation of helicopter occupants during an emergency situation.

To address this potentially unsafe condition, as a temporary measure, EASA issued AD 2016-0049 to require installation of polytetrafluoroethylene (PTFE) skived film on window frames.

After that AD was issued, following investigations carried out on customized VIP cabin windows, EASA issued AD 2018-0039 (later corrected) retaining the requirements of AD 2016-0049, which was superseded, and requiring installation of silicone seals (mod 332P087140.00) on certain identified VIP cabin windows, instead of the PTFE skived film and existing polychloroprene seals.

After that AD was issued, AH developed mod 07 28370, mod 332P087142.00 and mod 332P087142.03 applicable to a limited population of helicopters affected by AD 2018-0039 and available for in-service helicopters through the ASB AS332-56.90.14 and the ASB EC225-56A013 (later revised) and, consequently, EASA issued AD 2019-0107 to require modification of the windows jettisoning system.

Since that AD was issued, AH developed a set of modifications applicable to additional group of helicopters, which were not addressed by that AD. It is expected that AH will also develop similar modifications for in-service installation on other affected helicopters, as addressed by EASA AD 2018-0039.

For the reasons described above, this AD retains the requirements of EASA AD 2019-0107, which is superseded, and requires modification of the windows jettisoning system by removing the PTFE skin between the window seal and the helicopter airframe, and installing silicone seals instead of seals currently installed on the helicopter cabin windows.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Modification:

- (1) Within the compliance time as defined in Table 1 or Table 2 of this AD, as applicable to helicopter Group and helicopter operation, modify the windows jettisoning system in accordance with the instructions of the applicable ASB.



Table 1 – Modification of Windows Jettisoning System for Group 1 Helicopters

Helicopter Operation	Compliance Time (whichever occurs first after 30 May 2019 [the effective date of EASA AD 2019-0107])
not operated over water	250 flight hours (FH) or 6 months
operated over water	110 FH or 6 months

Table 2 – Modification of Windows Jettisoning System for Group 2 Helicopters

Helicopter Operation	Compliance Time (whichever occurs first after the effective date of this AD)
not operated over water	250 FH or 6 months
operated over water	110 FH or 6 months

Related Action:

- (2) After modification of a helicopter as required by paragraph (1) of this AD, as applicable, that helicopter is no longer affected by the requirements of EASA AD 2018-0039.

Ref. Publications:

AH ASB AS332-56.00.16 original issue dated 10 February 2020.

AH ASB AS332-56.90.14 original issue dated 10 April 2019.

AH ASB EC225-56A013 Revision 1 dated 10 February 2020.

AH ASB EC225-56A015 original issue dated 10 February 2020.

AH ASB EC225-56A016 original issue dated 10 February 2020.

AH ASB EC225-56A017 original issue dated 10 February 2020.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 14 February 2020 as PAD 20-035 for consultation until 13 March 2020. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on



a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).

5. For any question concerning the technical content of the requirements in this AD, please contact: Airbus Helicopters (Technical Support), Aéroport de Marseille Provence 13725 Marignane Cedex, France, Telephone +33 (0)4 42 85 97 97, Fax +33 (0)4 42 85 99 66, Web portal: <https://keycopter.airbushelicopters.com> > Technical Requests Management, E-mail: support.technical-dyncomp.ah@airbus.com, and TechnicalSupport.Helicopters@airbus.com.

Superseded

