



Airworthiness Directive

AD No.: 2021-0111R1

Issued: 05 August 2021

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: Revision 1: 12 August 2021
Original issue: 06 May 2021

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Revision: This AD revises EASA AD 2021-0111 dated 22 April 2021.

ATA 56 – Windows – Windshields – Inspection

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-252N, A321-253N, A321-251NX, A321-252NX, A321-253NX, A321-271N, A321-272N, A321-271NX and A321-272NX aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

Affected part: Windshields having a Part Number (P/N) as defined in Table 1 of this AD. Depending on its P/N, an affected part is then Group 1, Group 2 or Group 3.

New/repaired part: Any affected part which is new; or which accumulated 0 flight hours (FH) since a repair accomplished by SAINT-GOBAIN SULLY (SGS), including "Outer ply replacement".



Serviceable part: Any windshield, eligible for installation, which is not an affected part; or an affected part which is a new/repaired part, as defined in this AD; or an affected part (not new) that, before next installation, or before next flight after installation, passes (no defects found) a detailed inspection (DET) and passes (results included in the “green area” or “amber area”, as identified in the SB) an electrical test measurement (ETM), as applicable, in accordance with the instructions of the SB.

Aeroplane date of manufacture: The date of transfer of title (ownership) which is referenced in Airbus documentation at the time of first delivery to an operator.

Date of first installation: For an affected part, the date of first installation on an aeroplane. If unknown, or for a part not replaced in service, the aeroplane date of manufacture must be used instead.

The SB: Airbus Service Bulletin (SB) A320-56-1022 or Airbus SB A320-56-1023, as applicable, and SGS SB STA320-56-001.

Groups: Group A aeroplanes are those that have an affected part installed.

Group B aeroplanes are those that do not have an affected part installed.

Note 1: An aeroplane on which Airbus modification 167352 has been embodied in production (only windshields installed having P/N STA320-1-9-3 and P/N STA320-2-9-3) is Group B, provided that no affected part has been installed on that aeroplane since its date of manufacture.

Reason:

An occurrence was reported where an A319 aeroplane lost in flight the right windshield, with consequent rapid cockpit depressurization, causing damage to cockpit items/systems and significant increase of flight crew workload. The investigations identified several contributing factors (including manufacturing variability, fretting between windshield components, water ingress, electrical braids corrosion) which led to a thermal shock/overheat, damaging more than one windshield structural plies and impairing the structural integrity of the windshield.

This condition, if not detected and corrected, could lead to failure of the windshield, possibly resulting in injury to the flight crew, in-flight depressurization of the aeroplane, and would require exceptional piloting skill to maintain control the aeroplane.

To address this potential unsafe condition, Airbus issued the SB to provide inspection instructions for the affected parts. Consequently, EASA issued AD 2021-0111 to require repetitive DET and ETM of the affected parts, and, depending on findings, accomplishment of applicable corrective action(s).

Since that AD was issued, it was determined that the compliance times can be based only on calendar time and Flight Cycles (FC) accumulated by an affected part.

For the reasons described above, this AD is revised to remove reference to FH in the compliance times.



Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Table 1 – Affected Parts P/N and Groups

Affected Part Group	SGS Windshield P/N	
	Left-hand side	Right-hand side
1	STA320-1-7-1	STA320-2-7-1
2	STA320-1-8-2	STA320-2-8-2
3	STA320-1-3-1	STA320-2-3-1
	STA320-1-4-1	STA320-2-4-1
	STA320-1-5-1	STA320-2-5-1
	STA320-1-6-1	STA320-2-6-1

Inspection(s):

- (1) For Group A aeroplanes: Within the compliance times as specified in Table 2 of this AD, and thereafter, at intervals not exceeding 750 flight cycles (FC) or 4 months, whichever occurs first, accomplish a DET followed by an ETM of each Group 1 affected part in accordance with the instructions of the SB.

Table 2 – Group 1 Affected Parts – Initial DET / ETM

Compliance Time(s) (whichever occurs later, A or B)	
A	Within 750 FC or 4 months, whichever occurs first after 06 May 2021 [the effective date of the original issue of this AD]
B	Before exceeding 750 FC or 4 months, whichever occurs first since the date of first installation

- (2) For Group A aeroplanes: Within the compliance times as specified in Table 3 of this AD, as applicable, and, thereafter, at intervals not exceeding 7 500 FC or 24 months, whichever occurs first, accomplish a DET followed by an ETM of each Group 2 affected part in accordance with the instructions of the SB.



Table 3 – Group 2 Affected Parts – Initial DET and ETM

Windshield Maintenance History (see Note 2 of this AD)	Windshield Age / Utilization (see Notes 3 and 4 of this AD)	Compliance Time(s) (after 06 May 2021 [the effective date of the original issue of this AD], or since the date of first installation, whichever occurs later)
Fault message "561000L(R) WINDSHIELD SENSOR" recorded since windshield installation on an aeroplane OR unknown maintenance history	n/a	Within 750 FC or 4 months, whichever occurs first
Fault message "561000L(R) WINDSHIELD SENSOR" NOT recorded since windshield installation on an aeroplane	Windshield age / utilization being more than 48 months, or 10 000 FC, or 15 000 FH	Within 3 750 FC or 12 months, whichever occurs first
	Windshield age / utilization being less or equal to 48 months, and 10 000 FC and 15 000 FH	Within 7 500 FC or 24 months, whichever occurs first

Note 2: Any fault message "561000L(R) WINDSHIELD SENSOR" recorded after the identification of the DET and ETM threshold, as applicable for a Group 2 affected part, does not require re-assessment of the DET and ETM threshold for that affected part.

Note 3: If no data, or only partial data, is available, operators may refer to the guidance specified in Airworthiness Limitations Section (ALS) Part 1 Section 1 Chapter 5.2 (traceability) to determine the age/utilisation of the windshield.

Note 4: Windshield age and utilization are counted since the date of first installation, as defined in this AD, or since first installation of that part after a repair accomplished by SGS and including "Outer ply replacement".

- (3) If, during any ETM as required by paragraph (2) of this AD, the results are found to be in the "amber area", as identified in the SB, accomplish subsequent DET and ETM of that affected part at intervals not exceeding 750 FC or 4 months, whichever occurs first.
- (4) For Group A aeroplanes: Within 750 FC or 4 months, whichever occurs first after 06 May 2021 [the effective date of the original issue of this AD] or since the date of first installation, whichever occurs later, and, thereafter, at intervals not exceeding 750 FC or 4 months, whichever occurs first, accomplish a DET of each Group 3 affected part, as applicable, in accordance with the instructions of the SB.



Corrective Action(s):

- (5) If, during any DET as required by paragraph (1), (2), (3) or (4) of this AD, as applicable, any defect, as identified in the SB, is found on an affected part, before next flight, replace that affected part with a serviceable part in accordance with the instructions of the SB.
- (6) If, during any ETM as required by paragraph (1), (2) or (3) of this AD, as applicable, the results are found to be in the “red area”, as identified in the SB, before next flight, replace that affected part with a serviceable part in accordance with the instructions of the SB.
- (7) Replacement of an affected part with a serviceable part on an aeroplane, as required by paragraph (5) or (6) of this AD, as applicable, can be deferred in accordance with the applicable instructions and limitations of Master Minimum Equipment List (MMEL) item 30-42-03A or 30-42-03B.

Terminating Action:

- (8) For Group A aeroplanes: Replacement on an aeroplane of each affected part with a not affected part constitutes terminating action for the repetitive inspections as required by paragraphs (1) to (4) of this AD, as applicable for that aeroplane, provided that, following that replacement, no affected part is installed on that aeroplane.

Parts Installation:

- (9) For Group A and Group B aeroplanes: From 06 May 2021 [the effective date of the original issue of this AD], it is allowed to install on any aeroplane a windshield, provided it is a serviceable part, as defined in this AD. Following installation of an affected part on an aeroplane, that aeroplane is effectively a Group A aeroplane, and that affected part must be inspected as required by this AD. For an affected part, which is not new/repairs, as defined in this AD, the first inspection after that installation can be deferred up to the applicable interval for repetitive inspection, provided that part accumulated 0 FH since last inspection, and has been stored in accordance with the instructions of the applicable Component Maintenance Manual.

Reporting:

- (10) Within 30 days after accomplishment of the initial DET and ETM as required by paragraph (1), (2) or (4) of this AD, as applicable, or after 06 May 2021 [the effective date of the original issue of this AD], whichever occurs later, report the inspection results (including no findings) to Airbus. Using the inspection report attached to the SB is an acceptable method to comply with this requirement.
- (11) Within 90 days after each subsequent DET and ETM as required by paragraph (1), (2), (3) or (4) of this AD, as applicable, report any inspection finding to Airbus. Using the inspection report attached to the SB is an acceptable method to comply with this requirement.

Ref. Publications:

Airbus SB A320-56-1022 original issue dated 28 January 2021.

Airbus SB A320-56-1023 original issue dated 28 January 2021.



SGS SB STA320-56-001 original issue dated 25 January 2021.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The original issue of this AD was posted on 02 March 2021 as PAD 21-033 for consultation until 30 March 2021. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – IIASA; E-mail: account.airworth-eas@airbus.com.

