


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	<p>PAD No.: 15-095</p> <p>Date: 23 July 2015</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>	
Design Approval Holder's Name: AIRBUS	Type/Model designation(s): A300 aeroplanes
TCDS Number: EASA.A.172	
Foreign AD: Not applicable	
Supersedure: This AD supersedes DGAC France AD F-2004-001 dated 07 January 2004, EASA approval 2003-2107.	
ATA 53	Fuselage – Multiple Cracks Development – Inspection / Modification
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	Airbus A300 aeroplanes, all certified models, all Manufacturer Serial Numbers.
Reason:	<p>A widespread fatigue damage (WFD) analysis conducted on A300 aeroplanes identified areas which are susceptible to crack development.</p> <p>This condition, if not corrected, could affect the structural integrity of the aeroplane.</p> <p>To address this issue, Airbus developed a modification (mod) to reinforce the structure of the aeroplane.</p> <p>Airbus issued Service Bulletin (SB) A300-53-0271 to provide instructions for a cold expansion of the foot attachment holes of certain fuselage frames, and DGAC France issued AD F-2004-001 to require this mod.</p> <p>Since that AD was issued, Airbus released twelve other mods with corresponding SBs, to complete the set of inspections and repairs in the frame of the A300 WFD campaign. EASA issued AD 2015-0115 to require ten of these mods through section 3 of ALS Part 2, and decision is made to delete section 3 from ALS Part 2.</p> <p>For the reasons described above, this AD retains the requirements of DGAC France AD F-2004-001, which is superseded, and requires implementation of the additional inspection, modification and/or repair actions, as applicable to aeroplane model.</p>
Effective Date:	[TBD: 14 days after final AD issue date]

Required Action(s)
and Compliance
Time(s):

Required as indicated, unless accomplished previously:

- (1) Within 4 months after the effective date of this AD, verify if the Airbus mods listed in Table 1 and Table 2 of this AD, as applicable to aeroplane model, have been embodied on the aeroplane in accordance with the instructions of the related Airbus SB as listed in Table 1 and Table 2 of this AD.

A review of the aeroplane maintenance records is acceptable to accomplish the verification as required by this paragraph, provided those records can be relied upon for that purpose.

Table 1 – Airbus mod and related SB

Airbus mod	Airbus SB
751	A300-53-0247 Revision 02
7301	A300-53-0239 Revision 02
10326	A300-57-0203 Revision 04
12735	A300-53-0366
12736	A300-53-0368
12737	A300-53-0369 Revision 03
12798	A300-53-0375 Revision 01
07757 / 12977	A300-53-0271 Revision 05
13611	A300-57-0258
13692	A300-53-0393
13716	A300-57-0259

Table 2 - Airbus mod and related SB

Airbus mod	Airbus SB
12794	A300-53-0374 Revision 04
12796	A300-53-0373 Revision 03

- (2) If, during the verification as required by paragraph (1) of this AD, it is determined that an Airbus mod/SB included in Table 1 of this AD is not embodied, accomplish the applicable corrective action(s) within the compliance time as specified in, and in accordance with the instructions of, the related Airbus SB as listed in Table 1 of this AD.
- (3) If, during the verification as required by paragraph (1) of this AD, it is determined that Airbus SB A300-53-0374 (mod 12794) is not embodied, accomplish the applicable corrective action(s) within the compliance time as specified in Table 3 of this AD, and in accordance with the instructions of Airbus SB A300-53-0374.

Table 3 – Airbus mod 12794

Aeroplane model	Compliance time (since aeroplane first flight)	
	Frame 55	Frame 58
A300B2	31 300 flight cycles (FC)	49 700 FC
A300B4-100		
A300B4-200	33 600 FC	55 800 FC

	<p>(4) If, during the verification as required by paragraph (1) of this AD, it is determined that Airbus SB A300-53-0373 (mod 12796) is not embodied, accomplish the applicable corrective action(s) within the compliance time as specified in Table 4 of this AD, and in accordance with the instructions of Airbus SB A300-53-0373.</p> <p style="text-align: center;">Table 4 – Airbus mod 12796</p> <table border="1" data-bbox="552 427 1444 629"> <thead> <tr> <th>Aeroplane model(s)</th><th>Compliance time (since aeroplane first flight)</th></tr> </thead> <tbody> <tr> <td>A300B2</td><td>42 700 FC</td></tr> <tr> <td>A300B4-100</td><td>41 700 FC</td></tr> <tr> <td>A300B4-200, A300C4, A300F4</td><td>47 900 FC</td></tr> </tbody> </table> <p>Note: Grace periods may be applied for the corrective action(s) required by paragraphs (2), (3) and (4) of this AD, as specified in the respective Airbus SB, applicable from the issue date of the relevant Airbus SB.</p>	Aeroplane model(s)	Compliance time (since aeroplane first flight)	A300B2	42 700 FC	A300B4-100	41 700 FC	A300B4-200, A300C4, A300F4	47 900 FC
Aeroplane model(s)	Compliance time (since aeroplane first flight)								
A300B2	42 700 FC								
A300B4-100	41 700 FC								
A300B4-200, A300C4, A300F4	47 900 FC								
Ref. Publications:	<p>Airbus SB A300-57-0203 Revision 04 dated 18 February 2015.</p> <p>Airbus SB A300-53-0239 Revision 02 dated 06 March 2000.</p> <p>Airbus SB A300-53-0247 Revision 02 dated 20 July 1990.</p> <p>Airbus SB A300-57-0258 original issue dated 30 September 2014.</p> <p>Airbus SB A300-57-0259 original issue dated 30 September 2014.</p> <p>Airbus SB A300-53-0271 Revision 05 dated 21 June 2013.</p> <p>Airbus SB A300-53-0366 original issue dated 07 April 2005.</p> <p>Airbus SB A300-53-0368 original issue dated 07 April 2005.</p> <p>Airbus SB A300-53-0369 Revision 03 dated 01 September 2010.</p> <p>Airbus SB A300-53-0373 Revision 03 dated 01 September 2010.</p> <p>Airbus SB A300-53-0374 Revision 04 dated 05 July 2013.</p> <p>Airbus SB A300-53-0375 Revision 01 dated 24 June 2013.</p> <p>Airbus SB A300-53-0393 original issue dated 27 September 2013.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>								
Remarks:	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 20 August 2015. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS SAS – EIAW (Airworthiness Office) E-mail: continued.airworthiness-wb.external@airbus.com 								