



Notification of a proposal to issue an Airworthiness Directive

PAD No.: 16-079

Issued: 30 May 2016

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

ZODIAC SEATS FRANCE

Type/Model designation(s):

CABIN ATTENDANT SEAT 537 - SERIES

Effective Date: [TBD -standard: 14 days after AD issue date]

ETSO Authorisation(s): EASA.210.10036580

Foreign AD: Not applicable

Supersedure: None

ATA 25 – Equipment / Furnishings – Cabin Attendant Seat – Modification / Replacement

Manufacturer(s):

Zodiac Seats France (formerly Sicma Aero Seat)

Applicability:

Zodiac Seats France cabin attendant seats 537 series with Part Number (P/N) 53701-XX-XXX.

These seats are known to be installed on, but not limited to, ATR-GIE Avions de Transport Régional ATR 42 and ATR 72 aeroplanes.

Reason:

Cases were reported by operators of finding safety belt worn out at the attachment to the cabin attendant seat. This kind of belt damage is due to chafing between the belt and the surrounding metal lap belt fitting of the cabin attendant seat.

This condition, if not detected and corrected, could lead to failure of the attendant seat to perform its intended function, possibly resulting in injury to the seat occupant.



Prompted by these occurrences, Zodiac Seats issued Service Bulletin (SB) No. 537-25-003, providing instructions to modify the affected seats.

For the reason described above, this AD requires a modification of the seat pan shaft by installing new seat pan spacers, and subsequent re-identification with a new P/N.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

- (1) Within 6 months after the effective date of this AD modify and re-identify each affected cabin attendant seat in accordance with the instructions of Zodiac Seats France SB No. 537-25-003.
- (2) Do not install (see Note of this AD) an affected cabin attendant seat on any aeroplane, as required by paragraph (2.1) or (2.2) of this AD, as applicable
 - (2.1) For an aeroplane that, on the effective date of this AD, has an affected seat installed:
After modification of that aeroplane as required by paragraph (1) of this AD.
 - (2.2) For an aeroplane that, on the effective date of this AD, does not have an affected seat installed: From the effective date of this AD.

Note: For the purpose of this AD, removal of a seat from an aeroplane and subsequent re-installation of that seat on that same aeroplane is not “installation” as specified in paragraph (2) of this AD.

Ref. Publications:

Zodiac Seats France SB No. 537-25-003 original issue dated 21 March 2016.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 27 June 2016.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. For any question concerning the technical content of the requirements in this PAD, please contact:
Zodiac Seats France,
Rue Robert Marechal Senior,
B.P. 69 36100 Issoudun, France
Tel.: +33 (0)2 54 03 39 39 - Fax: +33 (0) 2 54 03 39 00.

