



# Notification of a Proposal to issue an Airworthiness Directive

**PAD No.: 18-041**

**Issued: 19 March 2018**

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

**Design Approval Holder's Name:**

DASSAULT AVIATION

**Type/Model designation(s):**

Falcon 10 aeroplanes

**Effective Date:** [TBD - standard: 14 days after AD issue date]

**TCDS Number(s):** EASA.A.173

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

**Manufacturer(s):**

Dassault Aviation (Dassault), formerly Avions Marcel Dassault - Breguet Aviation

**Applicability:**

Falcon 10 aeroplanes, all serial numbers.

**Definition(s):**

For the purpose of this AD, the following definitions apply:

**The ALS:** The airworthiness limitations (ALS) and certification maintenance instructions for Falcon 10 aeroplanes, as specified in Chapter 5-40 of the Dassault Falcon 10 Aircraft Maintenance Manual (AMM), revision 13.

**Reason:**

The airworthiness limitations and certification maintenance instructions for the Dassault Falcon 10 aeroplanes, which are approved by EASA, are currently defined and published in the Dassault Falcon 10 AMM, Chapter 5-40. These instructions have been identified as mandatory for continued airworthiness.



Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2008-0221 to require accomplishment of the maintenance tasks, and implementation of the airworthiness limitations, as specified in the Dassault Falcon 10 AMM, Chapter 5-40, at Revision 8.

Since that AD was issued, Dassault issued the ALS, which introduces new and more restrictive maintenance requirements and/or airworthiness limitations.

For the reason described above, this AD takes over the requirements for Falcon 10 aeroplanes from EASA AD 2008-0221, and requires accomplishment of the actions specified in the ALS.

Once new ADs have been published for all the types addressed by EASA AD 2008-0221, EASA plans to cancel that AD.

#### **Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

#### **Maintenance Tasks and Replacement of Life Limited Parts:**

(1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable, depending on aeroplane configuration:

(1.1) Replace each component before exceeding the applicable life limit, and

(1.2) Within the thresholds and intervals (see Note 1 of this AD), accomplish all applicable maintenance tasks.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

#### **Corrective Action(s):**

(2) In case of finding discrepancies (as defined in the ALS) during accomplishment of any task as required by paragraph (1) of this AD, within the compliance time specified in the ALS, accomplish the applicable corrective action(s) in accordance with applicable Dassault maintenance documentation. If no compliance time is identified in the ALS, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy is not identified in the ALS, before next flight, contact Dassault for approved instructions and accomplish those instructions accordingly.

#### **Aircraft Maintenance Programme (AMP) Revision:**

(3) Within 12 months after the effective date of this AD, revise the approved AMP, on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane, by incorporating the limitations, tasks and associated thresholds and intervals described in the ALS, as applicable, depending on aeroplane configuration.



**Credit:**

- (4) For an AMP that, on the effective date of this AD, is already updated to incorporate the maintenance tasks and life limitations as specified in Dassault Falcon 10 AMM Chapter 5-40 at Revision 8 (or later, up to Revision 12 inclusive), that action ensures (see Note 2 of this AD) the continued accomplishment of those tasks and limitations.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and more restrictive tasks and limitations, introduced into the Dassault Falcon 10 AMM Chapter 5-40 since the latest AMP-embodied revision, as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times (see Note 1 of this AD) as specified in, the ALS, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and more restrictive tasks and limitations, as applicable, depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (3) of this AD.

**Recording AD compliance:**

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures (see Note 2 of this AD) continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Note 2: For affected Dassault Falcon 10 aeroplanes registered in Europe, complying with the approved AMP, as specified in paragraph (3) or (4) of this AD, as applicable, is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.

**Ref. Publications:**

Dassault Falcon 10 AMM DMD 11745, chapter 5-40, Revision 13, dated July 2017.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. This Proposed AD will be closed for consultation on 02 April 2018.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. For any question concerning the technical content of the requirements in this PAD, please contact your Dassault Falcon Technical Assistance:
  - For Europe, Middle East and Africa based operators: Hot Line: (33) 1 47 11 37 37
  - For USA, Canada and Mexico based operators: Help Desk: (1) 800-2FALCON (2325266)
  - All other areas: Help Desk: (1) 201 541 4747.

