



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 19-219

Issued: 20 December 2019

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name::

AIRBUS

Type/Model designation(s):

A380 aeroplanes

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.A.110

Foreign AD: Not applicable

Supersedure: None

ATA 36 – Pneumatic – Engine Bleed Air Supply System High Pressure Valves – Modification / Replacement

Manufacturer(s):

Airbus

Applicability:

Airbus A380-841 and A380-842 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A380-36-8047.

Affected part: High pressure bleed valves (HPV), having Part Number (P/N) 6863B020001 or P/N 6863B030001.

Serviceable part: An affected part which has been modified in accordance with the instructions of the SB, or an HPV having P/N 6863B040001.

Groups: Group 1 aeroplanes are those that have an affected part installed. Group 2 aeroplanes are those that do not have an affected part installed. An aeroplane on which Airbus modification 77028



has been embodied in production is a Group 2 aeroplane, provided the aeroplane remains in that configuration.

Reason:

Occurrences of HPV clamping pin rupture were reported on in-service aeroplanes. Subsequent investigation determined that the dynamic solicitation and airflow disturbance introduced by the installation of the upstream duct have caused this clamping pin failure.

This condition, if not corrected, could, in case of HPV clip failures, lead to a non-isolated burst in an engine pylon, possibly resulting in structural failure of that pylon.

To address this potential unsafe condition, Airbus issued the SB to provide instructions to modify or replace the affected parts.

For the reasons described above, this AD requires modification or replacement of the affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Modification:

- (1) For Group 1 aeroplanes: Within 6 months after the effective date of this AD, modify all affected parts installed on all engines installed on the aeroplane, in accordance with the instructions of the SB.

Replacement:

- (2) Replacing all affected parts with serviceable parts, as defined in this AD, on all engines installed on an aeroplane is an acceptable alternative method to comply with the requirements of paragraph (1) of this AD for that aeroplane.

Parts Installation:

- (3) Do not install an affected part on any engine on an aeroplane, as required by paragraph (3.1) or (3.2) of this AD, as applicable.

(3.1) For Group 1 aeroplanes: After modification of the aeroplane as required by paragraph (1) of this AD, or as specified in paragraph (2) of this AD, as applicable.

(3.2) For Group 2 aeroplanes: From the effective date of this AD.

Ref. Publications:

Airbus SB A380-36-8047 original issue dated 25 April 2018.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 17 January 2020.



2. Enquiries regarding this PAD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#).
4. For any question concerning the technical content of the requirements in this PAD, please contact: Airbus – EIANA (Airworthiness Office), Telephone: +33 562 110 253, Fax: +33 562 110 307, E-mail: account.airworth-A380@airbus.com.

