

Airworthiness Directive

AD No.: 2021-0003

Issued: 06 January 2021

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 332 and EC 225 helicopters

Effective Date: 20 January 2021

TCDS Number(s): EASA.R.002

Foreign AD: Not applicable

Supersedure: None

ATA 11 – Placards and Markings – Emergency Exit Labels – Installation

Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale, Sud Aviation

Applicability:

AS 332 C, AS 332 C1, AS 332 L, AS 332 L1, AS 332 L2 and EC 225 LP helicopters, all manufacturer serial numbers, equipped with at least one cabin plug door, having Part Number 332A221301.XX or 332A251406.XX, where XX represents any number.

Definitions:

For the purpose of this AD, the following definitions apply:

The applicable ASB: AH Alert Service Bulletin (ASB) AS332-11.00.06 and ASB EC225-11A002, as applicable.

Reason:

During review of existing emergency exit placards, attached to or located near to the cabin plug doors (both left-hand (LH) and right-hand (RH) sides), to verify that they provide an accurate illustration of the proper method of plug doors emergency opening, it was identified that in some cases, these placards could be confusing for passengers.

This condition, if not corrected, could prevent the jettisoning of the cabin plug doors, possibly preventing safe evacuation from the helicopter during an emergency and resulting in injury to occupants.

To address this potential unsafe condition, AH issued the applicable ASB to provide additional emergency exit placards with improved operating and control instructions.

For the reasons described above, this AD requires installation of additional emergency exit placards.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Placard Installation:

- (1) Within 12 months after the effective date of this AD, install the additional emergency exit placards on the cabin plug doors (RH and LH sides) in accordance with the instructions of the applicable ASB.

Parts Installation:

- (2) From the effective date of this AD, it is allowed to install on any helicopter a cabin plug door (RH or LH side), provided that, prior to installation, the additional emergency exit labels are installed on that cabin plug door in accordance with the instructions of the applicable ASB.

Ref. Publications:

AH ASB AS332-11.00.06 original issue dated 09 September 2020.

AH ASB EC225-11A002 original issue dated 09 September 2020.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 11 September 2020 as PAD 20-140, and republished as PAD 20-140R1 on 08 December 2020, for consultation until 22 December 2020. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or



may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.

5. For any question concerning the technical content of the requirements in this AD, please contact:
Airbus Helicopters (Technical Support), web portal: <https://keycopter.airbushelicopters.com> >
Technical Requests Management, or e-mail: support.technical-airframe.ah@airbus.com and
TechnicalSupport.Helicopters@airbus.com.

Superseded

