



# Notification of a Proposal to issue an Airworthiness Directive

**PAD No.:** 24-053

**Issued:** 21 May 2024

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

**Design Approval Holder's Name:**

SAFRAN HELICOPTER ENGINES

**Type/Model designation(s):**

ARRIUS 2 engines

**Effective Date:** [TBD - standard: 14 days after AD issue date]

**TCDS Number(s):** EASA.E.029

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

### Manufacturer(s):

SAFRAN Helicopter Engines, S.A. (SAFRAN), formerly Turboméca, S.A.

### Applicability:

ARRIUS 2G1 engines, all serial numbers.

These engines are known to be installed on, but not limited to, KAMOV 226T twin-engine helicopters.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The ALS:** Chapter 05-10 Airworthiness Limitations Section (ALS) of SAFRAN Arrius 2G1 Maintenance Manual (MM), reference X 319 R4 450 2, update no. 22.

**The AMP:** The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated



engine. For engines installed on aircraft operated under EU regulations, the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) [1321/2014](#).

**New and/or more restrictive tasks:** This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS revision that is currently incorporated in the AMP.

**Reason:**

The airworthiness limitations and/or certification maintenance instructions for the ARRIUS 2G1 engines, which are approved by EASA, are currently defined and published in Chapter 05-10 ALS of the ARRIUS 2G1 MM, reference X 319 R4 450 2. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

Since the original issue of the Chapter 05-10 ALS of the ARRIUS 2G1 MM, new and/or more restrictive tasks have been developed, and introduced in the ALS, as defined in this AD.

For the reasons described above, this AD requires accomplishment of the actions specified in the ALS.

**Required Action(s) and Compliance Time(s):**

Required as indicated by this AD, unless the actions required by this AD have been already accomplished:

**Maintenance Tasks and Replacement of Life Limited Parts:**

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable depending on engine configuration:
  - (1.1) Replace each component before exceeding the applicable life limit, and
  - (1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.

**Corrective Action(s):**

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable SAFRAN maintenance documentation. If no compliance time is identified in the ALS, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy cannot be corrected by using existing SAFRAN instructions, before next flight, contact SAFRAN for approved instructions and accomplish those instructions accordingly.

**AMP Revision:**

- (3) Within 12 months after the effective date of this AD, revise the AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the ALS, as applicable depending on engine configuration.



**Credit:**

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in a previous ALS revision, that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for a helicopter to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations, as defined in this AD, as applicable depending on engine configuration, within the compliance times as specified in the ALS to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations, as specified in the ALS, as applicable depending on engine configuration, into the AMP to comply with paragraph (3) of this AD.

**Recording AD Compliance:**

- (5) When the AMP of a helicopter has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for the engine(s) installed on that helicopter. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

**Ref. Publications:**

SAFRAN Arrius 2G1 MM, reference X 319 R4 450 2, update no. 22, dated 15 October 2023.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. This Proposed AD will be closed for consultation on 18 June 2024.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
4. For any question concerning the technical content of the requirements in this PAD, please contact: SAFRAN Helicopter Engines, S.A. at [www.tools.safran-helicopter-engines.com](http://www.tools.safran-helicopter-engines.com).

