EASA PAD No.: 24-120



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 24-120

Issued: 16 October 2024

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name: Type/Model designation(s):

SAFRAN HELICOPTER ENGINES ARRIUS 2F and 2R engines

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.E.031

Foreign AD: Not applicable

Supersedure: None

ATA 72 – Engine – Gas Generator High-Pressure Turbine Blades – Replacement

Manufacturer(s):

SAFRAN Helicopter Engines (SAFRAN), formerly Turboméca

Applicability:

ARRIUS 2F and ARRIUS 2R engines, all serial numbers (s/n).

These engines are known to be installed on, but not limited to, Airbus Helicopters (formerly Eurocopter, Eurocopter France) EC120 B single-engine helicopters, and Bell Textron Canada Ltd B505 single-engine helicopters.

Definitions:

For the purpose of this AD, the following definitions apply:

The MSB: SAFRAN Mandatory Service Bulletin (MSB) 319 72 4853 version B.

Affected part: High-pressure (HP) turbine blade having Part Number (P/N) 2 319 40 A5X 0 (ARRIUS 2F) or P/N 2 319 40 A64 0 (ARRIUS 2R), and an s/n as listed in Appendix 1 of the MSB.



EASA PAD No.: 24-120

Serviceable part: A HP turbine blade, eligible for installation in accordance with SAFRAN instructions, that is not an affected part; or an affected part that has not exceeded 2 500 engine cycles (EC) for P/N 2 319 40 A5X 0 (ARRIUS 2F engines) or 5 000 EC for P/N 2 319 40 A64 0 (ARRIUS 2R engines) since first installation.

Groups: Group 1 engines are those which have at least one affected part installed. Group 2 engines are those which do not have any affected part installed.

Reason:

An investigation revealed that a change in the casting manufacturing process of the affected part had an effect on the porosity rate in the root of those parts.

A non-conformant porosity rate can have an effect on the mechanical strength of the HP turbine blade, causing its premature rupture.

This condition, if not corrected, could lead to an uncommanded engine shutdown in flight which, on a single-engine helicopter, may result in a significant reduction of the control of a helicopter.

To address this potential unsafe condition, SAFRAN issued the MSB, providing instructions for implementation of the reduced use limit of the affected parts and for the replacement of affected parts before exceeding the reduced use limit.

For the reasons described above, this AD requires the replacement of the affected parts with the serviceable parts, and provides condition for installation of affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Replacement:

(1) For Group 1 engines: Within the compliance time specified in Table 1 of this AD, as applicable, replace each affected part with a serviceable part in accordance with the instructions of the MSB.

- Programme Programme	
Engine Model	Compliance Time
ARRIUS 2F engines	Before exceeding 2 500 EC since first installation
ARRIUS 2R engines	Before exceeding 5 000 EC since first installation

Table 1 – Replacement Compliance Time

Part(s) Installation:

(2) For Group 1 and Group 2 engines: From the effective date of this AD, it is allowed to install an affected part on an HP turbine assembly, provided that the affected part is a serviceable part, as defined in this AD and that, following installation, it is replaced as required by paragraph (1) of this AD.



EASA PAD No.: 24-120

Ref. Publications:

SAFRAN SB 319 72 4853 version A dated 16 April 2024, and version B dated 10 October 2024.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

- 1. This Proposed AD will be closed for consultation on 13 November 2024.
- Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
- 3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the <u>EU aviation safety reporting system</u>. This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
- 4. For any question concerning the technical content of the requirements in this PAD, please contact your nearest SAFRAN Helicopter Engines technical representative, or connect to www.tools.safran-helicopter-engines.com.