

Notification of a Proposal to cancel an Airworthiness Directive

PAD No.: 25-014-CN

Issued: 20 January 2025

Note: This Proposed Airworthiness Directive (PAD) Cancellation Notice (CN) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the cancellation of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name: **Type/Model designation(s):**

ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG RB211 Trent 700 engines

Effective Date: [TBD - standard: the same as issue date]

TCDS Number(s): EASA.E.042

Foreign AD: Not applicable

Cancellation: This PAD-CN proposes to cancel EASA AD 2009-0069 dated 25 March 2009.

ATA 72 – CANCELLED: Engine – Intermediate Pressure Turbine Bearing Oil Vent & Scavenge Tube – Inspection / Modification

Manufacturer(s):

Rolls-Royce plc

Applicability:

RB211 Trent 768-60, 772-60, 772B-60 and 772C-60 engines, except engines modified in accordance with Rolls-Royce Service Bulletin (SB) RB211-72-E708, SB RB.211-72-E965 or SB RB.211-72-F227.

These engines are known to be installed on, but not limited to, Airbus A330 aeroplanes.

Definitions:

For the purpose of this AD, the following definitions apply:

None.

Reason:

In 2004, two Trent 700 engines were removed due to high oil consumption. Investigation determined that the High Pressure/Intermediate Pressure (HP/IP) turbine bearing oil tubes had been fretted by the tubes' damaged heat shields. On both occasions, the outer heat shield had

fretted through the tube wall, in one case affecting the feed tube, and in the other one the scavenge tube. A previous service incident has shown that ingestion of HP3 cooling air into a breached scavenge or vent tube can cause over-pressurisation of the HP/IP bearing chamber. This would cause oil ejection from the rear of the chamber. The possible ignition of this oil could result in an IPT shaft failure, leading to IP turbine disc overspeed and resultant release of hazardous high energy debris.

This condition, if not detected and corrected, could result to engine fire and damage to or reduced control of the aeroplane.

To address this potential unsafe condition, the Civil Aviation Authority of the United Kingdom issued AD G-2005-0016, requiring the inspection of the vent- and scavenge tubes and heatshields for damage. That AD was revised and subsequently superseded by EASA AD 2005-0024, retaining the requirements thereof and requiring the modification of the tubes to delete or upgrade the outer heatshield. Later, EASA AD 2007-0255 superseded EASA AD 2005-0024, retaining the requirements thereof and adding an inspection of the vent pipe restrictor, to ensure that blockage of the restrictor does not occur due to carbon deposits loosened by the heatshield inspection. Subsequently, EASA AD 2009-0069 superseded EASA AD 2007-0255 retaining its requirements, expanding the Applicability by adding 772C-60 engines and extending the deadline for accomplishing the terminating action.

Since EASA AD 2009-0069 was issued, Rolls-Royce confirmed that all in-service Trent 700 engines were modified to embody Rolls-Royce SB RB.211-72-E708 and SB RB.211-72-F227 and are not affected anymore by the unsafe condition addressed by that AD.

This Notice, therefore, proposes to cancel EASA 2009-0069.

Required Action(s) and Compliance Time(s):

None.

Ref. Publications:

Rolls-Royce Non-Modification Service Bulletin RB211-72-AE792 Revision 4 dated 02 August 2007, or Revision 5 dated 06 December 2024.

Rolls-Royce Modification Service Bulletin (MSB) RB211-72-F227 original issue 30 March 2007, or Revision 1 dated 08 October 2007, or Revision 2 dated 01 December 2013.

Rolls-Royce MSB RB211-72-AE708 Revision 2 dated 06 September 2005.

Rolls-Royce MSB RB211-72-F117 original issue dated 06 June 2006, or Revision 1 dated 14 September 2006, or Revision 2 dated 25 September 2006.

Rolls-Royce MSB RB211-72-E965 Revision 1 dated 18 December 2009.

Remarks:

1. This Proposed AD-CN will be closed for consultation on 17 February 2025.



2. Enquiries regarding this PAD-CN should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. For any question concerning the technical content of this PAD-CN, please contact your designated Rolls-Royce representative, or download the publication from your Rolls-Royce Care account at <https://customers.rolls-royce.com>.

