

Airworthiness Directive

AD No.: 2025-0237R1

Issued: 23 June 2026

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: Revision 01: 30 June 2026
 Original issue: 10 November 2025

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD revises EASA AD 2025-0237 dated 27 October 2025, which superseded EASA AD 2022-0120R2 dated 28 July 2023.

ATA 25 – Equipment / Furnishings – 80 VU Rack Attachments – Inspection / Repair

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A319-173N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-253NY, A321-271N, A321-271NX, A321-271NY, A321-272N, and A321-272NX aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A320-25-1BKJ Revision 04, or A320-25-1CJH Revision 01, as applicable.

Zones: Zone A are 80 VU (View Unit) lower lateral fittings. Zone B is lower central support (central pyramid). Zone C are central post, upper fittings, shelves attachments and lateral pyramid structure side.

CEO aeroplanes: Current Engine Option (CEO), a commercial designation for Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes.

NEO aeroplanes: New Engine Option (NEO), a commercial designation for Airbus A319-151N, A319-153N, A319-171N, A319-173N, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-253NY, A321-271N, A321-271NX, A321-271NY, A321-272N and A321-272NX, and aeroplanes.

Groups:

Group	Aeroplane Configuration(s) (see Note 1 of this AD)
1	Airbus CEO aeroplanes having modification (mod) 34804 not embodied in production, and Airbus SB A320-53-1215, SB A320-25-1557, Repair Instruction (RI) Number R53113174000 (left-hand, (LH)) and RI Number R53113174001 (right-hand, (RH)) not embodied in service
2	Airbus CEO aeroplanes having mod 34804 not embodied in production, and Airbus SB A320-53-1215, RI Number R53113174000 (LH) and RI Number R53113174001 (RH) not embodied in service, and Airbus SB A320-25-1557 original issue, Revision 01 or Revision 02 embodied in service or having Airbus mod 34804 not embodied in production, and Airbus SB A320-53-1215 not embodied in service, and RI Number R53113174000 (LH) and RI Number R53113174001 (RH) embodied in service
3	Airbus CEO aeroplanes having mod 34804 not embodied in production, and Airbus SB A320-53-1215 and SB A320-25-1557 embodied in service or Airbus mod 34804 not embodied in production, and Airbus SB A320-53-1215, RI Number R53113174000 (LH) and RI Number R53113174001 (RH) embodied in service
4	Airbus CEO aeroplanes having mod 34804 embodied in production
5	Airbus NEO aeroplanes

Note 1: Airbus SB A320-25-1557 Revision 03 includes reference to Airbus SB A320-53-1215 as concurrent requirement.



Note 2: Following accomplishment of Airbus SB A320-53-1215 and SB A320-25-1557, a Group 1 aeroplane is considered to be a Group 3 aeroplane. Following accomplishment of Airbus SB A320-53-1215, a Group 2 aeroplane is considered to be a Group 3 aeroplane.

Reason:

Damage to the lower lateral fittings of the 80VU rack, typically elongated holes, migrated bushes, and/or missing bolts, has been reported on in-service aeroplanes not having Airbus mod 34804 embodied. The 80VU rack contains computers for flight controls, communication and radio-navigation. In addition, damage to the lower central support fitting (including cracking) has been reported.

Failure of the 80VU fittings, in combination with a high load factor or strong vibration, could lead to failure of the rack structure and/or computers or rupture/disconnection of the cable harnesses to one or more computers located in the 80VU rack. Even though the computer functions are duplicated across other racks, multiple system failures or (partial) disconnection of systems, if occurring during a critical phase of flight, could result in reduced control of the aeroplane.

To address this potential unsafe condition, Airbus published SB A320-25A1555 and SB A320-25-1557 original issue, and EASA issued AD 2007-0276 to require repetitive inspections of the lower lateral 80VU fittings and the lower central 80VU support and, depending on findings, the accomplishment of corrective actions. That AD was later revised to introduce a reinforced lower central support (SB A320-53-1215) as an optional terminating action for the repetitive inspections.

After EASA AD 2007-0276R1 was issued, prompted by in-service experience, Airbus published SB A320-25A1555 Revision 03 to amend the inspection program, and EASA issued AD 2012-0134, superseding EASA AD 2007-0276R1, to require those inspections at reduced intervals.

After EASA AD 2012-0134 was issued, new damage was found on aeroplanes having Airbus SB A320-53-1215 and SB A320-25-1557 embodied, which therefore could no longer be considered terminating action for the repetitive inspections. Damage was also found on aeroplanes on which Airbus mod 34804 (VU reinforcement – 1st step) was embodied in production. Consequently, Airbus published SB A320-25-1BKJ Revision 02 providing new instructions for inspection of the 80VU rack, and EASA issued AD 2021-0045, which superseded EASA AD 2012-0134, to expand the Applicability and require those new repetitive inspections.

After EASA AD 2021-0045 was issued, additional damage was reported which led to amendment of the compliance time to inspect certain affected parts, depending on aeroplane configuration. Consequently, EASA issued AD 2021-0172, superseding EASA AD 2021-0045, to update the compliance time for the various configurations.

After EASA AD 2021-0172 was issued, following customer feedback, Airbus published A320-25-1BKJ at Revision 02, to amend and provide additional clarification on the threshold and compliance time for inspection applicable to each aeroplane configuration and zone.

Consequently, EASA issued AD 2022-0120 (later revised), retaining the requirements of EASA AD 2021-0172, which was superseded, and requiring accomplishment of inspections and corrective actions in accordance with the amended SB instructions (A320-25-1BKJ at Revision 04).



After EASA AD 2022-0120R1 was issued, Airbus determined, after additional analysis, that the repetitive inspection interval for Group 4 aeroplanes can be increased, while for Group 1, Group 2 and Group 3 aeroplanes the repetitive inspection interval has to remain unchanged. Consequently, Airbus SB A320-25-1BKJ was revised to Revision 05, and EASA AD 2022-0120R1 was revised to extend the repetitive inspection interval for Group 4 aeroplanes.

After EASA AD 2022-0120R2 was issued, it was determined that also NEO aeroplanes are affected by this unsafe condition. Consequently, Airbus issued SB A320-25-1CJH for NEO aeroplanes and EASA issued AD 2025-0237 accordingly, introducing repetitive inspection requirements for those aeroplanes.

Since this AD was issued, it has been determined that certain RI have been erroneously quoted as applicable to NEO aeroplanes in Airbus SB A320-25-1CJH. Consequently, Airbus issued SB A320-25-1CJH Revision 02, also introducing specific repair instructions for NEO aeroplanes.

For the reason described above, this AD is revised accordingly, updating the reference to the repair instructions in Table 1 for Group 5 aeroplanes.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Inspection(s):

- Before exceeding the threshold and, thereafter, at intervals as defined in Table 1 of this AD, as applicable depending on aeroplane group and zone, accomplish a Special Detailed Inspection (SDI) of each zone in accordance with the instructions of the SB.

Table 1 – SDI by Group and Zone

Group	Zone	Threshold (whichever occurs later)	Interval
1	A	Before exceeding 19 500 flight cycles (FC) since aeroplane first flight, or before exceeding 19 500 FC since last repair per Airbus SB A320-25A1555 at any revision, or within 500 FC since last inspection per Airbus SB A320-25A1555 Revision 03	Within 500 FC
	B	or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	
	C	Before exceeding 19 500 FC since aeroplane first flight or within 500 FC after the 03 August 2021 [the effective date of EASA AD 2021-0172]	



Table 1 – SDI by Group and Zone – continued

Group	Zone	Threshold (whichever occurs later)	Interval
2	A	Within 19 500 FC after Airbus SB A320-25-1557 embodiment, or within 19 500 FC after last repair per RI R53113174000 and R53113174001 or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	Within 500 FC
	B	Before exceeding 19 500 FC since aeroplane first flight, or before exceeding 19 500 FC since last repair per Airbus SB A320-25A1555 at any revision, or within 500 FC since last inspection per Airbus SB A320-25A1555 Revision 03 or within 500 FC after 07 July 2022 [the effective date of EASA AD 2022-0120R1]	
	C	before exceeding 19 500 FC since aeroplane first flight or within 500 FC after the 03 August 2021 [the effective date of EASA AD 2021-0172]	



Table 1 – SDI by Group and Zone – continued

Group	Zone	Threshold (whichever occurs later)	Interval
3	A	Within 19 500 FC after Airbus SB A320-25-1557 embodiment, or within 19 500 FC after last repair per RI R53113174000 and R53113174001, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	Within 1000 FC
	B	Within 19 500 FC after Airbus SB A320-53-1215 embodiment, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	
	C	Within 19 500 FC since aeroplane first flight, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	
4	A	Before exceeding 19 500 FC since aeroplane first flight, or within 19 500 FC after last repair per RI R53113174002 and R53113174003, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	Within 2000 FC
	B	Before exceeding 19 500 FC since aeroplane first flight, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	
	C	Before exceeding 19 500 FC since aeroplane first flight, or within 500 FC after 03 August 2021 [the effective date of EASA AD 2021-0172]	



Table 1 – SDI by Group and Zone – continued

Group	Zone	Threshold (whichever occurs later)	Interval
5	A	Before exceeding 19 500 FC since aeroplane first flight, or within 19 500 FC after last repair per RI R53113174004 and R53113174005 or within 3 months after 10 November 2025 [the effective date of the original issue of this AD]	Within 2000 FC
	B	Before exceeding 19 500 FC since aeroplane first flight or	
	C	within 3 months after 10 November 2025 [the effective date of the original issue of this AD]	

Corrective Action(s):

- (2) If, during any inspection as required by paragraph (1) of this AD, any discrepancy is detected, accomplish the applicable corrective action(s) within the compliance time as specified in, and in accordance with the instructions of, the SB.

Credit:

- (3) For Airbus CEO aeroplanes: Inspections and corrective action(s), accomplished on an aeroplane before 07 July 2022 [the effective date of EASA AD 2022-0120 at original issue] in accordance with the instructions of Airbus SB A320-25-1BKJ at Revision 02 or Revision 03, are acceptable to comply with the (initial) requirements of paragraphs (1) and (2) of this AD for that aeroplane. From 07 July 2022 [the effective date of EASA AD 2022-0120 at original issue], inspections and corrective actions have to be accomplished in accordance with the instructions of the SB.
- (4) Inspection(s) and corrective action(s), as applicable, accomplished on an aeroplane, before 10 November 2026 [the effective date of the original issue of this AD], in accordance with the instructions of SB A320-25-1CJH at original issue, are acceptable to comply with the (initial) requirements of paragraphs (1) and (2) of this AD, as applicable, for that aeroplane.

Reporting:

- (5) Within 90 days after the accomplishment of each SDI as required by paragraph (1) of this AD, or after 10 November 2026 [the effective date of the original issue of this AD], whichever occurs later, report the inspection results (including no findings for the first inspection only) to Airbus. Using the inspection report attached to the SB at any revision, as applicable, is an acceptable method to comply with this requirement.

Terminating Action:

- (6) None.



Ref. Publications:

Airbus SB A320-25A1555 Revision 03 dated 28 February 2012.

Airbus SB A320-25-1557 original issue dated 14 June 2007, or Revision 01 dated 07 February 2008, or Revision 02 dated 05 November 2008, or Revision 03 dated 01 July 2013.

Airbus SB A320-53-1215 original issue dated 05 November 2008, or Revision 01 dated 26 July 2013.

Airbus SB A320-25-1BKJ Revision 02 dated 09 April 2020, or Revision 03 dated 17 February 2022, or Revision 04 dated 29 April 2022, Revision 05 dated 30 May 2023 or Revision 06 dated 22 October 2024.

Airbus SB A320-25-1CJH Revision 01 dated 01 August 2025 or Revision 02 dated 28 April 2026.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The original issue of this AD was posted on 16 September 2025 as PAD 25-147 for consultation until 14 October 2025. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – 1IASA; E-mail: account.airworth-eas@airbus.com.

