

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-559-002(A) R3
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

EC 130 helicopters

Main rotor - STARFLEX star (ATA 05, 62)

1. EFFECTIVITY:

EC 130 version B4 helicopters equipped with STARFLEX stars P/N 350A31.1916.00, mounted on Main Rotor Hubs (MRH) prior to the embodiment of MOD 076221.

2. REASONS:

This Airworthiness Directive (AD) is issued following several occurrences of rapid bonding failure of the metal bush that is installed on the STARFLEX star arm ends. In some cases, these incidents caused the pilots to land quickly due to strong vibrations in the cabin.

Revision 1 introduces Revision 1 of the Alert Telex, with no change to the contents of the Airworthiness Directive and adds the Note in paragraph 3.1.

Revision 2 renders the embodiment of MOD 076221, which is the subject of referenced EUROCOPTER EC 130 Alert Service Bulletin (ASB) No. 62A001, mandatory.

Revision 3 excludes the MRHs post MOD 076221 from the scope of application of the AD.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

3.1. Before the next flight after the effective date of the original issue of this AD, then after each flight after which the rotors are stopped, on MRHs not embodying MOD 076221, check the adhesive bead of the metal bushes bonded at the end of the three arm of STARFLEX stars, in compliance with the instructions described in paragraph 2 of referenced EC 130 Alert Telex No. 05A001 R2.

Note: The check can be carried out by a pilot having received the appropriate training.

- 3.2. No later than February 28, 2002, install a stop stud at the bottom of each frequency adapter per MOD 076221, in compliance with the instructions described in paragraph 2 of referenced EC 130 ASB No. 62A001.
- 3.3. From the effective date of Revision 2 of this AD, before installation on aircraft, on main rotor heads held as spares, install a stop stud at the bottom of each frequency adapter per MOD 076221, in compliance with the instructions described in paragraph 2 of referenced EC 130 ASB No. 62A001.

REF.: EUROCOPTER EC 130 Alert Telex No. 05A001 R2
EUROCOPTER EC 130 Alert Service Bulletin No. 62A001.

This Revision 3 replaces AD 2001-559-002(A) R2 dated February 06, 2002.

EFFECTIVE DATES :

Original AD : On receipt of the telegraphic AD
issued on **NOVEMBER 12, 2001**

Revision 1 : On receipt from **NOVEMBER 28, 2001**

Revision 2 : On receipt from **FEBRUARY 06, 2002**

Revision 3 : On receipt from **MAY 15, 2002**