

SERVICE BULLETIN SUMMARY

AIRBUS CUSTOMER SERVICES DIRECTORATE 1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX FRANCE Tel : (33) 5 61 93 33 33 Telex : AIRBU 530526F Fax : (33) 5 61 93 42 51

This summary is for information only and is not approved for modification of the aircraft.

# **MANDATORY MANDATORY MANDATORY**

ATA SYSTEM: 34

### TITLE: NAVIGATION - GENERAL - REPLACE AOA PROBE CONIC PLATE BY AOA PROBE FLAT PLATE

#### \*\*CONF ALL

#### MODIFICATIONS

MODIFICATION CLASSIFICATION								
MAJOR	MAJOR 203295S32646							
MINOR	None							

<u>NOTE</u>: As per EASA IR 21, a minor change is one that has no appreciable effect on the mass, balance, structural strength, reliability, operational characteristics affecting the airworthiness of the product. All other changes are major changes.

#### REASON/DESCRIPTION/OPERATIONAL CONSEQUENCES

Following a recent in-service event, as a precautionary measure, Airbus requires to suspend the installation of the AOA (Angle Of Attack) conic plates as per Operator Information Transmission (OIT) No. 999.0086/12, currently performed through an Airbus monitored campaign with Service Bulletin No. A340-34-5081.

This modification requires the removal of the conic plates PN F3411060200000 and PN F3411060900000, and the installation of flat plates PN F3411007920200 (LH) / PN F3411007920300 (RH).

Also, it requires to change the 3 AOA Sensor Protection Covers (FINs 7955ME, 7956ME and 7957ME) stored in Flight Kit No 2 (FIN 7500NW or FIN 7503NW).

Refer to OIT No. 999.0086/12 and FOT No. 999.0089/12 for further explanations.

For aircraft already fitted with the AOA conic plates through retrofit or from production, Airbus released associated operational recommendations in an FOT No. 999.0089/12, the Operations Engineering Bulletin (OEB) 45 and Flight Manual (FM) Temporary Revision 294.

This Service Bulletin modifies the Ground System Equipment (the AOA Protection Covers) needed for parking, mooring or storing the aircraft.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN SUMMARY

Accomplishment of this Service Bulletin cancels OEB 45 and FM TR294. It is expected that an Airworthiness Directive (AD) published by the European Aviation Safety Agency (EASA) will be issued to confirm this cancellation.

This Service Bulletin modifies the Ground System Equipment (the AOA Protection Covers) needed for parking, mooring or storing the aircraft.

The operational consequence of this Service Bulletin is the modification of the Flight Manual (FM) and Flight Crew Operating Manual (FCOM) by removing temporary operational measures introduced by OEB 45, FOT No. 999.0089/12 and FM TR294.

#### **GENERAL EVALUATION**

EVALUATION TABLE					
COMPLIANCE	MANDATORY (1)	CANCELS INSPECTION SB	NO		
POTENTIAL AD	YES	A/C OPERATION AFFECTED	YES		
RELIABILITY AFFECTED	NO	PAX COMFORT AFFECTED	NO		
COST SAVING	NO	LROPS AFFECTED	NO		
STRUCTURAL LIFE EXTN	NO	VENDOR SB INVOLVED	NO		

NOTE (1): Service Bulletin must be accomplished.

#### **MATERIAL PRICE INFORMATION**

#### \*\*CONF 001

MATERIAL PRICE INFORMATION TABLE						
MATERIAL SET	QTY PER A/C	PRICE PER A/C (USD)	MAIN PARTS			
Component COMPA01	1	See SB	Flat Plates, Covers			
Component COMPA02	1	See SB	Screws			

#### \*\*CONF 002

MATERIAL PRICE INFORMATION TABLE						
MATERIAL SET	MAIN PARTS					
Component COMPA01	1	See SB	Flat Plates, Covers			
Component COMPA02	1	See SB	Screws			

#### EFFECTIVITY

#### \*\*CONF ALL

This Service Bulletin is applicable to this (these) operator(s) :

06U	25R	36V	62X	70U	72W	AHY	CES	CHH	DLH	ETD	HFY	IBE
QAF	QTR	SAA	SIA	TAM	THA	UAE	VIR					

#### **CONCURRENT REQUIREMENTS**

None

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN SUMMARY

#### **REFERENCES / REPERCUSSIONS**

TFU	None
OEB	45
AOT	None
SIL	None
LINE MAINTENANCE AFFECTED	No
LIFE LIMIT	None
OTHER	OIT No. 999.0086/12
OTHER	FOT No. 999.0089/12

#### NATURE OF THE WORK

AIRCRAFT	YES
EQUIPMENT	NO
HARD	NO
SOFT	NO
OBRM	NO

#### MANPOWER

#### \*\*CONF 001

Task 345093-831-801-001: Modification of the AOA sensor plates.			
TOTAL MANHOURS	6.25		
ELAPSED TIME (HOURS)	4.25		

#### \*\*CONF 002

Task 345093-831-801-001: Modification of the AOA sensor plates.			
TOTAL MANHOURS	6.25		
ELAPSED TIME (HOURS)	4.25		

#### **APPENDICES**

#### \*\*CONF ALL

APPENDIX 01: Elapsed Time Assumption


5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



SERVICE BULLETIN SUMMARY

\*\*CONF ALL



### **BEFORE**



THALES



GOODRICH

#### NOTE:

TYPICAL ILLUSTRATION ASSOCIATED WITH THALES OR GOODRICH AOA SENSORS.

F\_SB\_345093\_5\_SAAA\_01\_01

Figure A-FSAAA - Sheet 01

Α

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 4

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.



SERVICE BULLETIN SUMMARY

\*\*CONF ALL

### **AFTER**





#### NOTE:

ONLY ONE CONFIGURATION SHOWN, AOA SENSOR DEPENDS ON AIRCRAFT CONFIGURATION.

TYPICAL ILLUSTRATION ASSOCIATED WITH THALES OR GOODRICH AOA SENSORS.

#### CAUTION:

NEW AOA FLAT PLATES SHALL NOT BE PAINTED AND SHALL REMAIN AS DELIVERED.

F\_SB\_345093\_5\_SAAA\_02\_01

Figure A-FSAAA - Sheet 02

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093


REVISION No.: 00 - Jan 30/13

Page: 5

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

SERVICE BULLETIN SUMMARY

\*\*CONF 001



F\_SB\_345093\_5\_SBAA\_01\_01

Figure A-FSBAA - Sheet 01

5 DATE: Jan 30/13 SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 6

SERVICE BULLETIN SUMMARY

\*\*CONF 002




Figure A-FSBAB - Sheet 01

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

**SA340-500/600** 

SERVICE BULLETIN SUMMARY

This Page Intentionally Left Blank

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



AIRBUS CUSTOMER SERVICES DIRECTORATE 1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX FRANCE Tel : (33) 5 61 93 33 33 Telex : AIRBU 530526F Fax : (33) 5 61 93 42 51

# **MANDATORY MANDATORY MANDATORY**

ATA SYSTEM: 34

### TITLE: NAVIGATION - GENERAL - REPLACE AOA PROBE CONIC PLATE BY AOA PROBE FLAT PLATE

MODIFICATION No.: 203295S32646

This document contains AIRBUS PROPRIETARY INFORMATION and shall at all times remain the property of AIRBUS; no intellectual property right or licence is granted by AIRBUS in connection with any information contained in it. It is delivered on the express condition that said document and the information contained in it shall be treated as confidential, shall not be used for any purpose other than that for which it is hereby delivered. It shall not be disclosed in whole or in part to third parties and shall not be duplicated in any manner (except for the purposes of performing the tasks described hereunder and provided that any recipient of such document shall comply with the conditions herein), without AIRBUS prior written consent.

#### 1. PLANNING INFORMATION

#### \*\*CONF ALL

- A. EFFECTIVITY
  - <u>NOTE</u>: This modification is applicable by Service Bulletin only.
  - <u>NOTE</u>: This Service Bulletin is only applicable to aircraft listed below on which Mod. No. 201609S31961 (INSTALL A NEW CONIC PLATE FOR NEW AOA (ANGLE OF ATTACK SENSOR) THALES) or Mod. No. 201610S31887 (INSTALL A NEW CONIC PLATE FOR NEW AOA (ANGLE OF ATTACK SENSOR) GOODRICH AND OLD THALES) are embodied or on which Service Bulletin No. A340-34-5081 is accomplished.
  - (1) Models

340-541 340-542 340-642

(2) Effectivity by MSN

0371 0376 0383 0391 0394 0410 0416-0417 0426 0431 0436 0440 0445 0449 0453 0457 0460 0464 0468 0471 0475 0478 0482 0485 0488 0492 0495 0499 0514 0517 0520 0523 0531 0534 0537 0540 0543 0547 0557 0560 0563 0566 0569 0572 0575 0577 0580 0583 0586 0601 0604 0606 0608 0611 0615 0617 0619 0622 0624 0626 0628 0630 0639 0672 0677 0681 0685 0689 0694 0698 0702 0706 0710 0715 0719 0723 0727 0736 0740 0744 0748 0753 0757 0761-0768 0771 0775 0779 0783 0787

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

0790 0794 0798 0804 0812 0829 0837 0846 0848 0870 0886 0894 0897 0902 0910 0912 0917 0924 0929 0933 0953 0960 0972 0981 0987 0993 1005 1017 1030 1040 1079 1091 1102 1122

(3) Effectivity by Operator

The Operator/MSN relationship is provided for information only and is correct at the time of issue in accordance with the information available to AIRBUS. Any future changes resulting from transfer of an aircraft from one operator to another will not be reflected in this list unless the Service Bulletin is revised for another reason.

OPERATOR	MSN
06U	1091 1102
25R	0924
36V	0391 0416
62X	0779
70U	0902
72W	0917
AHY	0886 0894
CES	0468 0488 0514 0577 0586
СНН	0436 0453 0475
DLH	0482 0517 0523 0537 0540 0543 0566 0569 0580 0583 0762 0763
	0767 0771 0790 0794 0812 0846 0848 0897 0972 0981 0987 1005
ETD	0748 0757 0761 0783 0829 0837 0870 0929 0933 1030 1040
HFY	0910 0912
IBE	0431 0440 0460 0601 0604 0606 0617 0619 0672 0702 0727 0744
	0960 0993 1017 1079 1122
QAF	0495
QTR	0715 0740 0766 0798
SAA	0410 0417 0426 0531 0534 0547 0557 0626 0630
SIA	0478 0492 0499 0560 0563
ТАМ	0445 0464
THA	0624 0628 0677 0681 0689 0698 0710 0719 0775 0953
UAE	0394 0457 0471 0485 0520 0572 0608 0611 0685 0694
VIR	0371 0376 0383 0449 0575 0615 0622 0639 0706 0723 0736 0753
	0764 0765 0768 0787 0804

(4) Configuration by MSN

MSN	CONFIGURATION
0371 0376 0383 0391 0416 0449	001

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

MSN	CONFIGURATION
0394 0410 0417 0426 0431 0436 0440 0445 0453 0457 0460	002
0464 0468 0471 0475 0478 0482 0485 0488 0492 0495 0499	
0514 0517 0520 0523 0531 0534 0537 0540 0543 0547 0557	
0560 0563 0566 0569 0572 0575 0577 0580 0583 0586 0601	
0604 0606 0608 0611 0615 0617 0619 0622 0624 0626 0628	
0630 0639 0672 0677 0681 0685 0689 0694 0698 0702 0706	
0710 0715 0719 0723 0727 0736 0740 0744 0748 0753 0757	
0761 0762 0763 0764 0765 0766 0767 0768 0771 0775 0779	
0783 0787 0790 0794 0798 0804 0812 0829 0837 0846 0848	
0870 0886 0894 0897 0902 0910 0912 0917 0924 0929 0933	
0953 0960 0972 0981 0987 0993 1005 1017 1030 1040 1079	
1091 1102 1122	

(5) Configuration definition

\*\*CONF 001 Config. 001 is valid for aircraft on which Mod. No. 50648D44169 is not embodied.

\*\*CONF 002 Config. 002 is valid for aircraft on which Mod. No. 50648D44169 is embodied.

(6) Material Effectivity

MATERIAL	QTY PER A/C	SEE NOTES
Consumable CMLA01	1	
Component COMPA01	1	
Component COMPA02	1	

#### B. <u>CONCURRENT REQUIREMENTS</u>

None

#### C. <u>REASON</u>

(1) History

Following a recent in-service event, as a precautionary measure, Airbus requires to suspend the installation of the AOA (Angle Of Attack) conic plates as per Operator Information Transmission (OIT) No. 999.0086/12, currently performed through an Airbus monitored campaign with Service Bulletin No. A340-34-5081.

(2) Objective/Action

This modification requires the removal of the conic plates PN F3411060200000 and PN F3411060900000, and the installation of flat plates PN F3411007920200 (LH) / PN F3411007920300 (RH).

Also, it requires to change the 3 AOA Sensor Protection Covers (FINs 7955ME, 7956ME and 7957ME) stored in Flight Kit No 2 (FIN 7500NW or FIN 7503NW).

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



(3) Advantages

Refer to OIT No. 999.0086/12 and FOT No. 999.0089/12 for further explanations.

(4) Operational/Maintenance Consequences

For aircraft already fitted with the AOA conic plates through retrofit or from production, Airbus released associated operational recommendations in an FOT No. 999.0089/12, the Operations Engineering Bulletin (OEB) 45 and Flight Manual (FM) Temporary Revision 294.

This Service Bulletin modifies the Ground System Equipment (the AOA Protection Covers) needed for parking, mooring or storing the aircraft.

Accomplishment of this Service Bulletin cancels OEB 45 and FM TR294. It is expected that an Airworthiness Directive (AD) published by the European Aviation Safety Agency (EASA) will be issued to confirm this cancellation.

This Service Bulletin modifies the Ground System Equipment (the AOA Protection Covers) needed for parking, mooring or storing the aircraft.

The operational consequence of this Service Bulletin is the modification of the Flight Manual (FM) and Flight Crew Operating Manual (FCOM) by removing temporary operational measures introduced by OEB 45, FOT No. 999.0089/12 and FM TR294.

#### D. DESCRIPTION

To accomplish this Service Bulletin it is necessary to :

#### \*\*CONF 001

Task 345093-831-801-001: Modification of the AOA sensor plates.

(1) Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.

(2) Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.

(3) Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7500NW).

#### \*\*CONF 002

Task 345093-831-801-001: Modification of the AOA sensor plates.

(1) Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.

(2) Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.

(3) Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7503NW).

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



#### \*\*CONF ALL

#### E. <u>COMPLIANCE</u>

(1) Classification

MANDATORY: Service Bulletin must be accomplished.

(2) Accomplishment Timescale

Accomplishment of this Service Bulletin must be done at the earliest opportunity where manpower and facilities are available but within 5 months from the initial Service Bulletin date.

This Service Bulletin has been classified Mandatory. It is expected that an Airworthiness Directive (AD) published by the European Aviation Safety Agency (EASA) will be issued to confirm this classification. It is anticipated that the AD will confirm the threshold given above but reference should be made to the AD for confirmation of the mandated accomplishment timescale.

#### F. <u>APPROVAL</u>

The technical content of this document is approved under the authority of Design Organisation Approval No. EASA.21J.031.

If an aircraft listed in the effectivity has a modification or repair embodied that is not of AIRBUS origin, and which affects the content of this Service Bulletin, the operator is responsible for obtaining approval by its airworthiness authority for any adaptation necessary before incorporation of the Service Bulletin.

#### G. MANPOWER

The manpower estimates given in this Service Bulletin are based on the direct labor cost to do the work. These estimates assume that the work will be done by experienced personnel, and may need to be revised upwards to suit operator's circumstances. The estimates do not include the time to prepare, plan or inspect the work. Manufacture and procurement of parts and tools, drying times for paints, sealants, etc., and general administration work are also not included.

#### \*\*CONF 001

Task 345093-831-801-001: Modification of the AOA sensor plates.		
Get Access	0.50	
On Aircraft		
Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.	1.50	
Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.	3.00	
Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7500NW).	0.50	
Tests	0.25	
Close-Up	0.50	

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

Task 345093-831-801-001: Modification of the AOA sensor plates.			
TOTAL MANHOURS 6.25			
ELAPSED TIME (HOURS) 4.25			

<u>NOTE</u>: For detail concerning the elapsed time assumption, refer to APPENDIX 01: Elapsed Time Assumption .

#### \*\*CONF 002

Task 345093-831-801-001: Modification of the AOA sensor plates.		
Get Access	0.50	
On Aircraft		
Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.	1.50	
Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.	3.00	
Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7503NW).	0.50	
Tests	0.25	
Close-Up	0.50	
TOTAL MANHOURS	6.25	
ELAPSED TIME (HOURS)	4.25	

<u>NOTE</u>: For detail concerning the elapsed time assumption, refer to APPENDIX 01: Elapsed Time Assumption .

#### \*\*CONF ALL

#### H. WEIGHT AND BALANCE

The weight and balance estimates given in this Service Bulletin are based on the Manufacturer's Empty Weight (MEW) and do not include operator item's. For the definition of (MEW) and operator's items refer to Weight and Balance Manual (WBM) Chapter 1-00-07.

Manufacturers Empty Weight	-0.549 KG	(-1.2103 LB)
Effect on Balance	-7.502 KGM	(-54.262 LB.FT )

#### I. ELECTRICAL LOAD DATA

Not Changed

#### J. <u>REFERENCES</u>

#### \*\*CONF 001

Aircraft Maintenance Manual (AMM)	06-20-00 12-34-24 52-30-00	06-31-53 20-21-11 52-41-00	06-41-53 20-28-00
Consumable Material List (CML)			
ATA Common Support Data Dictionary (CSDD), Chapter 2			

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

Elec. Std. Practices Manual (ESPM)	20-51-20	20-55-00	
Flight Crew Operating Manual (FCOM)			
Flight Manual (FM)			
Standards Manual (SM)			
Structural Repair Manual (SRM)	51-24-00	51-42-00	51-43-00
Weight and Balance Manual (WBM)	Chapter 1	-00-07	

#### \*\*CONF 002

Aircraft Maintenance Manual (AMM)	06-20-00	06-31-53	06-41-53
	12-34-24	20-21-11	20-28-00
	52-30-00	52-41-00	
Consumable Material List (CML)			
ATA Common Support Data Dictionary (CSDD),			
Chapter 2			
Elec. Std. Practices Manual (ESPM)	20-51-20	20-55-00	
Flight Crew Operating Manual (FCOM)			
Flight Manual (FM)			
Standards Manual (SM)			
Structural Repair Manual (SRM)	51-24-00	51-42-00	51-43-00
Weight and Balance Manual (WBM)	Chapter 1	-00-07	

#### \*\*CONF ALL

#### K. PUBLICATION AFFECTED

Aircraft Maintenance Manual (AMM)	10-11-00	12-21-11	34-11-19
Aircraft Wiring List (AWL)			
Flight Crew Operating Manual (FCOM)			
Flight Manual (FM)			
Illustrated Parts Catalog (IPC)	25-73-04	34-11-01	
Tool Equipment Manual (TEM)	10-11-00		

This Service Bulletin has an operational impact. Please inform AIRBUS, at least four weeks in advance, in case you need your operational documentation to be amended by a revision prior to Service Bulletin embodiment. For this purpose, please request the revision by e-mail, online through the SB Reporting service or alternatively by fax to:

SEDOR4, AIRBUS Customer Services Technical Data Fax No.: (33) 5 61 93 28 06 E-mail: sb.reporting@airbus.com

SB Reporting service is accessible on-line through AIRBUSWorld from:

- 'My on-line services' section, available on all AIRBUSWorld pages
- The Maintenance & Engineering Community, in:
  - . Modify and Upgrade page Access SB and VSB section.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 7

#### SERVICE BULLETIN

These amendments will be confirmed by the next normal revision of operational documentation, once your Service Bulletin accomplishment report has been sent, as usual, to our Customer Services Aircraft In-Service Data (SEDOR4).

#### L. INTERCHANGEABILITY/MIXABILITY

#### \*\*CONF 001

DESCRIPTION	OLD PART N°	NEW PART N°	INT	MIXABILITY	SEE NOTES
Plate	F3411060900000	F3411007920200	01	NO	
Plate	F3411060200000	F3411007920200	01	NO	
AOA Sensor	98D34203003000	98F10001000000	01	NO	
Protection Cover					
Plate	F3411060200000	F3411007920300	01	NO	
Plate	F3411060900000	F3411007920300	01	NO	

- <u>NOTE</u>: For definitions of interchangeability codes in column INT., refer to ATA Common Support Data Dictionary (CSDD), Chapter 2.
- <u>NOTE</u>: Only the mixability configuration(s) and condition(s) stated in this Service Bulletin are approved.

#### \*\*CONF 002

DESCRIPTION	OLD PART N°	NEW PART N°	INT	MIXABILITY	SEE NOTES
Plate	F3411060900000	F3411007920200	01	NO	
Plate	F3411060200000	F3411007920200	01	NO	
AOA Sensor	98D34203003000	98F10001000000	01	NO	
Protection Cover					
Plate	F3411060200000	F3411007920300	01	NO	
Plate	F3411060900000	F3411007920300	01	NO	

<u>NOTE</u>: For definitions of interchangeability codes in column INT., refer to ATA Common Support Data Dictionary (CSDD), Chapter 2.

<u>NOTE</u>: Only the mixability configuration(s) and condition(s) stated in this Service Bulletin are approved.

#### \*\*CONF ALL

#### M. SPARES

AOA Sensor Protection Cover	98D34203003000
Plate	F3411060200000
Plate	F3411060900000

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



#### 2. MATERIAL INFORMATION

#### \*\*CONF ALL

#### A. MATERIAL - PRICE AND AVAILABILITY

(1) Procurement Addresses

This Service Bulletin is the subject of an AIRBUS monitored retrofit campaign.

Component COMPA01	Customers with aircraft shown in the effectivity of this Service Bulletin should send a purchase order to AIRBUS. Quote the number of this Service Bulletin. The address is: AIRBUS Material, Logistics and Suppliers IFD - In Flight Desk Weg beim Jaeger 150 D-22335 HAMBOURG GERMANY
	For ordering by internet: http://spares.airbus.com For ordering by fax: +49 40 50 76 4012 For ordering by E-mail: ifd.spares@airbus.com
Component COMPA02	<ul> <li>Airbus Material, Logistics and Suppliers do not stock standard hardware as competitive multiple suppliers ensure access to minimum prices Airbus recommends Customers with aircraft shown in the effectivity of this Service Bulletin to send a purchase order to B/E Aerospace. The address is:</li> <li>B/E AEROSPACE INC</li> <li>CONSUMABLES MANAGEMENT</li> <li>10000 NW 15TH Terrace Miami</li> <li>FL 33172</li> <li>USA</li> <li>Tel EMEA: +49 (0) 40 822 285 31500</li> <li>Tel US: +1 305 925 2600</li> <li>Tel ASIA: +1 310 900 1300</li> <li>Fax EMEA: +49 (0) 40 822 285 31010</li> <li>Fax US: +1 305 507 7191</li> <li>Fax ASIA: +1 310 819 1200</li> <li>SITA: MIAMMCR</li> <li>E-Mail: AOGdesk_CMG@beaerospace.com</li> <li>internet: www.beconsumables.com</li> <li>or, alternatively any other source on the open market.</li> </ul>

(2) Price and Availability

No AIRBUS kit will be provided.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

Operator supplied AIRBUS parts required to accomplish this Service Bulletin are to be purchased by a spares purchase order.

Operator supplied standard hardware parts required to accomplish this Service Bulletin are to be supplied from the Operator's stock.

#### B. INDUSTRY SUPPORT INFORMATION

AIRBUS will share the costs of accomplishment of this Service Bulletin by crediting the operator supplied AIRBUS parts for orders placed before Jun 30/13. Claims for this allowance should be received not later than 90 days after completion of the last affected aircraft of your fleet.

For the accomplishment of this Service Bulletin before Jun 30/13, AIRBUS will credit the manhours indicated in this Service Bulletin at the agreed in-house warranty labor rate for claims received not later than 90 days after completion of the last affected aircraft of your fleet.

For the organisation of this retrofit, you are kindly requested to contact AIRBUS retrofit management department.

#### AIRBUS

CUSTOMER SERVICES DIRECTORATE 1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX France Tel : (33) 5 67 19 06 22 E-mail : monitored.retrofit@airbus.com Fax : (33) 5 61 93 27 45

#### C. LIST OF COMPONENTS

No Kit

#### D. LIST OF MATERIALS - OPERATOR SUPPLIED

(1) Consumable Materials

Consumable CMLA01

ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.		SEE NOTES
	Release Agent (obsolete Use 05-013a)	05-013	As required	
	Corrosion Inhibitingfillet Consistency	09-016	As required	
	Fuel Tank Sealant Quick Repair Permanent	09-058	As required	
	Solvent General Purpose	11-026	As required	

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

SERVICE BULLETIN

(2) Components

Component COMPA01

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
2	F3411007920200	1	PLATE	(2)	F3411060200000	01	
				(2)	F3411060900000	01	
2	F3411007920300	2	PLATE	(2)	F3411060200000	01	
				(2)	F3411060900000	01	
	98F10001000000	3	AOAPRTCT		98D34203003000	01	

- <u>NOTE</u>: For definitions of interchangeability codes in column INT., refer to ATA Common Support Data Dictionary (CSDD), Chapter 2.
- <u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Component COMPA02

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	 SEE NOTES
1	NAS1102-3-14	21	SCREW			

- <u>NOTE</u>: If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.
- <u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.
- (3) Equipment

None

#### E. PARTS TO BE RE-IDENTIFIED BY OPERATOR

None

F. TOOLING

None

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



This Page Intentionally Left Blank

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 12



#### 3. ACCOMPLISHMENT INSTRUCTIONS

Task 345093-831-801-001 - Modification of the AOA sensor plates.

- WARNING: MAKE SURE THAT YOU OBEY ALL THE WARNINGS AND ALL THE CAUTIONS INCLUDED IN THE REFERENCED PROCEDURES.
- <u>CAUTION</u>: ALWAYS OBEY THE PRECAUTIONS THAT FOLLOW TO KEEP ELECTRICAL WIRING IN A SATISFACTORY CONDITION (ELECTRICALLY AND MECHANICALLY SERVICEABLE). WHEN YOU DO MAINTENANCE WORK, REPAIRS OR MODIFICATIONS, ALWAYS KEEP ELECTRICAL WIRING, COMPONENTS AND THE WORK AREA AS CLEAN AS POSSIBLE. TO DO THIS:
  - PUT PROTECTION, SUCH AS PLASTIC SHEETING, CLOTHS, ETC; AS NECESSARY ON WIRING AND COMPONENTS.
  - REGULARLY REMOVE ALL SHAVINGS, UNWANTED MATERIAL AND OTHER CONTAMINATION.

THESE PRECAUTIONS WILL DECREASE THE RISK OF CONTAMINATION AND DAMAGE TO THE ELECTRICAL WIRING INSTALLATION.

IN CASE OF CONTAMINATION REFER TO ESPM 20-55-00.

#### Task Associated Data

#### \*\*CONF 001

Zone			
121 122 160			
	Modified FIN		
7955ME 7956ME 795	57ME 7500NW		
	Access		
Door	823		
Other access	Access platform		
Manpower			
TOTAL MANHOURS		6.25	
ELAPSED TIME (HO	URS)	4.25	

#### \*\*CONF 002

Zone			
121 122 130	121 122 130		
	Modified FIN		
7955ME 7956ME 79	7955ME 7956ME 7957ME 7503NW		
	Access		
Door	821		
Other access Access platform			

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

М	anpower	
TOTAL MANHOURS	6.25	
ELAPSED TIME (HOURS)	4.25	

#### \*\*CONF ALL

#### A. <u>GENERAL</u>

#### \*\*CONF 001

#### (1) Subtask 345093-910-001-001 - Standard Practices

Manpower Resourc	es
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	06-20-00, Page Block 001 06-31-53, Page Block 001 Task 20-21-11-911-801 Task 20-28-00-912-802 Task 20-28-00-912-805	
Consumable Material List (CML)		
Elec. Std. Practices Manual (ESPM)	20-51-20	
Structural Repair Manual (SRM)	51-24-00 51-42-00 51-43-00	

- (a) For the specification of materials (Mat. No.) given in this Service Bulletin, refer to Consumable Materials List (CML).
- (b) For the Frame (FR) identification, refer to AMM 06-31-53, Page Block 001.
- (c) For the identification of zones, refer to AMM 06-20-00, Page Block 001.
- (d) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-801.
- (e) Remove and install fasteners in accordance with SRM 51-42-00.
- (f) Obtain alternative and substitute fasteners data, in accordance with SRM 51-43-00.
- (g) If the length of any fastener specified in this Service Bulletin does not meet installation standards given in SRM Chapter 51, then a fastener of the same specification, or an approved substitute, with a length which meets the installation standards given in SRM Chapter 51 may be used. In addition, washers may be installed for fastener grip length in accordance with SRM Chapter 51.
- (h) For the electrical bonding, refer to ESPM 20-51-20 and AMM Task 20-28-00-912-802 and/or AMM Task 20-28-00-912-805.
- (i) Apply sealant in accordance with SRM 51-24-00.
- 5 DATE: Jan 30/13 SERVICE BULLETIN No.: A340-34-5093

SERVICE BULLETIN

#### (2) Subtask 345093-839-001-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

(a) Write in the applicable aircraft records that you have done all the work given in this Service Bulletin.

#### \*\*CONF 002

#### (1) Subtask 345093-910-001-001 - Standard Practices

	Manpower Resources
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	06-20-00, Page Block 001	
	06-31-53, Page Block 001	
	Task 20-21-11-911-801	
	Task 20-28-00-912-802	
	Task 20-28-00-912-805	
Consumable Material List (CML)		
Elec. Std. Practices Manual (ESPM)	20-51-20	
Structural Repair Manual (SRM)	51-24-00	
	51-42-00	
	51-43-00	

- (a) For the specification of materials (Mat. No.) given in this Service Bulletin, refer to Consumable Materials List (CML).
- (b) For the Frame (FR) identification, refer to AMM 06-31-53, Page Block 001.
- (c) For the identification of zones, refer to AMM 06-20-00, Page Block 001.
- (d) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-801.
- (e) Remove and install fasteners in accordance with SRM 51-42-00.
- (f) Obtain alternative and substitute fasteners data, in accordance with SRM 51-43-00.
- (g) If the length of any fastener specified in this Service Bulletin does not meet installation standards given in SRM Chapter 51, then a fastener of the same specification, or an approved substitute, with a length which meets the installation standards given in SRM Chapter 51 may be used. In addition, washers may be installed for fastener grip length in accordance with SRM Chapter 51.
- (h) For the electrical bonding, refer to ESPM 20-51-20 and AMM Task 20-28-00-912-802 and/or AMM Task 20-28-00-912-805.
- (i) Apply sealant in accordance with SRM 51-24-00.
- 5 DATE: Jan 30/13 SERVICE BULLETIN No.: A340-34-5093

SERVICE BULLETIN

#### (2) Subtask 345093-839-001-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

(a) Write in the applicable aircraft records that you have done all the work given in this Service Bulletin.

#### \*\*CONF ALL

#### B. PREPARATION

#### \*\*CONF 001

#### (1) Subtask 345093-941-001-001 - Job Set-up

	Manpower Resources
Skills	NON SPECIFIC

References			
Aircraft Maintenance Manual (AMM)	06-41-53, Page Block 001		
	Task 12-34-24-860-802		
	Task 52-30-00-010-803		
	52-41-00, Page Block 001		

- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-860-802.
- (b) Put the access platforms in position at the Bulk cargo-compartment door 823, at avionics compartment door 811 and at zone 121 to get access to the AOA sensor FIN 3FP1 and at zone 122 to get access to the AOA sensors FINs 3FP2 and 3FP3.
- (c) Open the Bulk cargo-compartment door 823, refer to AMM Task 52-30-00-010-803.
- (d) Open the avionics compartment door 811, refer to AMM 52-41-00, Page Block 001 and AMM 06-41-53, Page Block 001.
- (e) Safety precaution
  - 1 On the panel 225VU:
    - <u>a</u> Make sure that the PROBE/WINDOW HEAT pushbutton switch is released (the ON legend is OFF).

#### \*\*CONF 002

(1) Subtask 345093-941-001-002 - Job Set-up

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

Refe	erences
	06-41-53, Page Block 001 Task 12-34-24-860-802 Task 52-30-00-010-801 52-41-00, Page Block 001

- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-860-802.
- (b) Put the access platform(s) in position at the FWD cargo-compartment door 821, at avionics compartment door 811 and at zones 121 to get access to the AOA sensor FIN 3FP1 and zone 122 to get access to the AOA sensors FINs 3FP2 and 3FP3.
- (c) Open the FWD cargo-compartment door 821, refer to AMM Task 52-30-00-010-801.
- (d) Open the avionics compartment door 811, refer to AMM 52-41-00, Page Block 001 and AMM 06-41-53, Page Block 001.
- (e) Safety precaution
  - <u>1</u> On the panel 225VU:
    - <u>a</u> Make sure that the PROBE/WINDOW HEAT pushbutton switch is released (the ON legend is OFF).

#### \*\*CONF ALL

C. PROCEDURE

#### \*\*CONF 001

(1) Subtask 345093-831-001-001 - Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.

Work Zones and Access Panels				
	Zone	Access/Work location		
	121	Access Other access Access platform		

Manpower Resources			
Manhours	1.50		
Minimum number of person	1		
Subtask elapsed time	1.50		
Skills	NON SPECIFIC		

#### Material necessary to do the job

Component COMPA01				
ITEM	NEW PART N°	QTY (UM)		SEE NOTES
2	F3411007920200	1	PLATE	

5 DATE: Jan 30/13

#### SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Comp	onent COMPA02			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
1	NAS1102-3-14	7	SCREW	

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Cons	Consumable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO	QTY PER A/C	SEE	
		CML MAT. No.		NOTES	
	Solvent General Purpose	11-026	As required		

References		
Structural Repair Manual (SRM) 51-42-00		
	51-43-00	
Fig. A-FBAAA	Sheet 01	
Modification of the Plates	Sheet 02	

<u>NOTE</u>: The screw item (3) must not be removed to keep the AOA sensor in position and to avoid removing it.

(a) Replace the conic plate by the flat plate of the AOA Sensor FIN 3FP1:

<u>NOTE</u>: Make sure that the previous plate installed on the aircraft is a conic plate. Refer to aircraft maintenance records.

In accordance with SRM 51-42-00 and SRM 51-43-00

<u>1</u> Use a non-metallic spatula to remove the sealant and clean the areas with:

Solvent General 11-026 As required Purpose

<u>2</u> Remove the conic plate:

Refer to Fig. A-FBAAA Sheet 01

1	Plate	F3411060200000	Item (2)	Discard
	or			
1	Plate	F3411060900000	Item (2)	Discard
	attached with:			
7	Screw		Item (1)	Discard

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

<u>3</u> Use a non-metallic spatula to remove the sealant and clean the areas with:

Solvent General 11-026 As required Purpose

<u>4</u> Install the flat plate:

<u>CAUTION</u>: NEW AOA FLAT PLATE SHALL NOT BE PAINTED AND SHALL REMAIN AS DELIVERED.

<u>NOTE</u>: The attaching holes of the flat plates are delivered stripped from protection at level of the surface of the bonding areas.

Refer to Fig. A-FBAAA Sheet 02

1 Plate F3411007920200 Item 2

attached with:

- 7 Screw NAS1102-3-14 Item 1
- (2) Subtask 345093-831-002-001 Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.

	Work Zones and Access Panels					
		Zone	Access/Work location			
ĺ		122	Access	Other access Access platform		

Manpower Resources					
Manhours	3.00				
Minimum number of person	1				
Subtask elapsed time	3.00				
Skills	NON SPECIFIC				

Material necessary to do the job

Comp	onent COMPA01			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
2	F3411007920300	2	PLATE	

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Component COMPA02						
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
1	NAS1102-3-14	14	SCREW			

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 19

### SERVICE BULLETIN

ITEM	DES	SCRIF	PTION		RENCE TO MAT. No.	QTY PER A		EE IOTES
	Solv	vent C	eneral Purpos			As required		
Struc	tural	Rena	ir Manual (SRI		erences 51-42-00			
01100	uru	пори		<i>'</i>	51-43-00			
Fig. A Modif			the Plates		<u>Sheet 01</u> Sheet 02			
	<u>NO</u>	<u>TE</u> :			must not be d removing th		keep th	e AOA senso
	(a)	Rep 3FP	lace the conic 3:	c plates by t	the flat plates	s of the AOA	A Sensor	rs FINs 3FP2
		<u>NO</u>			t the previous aircraft mainte	•		aircraft is a
		In a	ccordance with	າ SRM 51-42	2-00 and SRM	1 51-43-00		
		<u>1</u>	Use a non-m	etallic spatul	a to remove t	he sealant an	nd clean	the areas wit
		Solve Purp	ent General ose	11-026	As	s required		
		<u>2</u>	Remove the	conic plates:				
			Refer to Fig.	A-FBAAA St	<u>neet 01</u>			
2		Plat	е	F341	1060200000	Item (2)	Disca	ırd
			or					
2		Plat	е	F341 <sup>-</sup>	1060900000	Item (2)	Disca	ırd
			attached with	:				
14		Srev	N			Item (1)	Disca	ırd
		<u>3</u>	Use a non-m	etallic spatul	a to remove t	he sealant ar	nd clean	the areas wit
		Solve Purp	ent General ose	11-026	As	s required		
		<u>4</u>	Install the flat	plates:				
			CAUTION:		DA FLAT PLA REMAIN AS D		. NOT E	E PAINTED
			NOTE:		hing holes o ection at level			

REVISION No.: 00 - Jan 30/13

5

#### SERVICE BULLETIN

#### Refer to Fig. A-FBAAA Sheet 02

2 Plate F3411007920300 Item 2

attached with:

- 14 Screw NAS1102-3-14 Item 1
- (3) Subtask 345093-831-003-001 Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7500NW).

Work Zones and Access Panels					
	Zone	Access/Work location			
	160	Access	Door 823		

Manpower Resources	
Manhours	0.50
Minimum number of person	1
Subtask elapsed time	0.50
Skills	NON SPECIFIC

Material necessary to do the job

Со	omponent COMPA01						
ITE	EM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
		98F10001000000	3	AOAPRTCT			

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

References					
Fig. A-FBBAA	Sheet 01				
Modification of AOA Protection Covers in the Flight Kit No 2					

<u>NOTE</u>: Depending on airline internal policy the Flight Kit No 2 may not be located in the place defined by Fig. A-FBBAA Sheet 01. Refer to airline internal policy for exact location for Flight Kit No 2 and/or its contents.

(a) Remove in the Flight Kit No 2 (FIN 7500NW):

Refer to Fig. A-FBBAA Sheet 01:

#### FIN 7955ME

1	AOA Sensor Protection	98D34203003000	Discard
	Cover		

FIN 7956ME

1

5

- AOA Sensor Protection 98D34203003000 Discard Cover
- DATE: Jan 30/13 SERV

SERVICE BULLETIN No.: A340-34-5093



#### FIN 7957ME

- 1 AOA Sensor Protection 98D34203003000 Cover
  - (b) Install in the Flight Kit No 2 (FIN 7500NW):

Fig. A-FBBAA Sheet 01:

#### FIN 7955ME

1 AOA Sensor Protection 98F10001000000 Cover

#### FIN 7956ME

1 AOA Sensor Protection 98F10001000000 Cover

#### FIN 7957ME

1 AOA Sensor Protection 98F10001000000 Cover

#### \*\*CONF 002

(1) Subtask 345093-831-001-001 - Replace the Conic Plate of the AOA Sensor FIN 3FP1, on the LH Side.

Work Zones and Access Panels						
Zone	Access/Work location					
121	Access	Other access Access platform				

Manpower Resources	
Manhours	1.50
Minimum number of person	1
Subtask elapsed time	1.50
Skills	NON SPECIFIC

Material necessary to do the job

Comp	Component COMPA01				
ITEM	NEW PART N°	QTY (UM)		SEE NOTES	
2	F3411007920200	1	PLATE		

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Comp	onent COMPA02			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
1	NAS1102-3-14	7	SCREW	

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

Discard

#### SERVICE BULLETIN

NOTE:

The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Cons	umable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES			
	Solvent General Purpose	11-026	As required				

Re	eferences
Structural Repair Manual (SRM)	51-42-00
	51-43-00
Fig. A-FBAAA	Sheet 01
Modification of the Plates	Sheet 02

<u>NOTE</u>: The screw item (3) must not be removed to keep the AOA sensor in position and to avoid removing it.

(a) Replace the conic plate by the flat plate of the AOA Sensor FIN 3FP1:

<u>NOTE</u>: Make sure that the previous plate installed on the aircraft is a conic plate. Refer to aircraft maintenance records.

In accordance with SRM 51-42-00 and SRM 51-43-00

<u>1</u> Use a non-metallic spatula to remove the sealant and clean the areas with:

Solvent General 11-026 As required Purpose

2 Remove the conic plate:

Refer to Fig. A-FBAAA Sheet 01

1 Plate F3411060200000 Item (2) Discard

Plate F3411060900000 Item (2) Discard

attached with:

7 Screw Item (1) Discard

<u>3</u> Use a non-metallic spatula to remove the sealant and clean the areas with:

Solvent General 11-026 As required

Purpose

or

4 Install the flat plate:

<u>CAUTION</u>: NEW AOA FLAT PLATE SHALL NOT BE PAINTED AND SHALL REMAIN AS DELIVERED.

5 DATE: Jan 30/13

1

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

<u>NOTE</u>: The attaching holes of the flat plates are delivered stripped from protection at level of the surface of the bonding areas.

Refer to Fig. A-FBAAA Sheet 02

1 Plate F3411007920200 Item 2

attached with:

7 Screw NAS1102-3-14 Item 1

# (2) Subtask 345093-831-002-001 - Replace the Conic Plates of the AOA Sensors FINs 3FP2 and 3FP3, on the RH Side.

Work Zones and Access Panels				
	Zone	Access/Work location		
	122	Access	Other access Access platform	

Manpower Resources					
Manhours	3.00				
Minimum number of person	1				
Subtask elapsed time	3.00				
Skills	NON SPECIFIC				

Material necessary to do the job

Comp	Component COMPA01					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
2	F3411007920300	2	PLATE			

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Comp	onent COMPA02			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
1	NAS1102-3-14	14	SCREW	

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

Consu	sumable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO	QTY PER A/C	SEE			
		CML MAT. No.		NOTES			
	Solvent General Purpose	11-026	As required				

	References	
Structural Repair Manual (SRM)	51-42-00	
	51-43-00	

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



			Referenc	es		
g. A-FBA		the Plates	Shee			
			I	<u>et 02</u>		
<u>NO</u>	<u>TE</u> :		ew item (3) mus and to avoid ren			keep the AOA set
(a)	Rep 3FF		plates by the f	lat plates	of the AOA	Sensors FINs 3F
	<u>NO</u>		ke sure that the e. Refer to aircr			d on the aircraft is Is.
	In a	ccordance with	SRM 51-42-00	and SRM	51-43-00	
	<u>1</u>	Use a non-me	tallic spatula to	remove th	ie sealant an	d clean the areas v
	Solv Purp	ent General ose	11-026	As	required	
	<u>2</u>	Remove the c	onic plates:			
		Refer to Fig. A	A-FBAAA Sheet	<u>01</u>		
	Plat	e	F3411060	200000	Item (2)	Discard
		or				
	Plat	e	F3411060	900000	Item (2)	Discard
		attached with:				
	Sre	w			Item (1)	Discard
	<u>3</u>	Use a non-me	tallic spatula to	remove th	ie sealant an	d clean the areas v
	Solvo Purp	ent General ose	11-026	As	required	
	<u>4</u>	Install the flat	plates:			
		CAUTION:	NEW AOA F SHALL REM/			NOT BE PAINTE
		NOTE:	-		•	tes are delivered e of the bonding ar
		Refer to Fig. A	-FBAAA Sheet	<u>02</u>		
	Plat	e	F3411007	920300	Item 2	
		attached with:				
	Scr	ew	NAS1102-	-3-14	Item 1	
E: Jan (	30/13			SER	VICE BULLE	TIN No.: A340-34-

5



(3) Subtask 345093-831-003-002 - Replace the AOA Protection Covers in the Flight Kit No 2 (FIN 7503NW).

Work Zones and Access Panels			
	Zone	Access/Work location	
	130	Access	Door 821

Manpower Resources		
Manhours	0.50	
Minimum number of person	1	
Subtask elapsed time	0.50	
Skills	NON SPECIFIC	

Material necessary to do the job

Comp	onent COMPA01			
ITEM	NEW PART N°	QTY (UM)		SEE NOTES
	98F10001000000	3	AOAPRTCT	

<u>NOTE</u>: The above list of components is not an AIRBUS Kit, the required parts shall be ordered as necessary through the given channel.

References		
Fig. A-FBBAB	Sheet 01	
Modification of AOA Protection Covers in the Flight Kit No 2		

<u>NOTE</u>: Depending on airline internal policy the Flight Kit No 2 may not be located in the place defined by <u>Fig. A-FBBAB Sheet 01</u>. Refer to airline internal policy for exact location for Flight Kit No 2 and/or its contents.

(a) Remove in the Flight Kit No 2 (FIN 7503NW):

Refer to Fig. A-FBBAB Sheet 01:

#### FIN 7955ME

1 AOA Sensor Protection 98D34203003000 Discard Cover

FIN 7956ME

1 AOA Sensor Protection 98D34203003000 Cover

#### FIN 7957ME

- 1 AOA Sensor Protection 98D34203003000 Discard Cover
  - (b) Install in the Flight Kit No 2 (FIN 7503NW):

Refer to Fig. A-FBBAB Sheet 01

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

Discard

#### SERVICE BULLETIN

#### FIN 7955ME

1 AOA Sensor Protection 98F10001000000 Cover

#### FIN 7956ME

1 AOA Sensor Protection 98F10001000000 Cover

### FIN 7957ME

AOA Sensor Protection 98F10001000000 Cover

#### \*\*CONF ALL

D. <u>TEST</u>

#### \*\*CONF 001

#### (1) Subtask 345093-700-001-001 - Testing

Manpower Resources		
Skills	NON SPECIFIC	
References		
Aircraft Maintenance Manual (AMM) Task 20-28-00-720-805		
Task 20-28-00-869-801		

- (a) Test of electrical bonding at level of the 7 screws item 1:
  - <u>1</u> Do a check of the electrical bonding, refer to AMM Task 20-28-00-720-805.
- <u>NOTE</u>: For the Maximum Permitted Resistance Values, refer to AMM Task 20-28-00-869-801.
- (b) Make sure that the bonding contact resistance between the sensor and the fuselage structure is not higher than 5 milliohms as per AMM Task 20-28-00-720-805.

#### \*\*CONF 002

#### (1) Subtask 345093-700-001-001 - Testing

Manpower Resources		
Skills	NON SPECIFIC	

References		
Aircraft Maintenance Manual (AMM)	Task 20-28-00-720-805	
	Task 20-28-00-869-801	

- (a) Test of electrical bonding at level of the 7 screws item 1:
  - <u>1</u> Do a check of the electrical bonding, refer to AMM Task 20-28-00-720-805.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN

- <u>NOTE:</u> For the Maximum Permitted Resistance Values, refer to AMM Task 20-28-00-869-801.
- (b) Make sure that the bonding contact resistance between the sensor and the fuselage structure is not higher than 5 milliohms as per AMM Task 20-28-00-720-805.

#### \*\*CONF ALL

#### E. CLOSE-UP

#### \*\*CONF 001

(1) Subtask 345093-942-001-001 - Close-up

Manpower Resources	
Skills	NON SPECIFIC

Material necessary to do the job

Consi	umable CMLA01			
ITEM DESCRIPTION		REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Release Agent	05-013	As required	
	Corrosion Inhibiting fillet Consistency	09-016	As required	
	Fuel Tank Sealant Quick Repair Permanent	09-058	As required	

References		
Aircraft Maintenance Manual (AMM)	06-41-53, Page Block 001 Task 20-28-00-912-802 Task 20-28-00-912-804 Task 52-30-00-410-803 52-41-00, Page Block 001	
Elec. Std. Practices Manual (ESPM)	20-51-20	
Structural Repair Manual (SRM)	51-24-00	
Fig. A-FBAAA Modification of the Plates	Sheet 01 Sheet 02	

- (a) Protect the screws Item 1 in accordance with ESPM 20-51-20 and AMM Task 20-28-00-912-802 and/or AMM Task 20-28-00-912-804.
- (b) Blank off the hole located in front of the screw item (3) in accordance with SRM 51-24-00 and as shown on Fig. A-FBAAA Sheet 02 with:

Release Agent	05-013	As required
Corrosion Inhibiting fillet Consistency	09-016	As required

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 28



or

Fuel Tank Sealant 09-058 Quick Repair Permanent

As required

- (c) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (d) Close the Bulk cargo-compartment door 823, refer to AMM Task 52-30-00-410-803.
- (e) Close the avionics compartment door 811, refer to AMM 06-41-53, Page Block 001 and AMM 52-41-00, Page Block 001.
- (f) Remove the access platform(s).
- (g) Restore the systems and the aircraft to normal operating condition.

#### \*\*CONF 002

#### (1) Subtask 345093-942-001-002 - Close-up

Manpower Resources	
Skills	NON SPECIFIC

Material necessary to do the job

Consumable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Release Agent	05-013	As required	
	Corrosion Inhibiting fillet Consistency	09-016	As required	
	Fuel Tank Sealant Quick Repair Permanent	09-058	As required	

References					
Aircraft Maintenance Manual (AMM)	06-41-53, Page Block 001 Task 20-28-00-912-802 Task 20-28-00-912-804 Task 52-30-00-410-801 52-41-00, Page Block 001				
Elec. Std. Practices Manual (ESPM)	20-51-20				
Structural Repair Manual (SRM)	51-24-00				
Fig. A-FBAAA Modification of the Plates	Sheet 01 Sheet 02				

(a) Protect the screws Item 1 in accordance with ESPM 20-51-20 and AMM Task 20-28-00-912-802 and/or AMM Task 20-28-00-912-804.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

#### SERVICE BULLETIN


(b) Blank off the hole located in front of the screw item (3) in accordance with SRM 51-24-00 and as shown on Fig. A-FBAAA Sheet 02 with:

Relea	se Agent	05-013	As required
	sion Inhibiting Consistency	09-016	As required
or			
	Tank Sealant Repair anent	09-058	As required


- (c) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (d) Close the FWD cargo-compartment door 821, refer to AMM Task 52-30-00-410-801.
- (e) Close the avionics compartment door 811, refer to AMM 06-41-53, Page Block 001 and AMM 52-41-00, Page Block 001.
- (f) Remove the access platform(s).
- (g) Restore the systems and the aircraft to normal operating condition.



\*\*CONF ALL



BEFORE



#### NOTE:

TYPICAL ILLUSTRATION ASSOCIATED WITH THALES OR GOODRICH AOA SENSORS.

F\_SB\_345093\_5\_BAAA\_01\_01

Figure A-FBAAA - Sheet 01 Modification of the Plates

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13


Page: 31

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.



\*\*CONF ALL

### **AFTER**



В

#### NOTE:

ONLY ONE CONFIGURATION SHOWN, AOA SENSOR DEPENDS ON AIRCRAFT CONFIGURATION.

01 BLANK OFF THE HOLE LOCATED IN FRONT OF THE SCREW ITEM (3) WITH: MAT. No. 05–013 AND MAT. No. 09–058 OR 09–016.



F\_SB\_345093\_5\_BAAA\_02\_03

Figure A-FBAAA - Sheet 02 Modification of the Plates

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093


REVISION No.: 00 - Jan 30/13

Page: 32

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

SERVICE BULLETIN

\*\*CONF 001



AOA PROTECTION COVERS FINs (7955ME, 7956ME AND 7957ME) ARE STORED IN FLIGHT KIT No 2 FIN (7500NW)

F\_SB\_345093\_5\_BBAA\_01\_02

Figure A-FBBAA - Sheet 01 Modification of AOA Protection Covers in the Flight Kit No 2

5 DATE: Jan 30/13


SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 33

SERVICE BULLETIN

\*\*CONF 002



AOA PROTECTION COVERS FINs (7955ME, 7956ME AND 7957ME) ARE STORED IN FLIGHT KIT No 2 FIN (7503NW)

F\_SB\_345093\_5\_BBAB\_01\_02

Figure A-FBBAB - Sheet 01 Modification of AOA Protection Covers in the Flight Kit No 2

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 34



SERVICE BULLETIN APPENDIX 01: Elapsed Time Assumption

#### \*\*CONF ALL

(1) The following Gantt chart is only a proposal operators may determine that another way to do the work is more suitable for them.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

SERVICE BULLETIN APPENDIX 01: Elapsed Time Assumption

\*\*CONF ALL

### ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A340-34-5093



STEPS	МН	PER	ET/S			
GET ACCESS	0.50	1	0.50			
REPLACEMENT OF THE PLATE OF THE AOA SENSOR FIN 3FP1, RH SIDE	1.50	1	1.50			
REPLACEMENT OF THE PLATE OF THE AOA SENSOR FINS 3FP2 AND 3FP3, LH SIDE	3.00	1	3.00			
REPLACEMENT OF AOA PROTECTION COVERS IN THE FLIGHT KIT No 2	0.50	1	0.50			
TEST	0.25	1	0.25			
CLOSE-UP	0.50	1	0.50			
0     1     2     3     4     5       0     1     2     3     4     5       SB ELAPSED TIME     SB ELAPSED TIME     (HOURS)       SB ELAPSED TIME     4.25						
MH : MANHOURS PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP MH : MANHOURS PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP MOTE: IT THIS CHART IS ONLY A PROPOSAL. OPERATORS MAY DETERMINE THAT ANOTHER WAY TO DO THE WORK IS MORE SUITABLE FOR THEM. IS OPERATORS MAY DETERMINE THAT ANOTHER WAY TO DO THE WORK IS MORE SUITABLE FOR THEM. IS OPERATORS MAY DETERMINE THAT ANOTHER WAY TO DO THE WORK IS MORE SUITABLE FOR THEM. IS OPERATORS MAY DETERMINE THAT ANOTHER WAY TO DO THE WORK IS MORE SUITABLE FOR THEM. IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART. F_SB_345093_5_AAAA_01_01 Figure A-FAAAA - Sheet 01 Gantt Chart						

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093

REVISION No.: 00 - Jan 30/13

Page: 2

#### SERVICE BULLETIN REPORTING SHEET

### TITLE: NAVIGATION - GENERAL - REPLACE AOA PROBE CONIC PLATE BY AOA PROBE FLAT PLATE

#### MODIFICATION No.: 203295S32646

Please complete the appropriate item (A or B):

A - SB WILL BE embodied

YES/NO (if NO please comment)

If YES, aircraft concerned (as per SB effectivity by default) and planned dates (month/year) of embodiment:

B - SB HAS BEEN embodied on aircraft:

Operator comments:

From Airline: Name/Title: Signature:

Date:

If operational documentation is affected (see Paragraph 1.K of this SB): If information is needed prior to next normal revision or prior to SB embodiment, please indicate required service(s): Either: Modification Operational Impact (MOI), if available YES/NO Or : Intermediate revision YES/NO

Important Information: This SB will only be incorporated in your maintenance and operational documentation if this sheet is returned to Airbus and signed by a duly authorised representative. With the next feasible revision, this will result in

- Updating of maintenance documentation to show pre and post SB data.
- Updating of maintenance and operational documentation to show post SB data after embodiment.

If this SB requires previous or simultaneous accomplishment of other SBs, Airbus shall automatically include them in the manual revisions. Refer to SIL 00-037 for detailed information.

Please return this completed sheet to:

AIRBUS CUSTOMER SERVICES DIRECTORATE 1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX FRANCE

Attn: SDC32 Technical Data and Documentation Services FAX: (+33) 5 61 93 28 06 e-mail: sb.reporting@airbus.com or via your Resident Customer Support Office.

Alternatively, SB lists via letters or fax are also accepted.

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093



#### SERVICE BULLETIN QUALITY PERCEPTION FORM

Use this form to tell us what is your perception of the quality of this Service Bulletin. The reported data that you provide us will be used to analyse areas of difficulties and to take corrective action to further improve the quality of our Service Bulletins.

We thank you for the time you have taken in completing this form.

(Please rate on a scale of 1 to 4, with 4 being the highest score)

- Quality rating of this SB	4	3	2	1
- Quality rating of the Accomplishment Instructions	4	3	2	1
- Quality rating of the Illustrations	4	3	2	1
- Is this SB easy to understand ?	Y / N			

If you have had difficulties in the accomplishment of this SB please quote below the area(s) and give a short description of the issue.

	Planning		Material		Instructions
Х	Effectivity	Х	Kit content	Х	Preparation
Х	Reason	Х	List of Materials Operator Supplied	Х	Mod/Inspection
Х	Manpower	Х	Industry support	Х	Test
Х	References	Х	Re-identification	Х	Close-Up
Х	Publication	Х	Tooling	Х	Illustrations

Comments:

Operator:

Name/Title:

Please return this form to:

AIRBUS CUSTOMER SERVICES DIRECTORATE 1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX FRANCE

Attn : SEM4 Service Bulletins Management FAX : (33) 5 61 93 42 51

Or via your Resident Customer Support Office.

Date:

5 DATE: Jan 30/13

SERVICE BULLETIN No.: A340-34-5093