

EASA Safety Information Notice

No.: 2008-11

Issued: 21 February 2008

Subject: Rescue Hoist P/N BL-10300-60 and P/N 412-8800-01-315 – Inspection of

Hook P/N S6150-61090-1 and P/N 412-8800-05-101

Ref. Publication: ENAC Italy Emergency Airworthiness Directive 2008-62 dated 19

February 2008.

Introduction: ENAC Italy, representing the State of Design of the affected products,

issued the referenced Emergency AD (attached as page 2 of this notice) following the discovery of a hook P/N 412-8800-05-101 without the pin P/N BL-1358. The investigation showed that the pin is missing due to a

manufacturing non-conformity.

According to Article 15(1) of Regulation (EC) No 1592/2002 of the European Parliament and of the Council of 15 July 2002 on common rules in the field of civil aviation and establishing a European Aviation Safety Agency, EASA has only taken over Member States obligations that

are related to design approval. As a consequence, EASA is only authorised to issue ADs related to design approval. EASA has

determined that the above referenced unsafe condition is not related to design approval, as it is the result of manufacturing non-conformity and that the type design is therefore not affected. However, this is a serious safety issue and this Safety Information has been issued accordingly. National Aviation Authorities of the EU member states may adopt the

referenced AD under their State of Registry responsibility.

Applicability: All Agusta AB412 and AB412EP helicopters having installed (and/or

stored as spare parts) the rescue hoist P/N BL 10300-60 or

P/N 412-8800-01-315 equipped respectively with hook P/N S6150-

61090-1 or P/N 412-8800-05-101.

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety

Management and Research Section, Certification Directorate, EASA.

E-mail: ADs@easa.europa.eu .

EMERGENCY AIRWORTHINESS DIRECTIVE



AD N°: 2008-62

Issued: 19th February 2008

The Certificate of Airworthiness of the aircraft to which structures and/or systems this Airworthiness Directive shall be applied expires if this AD is not embodied within specified terms.

Type Approval Holder's Name: Agusta S.p.A. Type/Model: AB412 (series) and AB412EP Foreign AD: N.A. Supersedure AD: N.A. Subject: rescue hoist P/N BL-10300-60 and P/N 412-8800-01-315 - inspection of hook P/N S6150-61090-1 and P/N 412-8800-05-101 Agusta S.p.A. Manufacturer: All Agusta AB412 and AB412EP helicopters having installed (and/or stored as spare parts) the rescue hoist P/N BL 10300-60 or Applicability: P/N 412-8800-01-315 equipped respectively with hook P/N S6150-61090-1 or P/N 412-8800-05-101 It has been reported a case of an hook P/N 412-8800-05-101 without the pin P/N BL-1358. The lack of this pin may cause the unthreaded of the nut with the consequently lose of this and its Reason: load. For this reason, this urgent AD requires a visual inspection of the hook. 20.02.2008 **Effective Date:** Required as indicated: Before the next flight of the helicopter with the rescue hoist installed or before the installation on the helicopter of the rescue hoists and/or for the hooks stored as spare parts, after the effective date Compliance: of this AD inspect the hook of the rescue hoist in accordance with the instructions of the Agusta Alert BT 412-124. However the inspection of spare parts must be done not later then 31.March.2008. Ref. Publications: Alert BT Agusta 412-124 1.If requested and appropriately substantiated, ENAC can accept Alternative Methods of Compliance for this AD. 2. This AD is issued by ENAC because concerns aspect of production only. 3. Enquiries regarding this AD should be referred to the following email address ad@enac.rupa.it Remarks: 4 For any questions concerning the technical content of the requirements in this AD, please contact: Agusta S.p.a. Customer Support - Via per Tornavento, 15 21019 Somma Lombardo (VA) -Italy; Phone + 39 0331 711453; Fax: +39 0331 711254; E-mail: absereng@agustawestland.com