	AIRWORTHINESS DIRECTIVE	Distribution:	Issue date:	Page:
	No F-2003-426	В	December 10, 2003	1/2
Direction générale de l'aviation civile France	This Airworthiness Directive is published by the DGAC: X on behalf of EASA, the Primary Airworthiness Authority for the affected product as the Registration Airworthiness Authority for the affected aircraft		Translation of "consigne de navigabilité" of same number. In case of difficulty, reference should be made to the French text.	
GSAC publication	No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.			
Corresponding foreign Airworthiness Directive(s): Airworthiness Directive(s):		vorthiness Directive(s) replaced:		
Not applicable		2002-435, cancelled by its revision 1		
Person in charge of airworthiness:		Type(s):		
AIRBUS	A34	A340-200/-300 aircraft		
Type certific	ate(s) No. 183			
TCDS No. 183				
ATA chapter(s	Subject: Wings - Outboard flap - Insper	ection and n	nodification of sensor stru	t at

1. **EFFECTIVITY**:

AIRBUS A340 aircraft, models -211, -212, -213, -311, -312 and -313, all serial numbers, except those on which AIRBUS modification 48579 has been embodied in production or on which AIRBUS Service Bulletin (SB) A340-27-4098 has been embodied in service.

2. REASONS:

Several sensor strut corrosion cases with the attachment bolt sheared have been reported.

The corrosion of the sensor strut is due to the wear of the protective surface.

The shearing of the attachment bolt is caused by a fatigue rupture subsequent to an increase of the axial loads. The increase of these axial loads is caused by the corrosion.

This situation could lead to total loss of the sensor strut function resulting in the inability to detect disconnection at tracks 4 and 5 which, in the worst case, could lead to the separation of the outboard flap.

Therefore, a repetitive inspection of the sensor strut to detect any corrosion and deformation has been rendered mandatory by Airworthiness Directive (AD) 2002-435.

This AD repeats the requirements above and requires modification of the sensor strut affected within the deadlines given below.

3. MANDATORY ACTIONS AND COMPLIANCE TIMES:

The following measures are rendered mandatory from August 31, 2002 [effective date of AD 2002-435]:



AIRWORTHINESS DIRECTIVE No F-2003-426

Distribution:

В

Issue date:

December 10, 2003

Page: **2/2**

3.1. Inspection

3.1.1. Unless already accomplished,

Prior to the accumulation of 18 months in service of the aircraft or within 2800 flight hours, whichever occurs later,

inspect the sensor strut to detect any corrosion and deformation and, if necessary, apply the corrective measures as shown on flow-chart figure 1 sheet 1 of AIRBUS SB A340-27-4097.

3.1.2. Repeat this inspection at intervals not exceeding 18 months.

3.2. Modification

Unless already accomplished,

At latest on June 30, 2006 replace the affected sensor struts by sensor struts PN F5757492600000 in accordance with instructions given in AIRBUS SB A340-27-4098.

- **Note 1:** Accomplishment of paragraph 3.2. of this AD makes the repetitive inspection requirements given in paragraph 3.1 of this AD null and void.
- Note 2: Removed sensor struts must be discarded.

4. REFERENCE PUBLICATIONS:

AIRBUS Service Bulletin A340-27-4097 AIRBUS Service Bulletin A340-27-4098 (Any later approved revision of these SBs are acceptable).

5 **EFFECTIVE DATE**:

December 20, 2003.

6. REMARK:

For questions concerning the technical contents of this AD's requirements, contact:

AIRBUS - Gérard MEUREY - Fax : 33 5 61 93 45 80.

7. APPROVAL:

This AD is approved under EASA reference No 1432 dated December 02, 2003.