


EASA	AIRWORTHINESS DIRECTIVE																								
	<p>AD No.: 2006-0140R1</p> <p>Date: 21 August 2008</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>																								
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008 Article 14(4) exemption].</p>																									
<p>Type Approval Holder's Name :</p> <p>Lufthansa Technik AG; SR Technics; Jet Aviation Basel, AG; CTT Systems AB</p>	<p>Type/Model designation(s) :</p> <p>CTT Systems AB Zonal Drying System, Part Numbers (P/Ns) listed in the Applicability of this directive.</p>																								
<p>TCDs Number :</p>	<p>A number of Supplemental Type Certificates (STCs) have been identified that are affected by the requirements of this AD. For clarity, they are listed in the Applicability paragraph (Table 1) of this directive.</p>																								
<p>Foreign AD :</p>	<p>None</p>																								
<p>Revision :</p>	<p>This AD revises and replaces EASA AD 2006-0140-E dated 24 May 2006</p>																								
ATA 21	Air Conditioning - Zonal Drying System Deactivation																								
<p>Manufacturer :</p>	<p>CTT Systems AB</p>																								
<p>Applicability:</p>	<p>CTT Systems AB Zonal Drying System P/N 1000-001, 2000-000, 2000-005, 2001-001, 2001-006, 3000-000 Rev.A, 3000-001, 3000-002 Rev.A and 3000-002 Rev.B are to be installed in, but not limited to, Airbus A330-243 and A330-322 being 737-700, 737-800, 747-400, and 767-300 series; Bombardier CL-600-2B19; and McDonnell Douglas MD-11 series aeroplanes.</p> <p>The following STCs have been identified to be affected by the requirements of this AD:</p>																								
<p style="text-align: center;">Table 1</p> <table border="1"> <thead> <tr> <th>STC Number</th><th>Issued by</th><th>Holder</th><th>Applicable to</th></tr> </thead> <tbody> <tr> <td>TA0259</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Airbus A330-322 (s/n 120)</td></tr> <tr> <td>LBA.21E2.TA0270</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Bombardier CL-600-2B19</td></tr> <tr> <td>LBA.21E2.TA0307</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Boeing 737-700</td></tr> <tr> <td>LBA.21E2.TA0609</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Airbus A330-243</td></tr> <tr> <td>LBA.21E2.TA0636*</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Boeing 737-800</td></tr> </tbody> </table>		STC Number	Issued by	Holder	Applicable to	TA0259	LBA	Lufthansa Technik AG	Airbus A330-322 (s/n 120)	LBA.21E2.TA0270	LBA	Lufthansa Technik AG	Bombardier CL-600-2B19	LBA.21E2.TA0307	LBA	Lufthansa Technik AG	Boeing 737-700	LBA.21E2.TA0609	LBA	Lufthansa Technik AG	Airbus A330-243	LBA.21E2.TA0636*	LBA	Lufthansa Technik AG	Boeing 737-800
STC Number	Issued by	Holder	Applicable to																						
TA0259	LBA	Lufthansa Technik AG	Airbus A330-322 (s/n 120)																						
LBA.21E2.TA0270	LBA	Lufthansa Technik AG	Bombardier CL-600-2B19																						
LBA.21E2.TA0307	LBA	Lufthansa Technik AG	Boeing 737-700																						
LBA.21E2.TA0609	LBA	Lufthansa Technik AG	Airbus A330-243																						
LBA.21E2.TA0636*	LBA	Lufthansa Technik AG	Boeing 737-800																						

	<table border="1"> <tr> <td>TA0733</td><td>LBA</td><td>Lufthansa Technik AG</td><td>Boeing 747-400</td></tr> <tr> <td>SA 0003 NL</td><td>RLD</td><td>CTT Systems AB</td><td>McDonnell Douglas MD-11</td></tr> <tr> <td>SA 0009 NL **</td><td>RLD</td><td>CTT Systems AB</td><td>Boeing 767-300</td></tr> <tr> <td>EASA.A.S.02547</td><td>EASA</td><td>CTT Systems AB</td><td>Boeing 767-300</td></tr> <tr> <td>Z 21-74-01</td><td>FOCA</td><td>SR Technics, TEC</td><td>McDonnell Douglas MD-11</td></tr> <tr> <td>Z 25-02-77</td><td>FOCA</td><td>Jet Aviation Basel, AG</td><td>Boeing 737-700 (s/n 32627)</td></tr> </table> <p>* LBA.21E2.TA0636 was approved by EASA under Approval Number 2006-014416.</p> <p>** RLD STC SA 0009 NL has been superseded by EASA.A.S.02547 on March 1, 2006.</p> <p>Note: The approval list for the installation of the affected Zonal Drying System in Table 1 may be not exhaustive. In case the relevant aircraft are not listed therein, this does not exempt an aircraft having an affected Zonal Drying System P/N installed from compliance with this directive.</p>	TA0733	LBA	Lufthansa Technik AG	Boeing 747-400	SA 0003 NL	RLD	CTT Systems AB	McDonnell Douglas MD-11	SA 0009 NL **	RLD	CTT Systems AB	Boeing 767-300	EASA.A.S.02547	EASA	CTT Systems AB	Boeing 767-300	Z 21-74-01	FOCA	SR Technics, TEC	McDonnell Douglas MD-11	Z 25-02-77	FOCA	Jet Aviation Basel, AG	Boeing 737-700 (s/n 32627)
TA0733	LBA	Lufthansa Technik AG	Boeing 747-400																						
SA 0003 NL	RLD	CTT Systems AB	McDonnell Douglas MD-11																						
SA 0009 NL **	RLD	CTT Systems AB	Boeing 767-300																						
EASA.A.S.02547	EASA	CTT Systems AB	Boeing 767-300																						
Z 21-74-01	FOCA	SR Technics, TEC	McDonnell Douglas MD-11																						
Z 25-02-77	FOCA	Jet Aviation Basel, AG	Boeing 737-700 (s/n 32627)																						
Reason:	<p>One incident had been reported where the leakage on air ducting downstream of a Zonal Drying System P/N 3000-002 installed on a Boeing 747-400 aircraft, showed signs of premature metal failure. As the root cause for the failure was initially not known, all other Zonal Drying Systems of similar design could have been affected by the same unsafe condition. Therefore, EASA AD 2006-0140-E mandated their de-activation.</p> <p>Investigation showed that such failure was caused by combustion of contaminants in the dryer unit.</p> <p>This Revision 1 addressed the development of a new dryer unit which removes this combustion risk.</p> <p>The installation of the new dryer unit is now approved through the EASA STCs listed in Table 2 of the Required action and Compliance Time section of this AD and once installed in a subject aircraft corrects the unsafe condition and eliminates the requirements of EASA AD 2006-0140-E. Consequently, the Zonal Drying System can be re-activated.</p>																								
Effective Date:	25 May 2006																								
Required action / Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> 1. Before next flight after the effective date of this directive, switch off the Zonal Drying System installed in accordance with one of the STCs listed in Table 1 of the Applicability section of this AD and set system inoperative by pulling and securing the affected circuit breaker in accordance with relevant maintenance instructions. 2. On aircraft where the following STCs are installed, the requirements of paragraph 1. of this AD are no longer applicable and the Zonal Drying System accordingly modified can be re-activated: <p style="text-align: center;">Table 2</p> <table border="1"> <tr> <th>STC Number</th><th>Issued by</th><th>Holder</th><th>Applicable to</th></tr> <tr> <td>EASA.A.S.03502 Revision 1</td><td>EASA</td><td>Lufthansa Technik AG</td><td>Bombardier CL-600-2B19</td></tr> <tr> <td>EASA.A.S.03504 Revision 1</td><td>EASA</td><td>Lufthansa Technik AG</td><td>Boeing 737-700</td></tr> <tr> <td>EASA.A.S.03505 Revision 1</td><td>EASA</td><td>Lufthansa Technik AG</td><td>Boeing 737-800</td></tr> </table>	STC Number	Issued by	Holder	Applicable to	EASA.A.S.03502 Revision 1	EASA	Lufthansa Technik AG	Bombardier CL-600-2B19	EASA.A.S.03504 Revision 1	EASA	Lufthansa Technik AG	Boeing 737-700	EASA.A.S.03505 Revision 1	EASA	Lufthansa Technik AG	Boeing 737-800								
STC Number	Issued by	Holder	Applicable to																						
EASA.A.S.03502 Revision 1	EASA	Lufthansa Technik AG	Bombardier CL-600-2B19																						
EASA.A.S.03504 Revision 1	EASA	Lufthansa Technik AG	Boeing 737-700																						
EASA.A.S.03505 Revision 1	EASA	Lufthansa Technik AG	Boeing 737-800																						

	EASA.A.S.03506 Revision 1	EASA	Lufthansa Technik AG	Boeing 747-400
	EASA.A.S.03507 Revision 1	EASA	Lufthansa Technik AG	Airbus A330-200
Ref. Publications:	<p>CTT Systems AB Information Letters IL06-01 dated May 5, 2006, IL06-02 issue 2 dated May 8, 2006 and IL06-03 dated May 10, 2006; and (for Lufthansa Technik STCs only) Lufthansa Technik AG Service Information Letter LHT 06-001, Revision IR dated May 12, 2006.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>			
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. The safety assessment has requested not to implement the full consultation process and an immediate publication and notification. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu 4. For any questions concerning the technical content of the requirements in this AD, please contact CTT Systems AB P.O. Box 421-611 29 Nyköping, Sweden – Ph.+46-(0)15 2205900, Fax +46-(0)15 2205925, E-mail: ctt@ctt.se or (for Lufthansa Technik STCs) Lufthansa Technik AG - Hamburg, Germany. Ph.: +49-(0) 40 40-4747, Fax: +49 (0) 40-5070-4855. E-mail: bernd.staack@lht.dlh.de 			