EASA AIRWORTHINESS DIRECTIVE AD No: 2007-0307 Date: 17 December 2007 No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry. Type/Model designation(s): Type Approval Holder's Name: BAE SYSTEMS (OPERATIONS) LTD BAe 146 and AVRO 146-RJ aircraft TCDS Number: United Kingdom BA16 Foreign AD: Not applicable Supersedure: None **ATA 53** Fuselage - Airbrake Upper Crossbeam - Inspection/Repair BAE Systems (Operations) Ltd, British Aerospace plc, British Aerospace (Commercial Aircraft) Ltd, British Aerospace (Operations) Ltd, British Aerospace Manufacturer(s): Regional Aircraft Ltd, British Aerospace Regional Aircraft trading as Avro International Aerospace. BAe 146 and AVRO 146-RJ aircraft, all Models, all serial numbers. Applicability: The airbrake upper crossbeam on an aircraft failed in-flight. The crossbeam failure caused damage to the rudder control system, resulting in loss of rudder control. Loss of rudder control will cause handling difficulties particularly during take-off, approach and landing phases in cross winds. BAE Systems (Operations) Ltd has published Inspection Service Bulletin (ISB) 53-200 that revises and supersedes the inspection requirements which are defined in the Maintenance Review Board Report (MRBR) SSI Task 53-40-125, Supplemental Structural Inspections Document (SSID) Tasks 53-40-125.1 and 53-40-125.2 (included in the Airworthiness Limitations Section of Reason: Aircraft Maintenance Manual Chapter 5 that is currently mandated as part of EASA AD 2007-0271) and in Maintenance Planning Document (MPD) Task Reference 534025-DVI-10000-1. These revised inspection requirements and reduced inspection periods are to ensure that any fatigue damage is detected before it causes upper airbrake crossbeam failure. MRBR, SSID and MPD will be amended in due course to reflect these revised inspection periods. For the reasons stated above, this Airworthiness Directive (AD) requires the inspection and, as necessary, repair of the airbrake upper crossbeam. 31 December 2007 Effective Date:

Compliance:	Required as indicated, unless accomplished previously:
	(1) From the effective date of this directive, perform the initial inspection at the threshold specified in paragraph 1.D.(1) or 1.D.(2), as applicable, and in accordance with the instructions of paragraph 2.B, 2.C and 2.D of BAE Systems (Operations) Ltd Inspection Service Bulletin (ISB) 53-200, except that the calendar inspection threshold in paragraph 1.D.(2) is defined from the effective date of the AD and not from the date of receipt of the service bulletin. The initial inspection includes the replacement of three rivets by three Hi-Lok Pins;
	(2) Thereafter, repeat the inspections at the intervals specified in paragraph 1.D.(3) and in accordance with the instructions of paragraph 2.B, 2.C and 2.D of BAE Systems (Operations) Ltd ISB 53-200;
	(3) If damage is found during any inspection, before next flight, accomplish the necessary repairs in accordance with the Structural Repair Manual. If the damage is outside allowed repair criteria, embody a BAE Systems (Operations) Ltd and/or EASA approved repair scheme.
Ref. Publications:	BAE Systems (Operations) Limited Inspection Service Bulletin ISB 53-200 Initial Issue.
	The use of later approved revisions is acceptable for compliance with the requirements of this AD.
Remarks:	If requested and appropriately substantiated, EASA can accept Alternative Methods of Compliance for this AD.
	 This AD was posted on 12 November 2007 as PAD 07-198 for consultation until 10 December 2007. The Comment response Document can be found at http://ad.easa.europa.eu/.
	 Enquiries regarding this AD should be referred to the AD Focal Point – Certification Directorate, EASA, E-mail: ADs@easa.europa.eu
	4. For any questions concerning the technical content of the requirements in this AD, please contact: Project Management Group, Customer Information Department, BAE Systems (Operations) Ltd, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Telephone: +44 1292 675207, Fax: +44 1292 675704, E-mail: RApublications@baesystems.com