


EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No : 2008-0037</p> <p>Date: 22 February 2008</p>	
<p>No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.</p>		
<p>Type Approval Holder's Name:</p> <p>BAE SYSTEMS (OPERATIONS) LTD</p>	<p>Type/Model designation(s):</p> <p>HP.137 Jetstream MK 1 aircraft; and Jetstream Series 200, 3100 and 3200 aircraft</p>	
<p>TCDS Number : United Kingdom BA4 and BA15</p>		
<p>Foreign AD : Not applicable</p>		
<p>Supersedure : None</p>		
ATA 32	Landing Gear – Nose Landing Gear (NLG) Wheel Outer Cone – Inspection	
<p>Manufacturer(s):</p>	<p>Handley Page Ltd, Scottish Aviation Ltd, British Aerospace PLC, British Aerospace (Commercial Aircraft) Ltd, British Aerospace Regional Aircraft Ltd, Jetstream Aircraft Ltd, British Aerospace (Operations) Ltd.</p>	
<p>Applicability:</p>	<p>Models HP.137 Jetstream Mk1 aircraft; and Jetstream Series 200, 3100 and 3200 aircraft, all models, all serial numbers</p>	
<p>Reason:</p>	<p>A failure mode has been identified following the examination of parts from another aircraft type (Jetstream 4100 series) that can lead to the loss of a nose-wheel. The Jetstream (HP.137) Mk1, 200, 3100 and 3200 series use a similar method for retaining the wheel assemblies on the landing gear axle and can therefore experience the same type of failure, i.e. a combination of excessive wear and/or adverse tolerances on the axle inner cone, outer cone or wheel hub splined sleeve cones resulting in the loss of the critical gap between the inner flange face of the wheel outer cone and the axle end face. If this gap is lost, it results in the wheel having free play along the length of the axle. This condition, if not corrected, can cause the wheel nut lock plate to break, leading to the wheel retention nut unscrewing and subsequent separation of the nose wheel from the landing gear axle.</p> <p>For the reasons described above, this AD requires repetitive inspections of the nose landing gear to ensure that the wheels are correctly retained and, depending on findings, replacement of worn parts.</p>	
<p>Effective Date:</p>	<p>07 March 2008</p>	

Compliance	<p>(1) Within 3 months of the effective date of this AD, inspect the left and right nose wheel attachments to the axle in accordance with paragraph 2 B of BAE Systems (Operations) Ltd Service Bulletin 32-JA070241;</p> <p>(2) If the measured gap size is less than 0.002 in (0.05 mm), before next flight, replace all worn parts;</p> <p>(3) If the measured gap size is equal to or more than 0.002 in (0.05 mm), depending on the exact finding, at intervals not to exceed the value as indicated in Table 1 of this AD (see below), repeat the inspection of the left and right nose wheel attachments to the axle in accordance with paragraph 2 B of BAE Systems (Operations) Ltd Service Bulletin 32-JA070241;</p> <table border="1" data-bbox="528 577 1420 1021"> <thead> <tr> <th colspan="2" data-bbox="528 577 1420 633">Table 1</th> </tr> <tr> <th data-bbox="528 633 978 719">Measured Gap Size</th> <th data-bbox="978 633 1420 719">Repeat Inspection Interval in Flight Hours (FH)</th> </tr> </thead> <tbody> <tr> <td data-bbox="528 719 978 801">0.002 in. to 0.005 in. (0.05/0.13mm).</td> <td data-bbox="978 719 1420 801">500 FH</td> </tr> <tr> <td data-bbox="528 801 978 884">More than 0.005 in. to 0.010 in. (0.13/0.25mm).</td> <td data-bbox="978 801 1420 884">1 000 FH</td> </tr> <tr> <td data-bbox="528 884 978 967">More than 0.010 in. to 0.020 in. (0.25/0.51mm).</td> <td data-bbox="978 884 1420 967">2 000 FH</td> </tr> <tr> <td data-bbox="528 967 978 1021">More than 0.020 in. (0.51mm).</td> <td data-bbox="978 967 1420 1021">3 000 FH</td> </tr> </tbody> </table> <p>Note 1: If, during any repeat inspection as required by paragraph (3) of this AD, the finding has changed to another value (see Table 1 above), adjust the new interval accordingly.</p> <p>(4) If, during any repeat inspection as required by paragraph (3) of this AD, the measured gap size is found to be less than 0.002 in (0.05 mm), before next flight, replace the worn parts.</p> <p>Note 2: Replacement of parts does not constitute terminating action for the inspection requirements of this AD.</p>	Table 1		Measured Gap Size	Repeat Inspection Interval in Flight Hours (FH)	0.002 in. to 0.005 in. (0.05/0.13mm).	500 FH	More than 0.005 in. to 0.010 in. (0.13/0.25mm).	1 000 FH	More than 0.010 in. to 0.020 in. (0.25/0.51mm).	2 000 FH	More than 0.020 in. (0.51mm).	3 000 FH
Table 1													
Measured Gap Size	Repeat Inspection Interval in Flight Hours (FH)												
0.002 in. to 0.005 in. (0.05/0.13mm).	500 FH												
More than 0.005 in. to 0.010 in. (0.13/0.25mm).	1 000 FH												
More than 0.010 in. to 0.020 in. (0.25/0.51mm).	2 000 FH												
More than 0.020 in. (0.51mm).	3 000 FH												
Ref. Publications:	<p>BAE SYSTEMS (Operations) Limited Service Bulletin 32-JA070241.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>												
Remarks :	<ol style="list-style-type: none"> <li data-bbox="523 1473 1326 1536">1. If requested and appropriately substantiated, EASA can accept Alternative Methods of Compliance for this AD. <li data-bbox="523 1547 1310 1641">2. This AD was posted on 16 January 2008 as PAD 08-010 for consultation until 13 February 2008. The Comment Response Document can be found at http://ad.easa.europa.eu/ . <li data-bbox="523 1653 1414 1715">3. Enquiries regarding this AD should be referred to the AD Focal Point – Certification Directorate, EASA, E-mail: ADs@easa.europa.eu <li data-bbox="523 1727 1422 1912">4. For any questions concerning the technical content of the requirements in this AD, please contact Project Management Group, Customer Information Department, BAE SYSTEMS (OPERATIONS), Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; Telephone: +44 1292 675207; Fax: +44 1292 675704; E-mail: RApublications@baesystems.com 												