


EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2008-0109 R1</p> <p>Date: 17 June 2008</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
<p>Type Approval Holder's Name : ROLLS-ROYCE PLC</p>		<p>Type/Model designation(s) : RB211 - Trent 500 engines</p>
<p>TCDS Number: EASA E.060</p>		
<p>Foreign AD : Not applicable</p>		
<p>Revision: This AD revises and replaces EASA AD 2008-0109 dated 06 June 2008.</p>		
<p> </p>		
ATA 72	Engine – Intermediate Pressure (IP) Turbine Blade Outer Shrouds – Inspection	
<p> </p>		
<p>Manufacturer(s):</p>	<p>Rolls-Royce plc</p>	
<p>Applicability:</p>	<p>RB211-Trent 500 series engines, all marks without Rolls-Royce service bulletin No. 72-D733 embodied.</p> <p>These engines are known to be installed on, but not limited to, Airbus A340-500 and Airbus A340-600 series aircraft.</p>	
<p>Reason:</p>	<p>The IP turbine blade shrouds of the RB211-Trent 500 series engines feature closure welds (dust caps). Development engine testing has revealed the potential for dust caps to crack, lift and release. The latter may potentially allow hot annulus gas to be ingested down the core passages of IP turbine blades. Radial inflow of annulus gas into the IP disc rim region could cause local heating of the disc firtree, resulting in creep of the disc material. Failure of the disc rim in creep could simultaneously release two blades and a disc post. Failure to this extent could be beyond the containment capabilities of the casing. Consequently, release of the dust caps would constitute a potentially unsafe condition.</p> <p>This Airworthiness Directive is published to require inspection of IP Turbine Blade Outer Shrouds and, depending on the results, subsequent corrective actions.</p> <p>This AD has been revised in order to allow the option of carrying out the required inspections while the engine is not installed on an aircraft.</p>	
<p>Effective Date:</p>	<p>20 June 2008</p>	

<p>Required action(s) and Compliance Time(s):</p>	<p><u>1) Borescope Inspection</u></p> <p>Before 1st July 2008, carry out the borescope inspection as specified in Section 3, Accomplishment Instructions of Rolls-Royce Non Modification Service Bulletin (NMSB) No. 72-AF994.</p> <p><u>2) Actions following Borescope Inspection (see also 1 above)</u></p> <p>Depending on the results of the inspection carried out according to paragraph 1) of this AD, carry out the following:</p> <table border="1" data-bbox="453 421 1394 1196"> <thead> <tr> <th data-bbox="453 421 852 501">Results of Borescope Inspection</th> <th data-bbox="852 421 1394 501">Actions that Must Be Carried Out</th> </tr> </thead> <tbody> <tr> <td data-bbox="453 501 852 647">Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> is 0</td> <td data-bbox="852 501 1394 647">At intervals not to exceed 100 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994</td> </tr> <tr> <td data-bbox="453 647 852 792">Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 0 but is equal to or less than 10</td> <td data-bbox="852 647 1394 792">At intervals not to exceed 20 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994</td> </tr> <tr> <td data-bbox="453 792 852 938">Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 10 but is equal to or less than 20</td> <td data-bbox="852 792 1394 938">At intervals not to exceed 10 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994</td> </tr> <tr> <td data-bbox="453 938 852 1055">Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 20</td> <td data-bbox="852 938 1394 1055">Within 10 Cycles, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733</td> </tr> <tr> <td data-bbox="453 1055 852 1196">Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>missing</u> is equal to or exceeds 1</td> <td data-bbox="852 1055 1394 1196">Before further flight, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733</td> </tr> </tbody> </table> <p>Note: In deviation to the instructions of Rolls-Royce NMSB No. 72-AF994, the inspections required by 1) and 2) above can also be carried out while the engine is not installed on an aircraft.</p>	Results of Borescope Inspection	Actions that Must Be Carried Out	Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> is 0	At intervals not to exceed 100 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994	Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 0 but is equal to or less than 10	At intervals not to exceed 20 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994	Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 10 but is equal to or less than 20	At intervals not to exceed 10 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994	Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 20	Within 10 Cycles, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733	Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>missing</u> is equal to or exceeds 1	Before further flight, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733
Results of Borescope Inspection	Actions that Must Be Carried Out												
Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> is 0	At intervals not to exceed 100 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994												
Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 0 but is equal to or less than 10	At intervals not to exceed 20 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994												
Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 10 but is equal to or less than 20	At intervals not to exceed 10 Cycles, re-inspect engine in accordance with Section 3, Accomplishment Instructions of Rolls-Royce NMSB No. 72-AF994												
Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>lifting</u> exceeds 20	Within 10 Cycles, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733												
Total Number of IP Turbine Blade Outer Shroud Dust Caps <u>missing</u> is equal to or exceeds 1	Before further flight, remove engine from service and incorporate Rolls-Royce service bulletin No. 72-D733												
<p>Ref. Publications:</p>	<p>Rolls-Royce RB211 Propulsion System Non Modification Service Bulletin (NMSB) No. 72-AF994.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>												
<p>Remarks :</p>	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. The required actions and the risk allowance have granted the issuance of a Final AD with Request for Comments, postponing the public consultation process after publication. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu 4. For any question concerning the technical content of the requirements in this AD, please contact: Rolls-Royce plc., P.O. Box 31, Derby, DE24 8BJ, United Kingdom; Telephone: +44 (0) 1332 242424, Fax: +44 (0) 1332 249936; Email: tech.help@rolls-royce.com or download the publication from https://www.aeromanager.com 												