EASA AD No.: 2008-0208R2

EASA	AIRWORTHINESS DIRECTIVE
	AD No.: 2008-0208R2
	Date: 24 September 2013
	Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.
This AD is issued in accordance	and of the European third countries that participate in the activities of EASA under Art

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

exemption].			
Design Approval Holder's Name : AIRBUS		Type/Model designation(s): A310 aeroplanes	
TCDS Number: Fi	TCDS Number: France No. 145		
Foreign AD: No	Foreign AD: Not applicable		
Revision: TI	nis AD revises EASA AD 20	08-0208R1 dated 19 December 2008.	
ATA 57	Wings – Centre Wing Bottom Skin at Rib 1 – Inspection		
Manufacturer(s):	Airbus (formerly Airbus Industrie)		
Applicability:	A310 aeroplanes, all certified models, all serial numbers.		
Reason:	Reason: DGAC France issued AD 1997-006-210 for A300, A310 and A300-aircraft to detect the presence of corrosion and prevent crack proparate the wing bottom skin, inboard and outboard of the Rib 1 external surface splice, between Frame (FR) 40 and FR47. This condition, is corrected, could affect the structural integrity of the airframe.		
	applicable Service Bulle number 2005-2576) wa	7-006-210R1 was issued to expand the choice of etins (SB). AD F-1997-006-210R2 (EASA approval s issued to allow A300-600 operators to use B A300-57-6047, converting flight cycles / "Fatigue (FC) / flight hours (FH).	
	the corrosion behaviour inspection programme 10599 A300-600 aerop Board Report (MRBR) i	nodification (mod) 10599 was developed to improve of the area. This improvement allowed refining the of the A300-600 aeroplane. For post-modification lanes, the application of the Maintenance Review inspection tasks was deemed sufficient for the level of safety on these aircraft.	
	requirements of DGAC superseded, to require	sued AD 2008-0208 (later revised), retaining the France AD F-1997-006-210R2, which was the use of Airbus SB A300-57-6047 Revision 05 for exclude post-mod 10599 A300-600 aeroplanes from	

EASA AD No.: 2008-0208R2

Since EASA AD 2008-0208R1 was issued, a fleet survey and updated Fatigue and Damage Tolerance analyses have been performed in order to substantiate the second A300-600 Extended Service Goal (ESG2) exercise. The results of these analyses have shown that the threshold and intervals must be reduced to allow timely detection of these cracks and the accomplishment of an applicable corrective action. For the reasons described above, this AD is revised to remove A300 and A300-600 aeroplanes from the Applicability, while retaining the requirements of EASA AD 2008-0208R1 for A310 aeroplanes. For A300 and A300-600 aeroplanes, the subject is now addressed through new EASA AD 2013-0230. Revision 02: 08 October 2013 Effective Date: Revision 01: 09 December 2008 Original issue: 25 November 2008 Required Action(s) Required as indicated, unless accomplished previously: and Compliance (1) Within 5 years since new or within 18 months after 11 January 1997 Time(s): [the effective date of DGAC AD 1997-006-210, original issue], whichever occurs later, accomplish a detailed visual corrosion inspection and corrective actions if necessary, in accordance with the instructions of SB A310-57-2061 Revision 01. For aircraft in service for 15 to 20 years on 11 January 1997 [the effective date of DGAC AD F-1997-006-210, original issuel, this first inspection must be performed within 12 months after 11 January 1997 [the effective date of DGAC AD F-1997-006-210, original issue]. For aircraft in service for more than 20 years on 11 January 1997 [the effective date of DGAC AD F-1997-006-210, original issue], this first inspection must be performed within 6 months after 11 January 1997 [the effective date of DGAC AD F-1997-006-210, original issue]. (2) After the initial inspection as required by paragraph (1) of this AD, at intervals not to exceed 5 years, repeat the corrosion inspection and corrective actions if necessary in accordance with the instructions of SB A310-57-2061 Revision 01. Depending on the results of each corrosion inspection as required by this AD and the reworked depth, within the thresholds and intervals defined in SB A310-57-2061 Revision 01, accomplish an inspection to detect possible cracks and apply an approved repair solution if needed, in accordance with the instructions of SB A310-57-2061 Revision 01. When cracks are detected, before further flight, contact Airbus for approved instructions and accomplish those instructions accordingly. The thresholds and intervals given for the fatigue inspection programmes have been determined for average flight times of 95 minutes. Note: To establish the average flight time, take the accumulated flight time (counted from the take-off up to the landing) and divide by the number of accumulated flight cycles. This gives the average flight time per flight cycle. When aeroplanes are operated with different average flight times, contact Airbus to obtain the adjusted threshold and intervals. Inspections and corrective actions accomplished in accordance with any previous issue of the Airbus SB identified in this AD are acceptable for compliance with the requirements in this AD.

EASA AD No.: 2008-0208R2

Ref. Publications:	Airbus SB A310-57-2061 original issue dated 04 December 1995 or Revision 01 dated 02 April 1999. The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.	
Remarks:	If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.	
	 The original issue of this AD was posted on 02 September 2008 as PAD 08-100 for consultation until 30 September 2008. The Comment Response Document can be found at http://ad.easa.europa.eu. 	
	 Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u>. 	
	4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS SAS – EIAW (Airworthiness Office), Email: continued.airworthiness-wb.external@airbus.com .	