| EASA | EMERGE | NCY AIRWORTHINESS DIRECTIVE | | |
|---|---|--|--|--|
| | AD No.: 2009-0 | 148-E | | |
| | Date: 09 July 2 | 009 | | |
| K | with Regulation (EC) | y Airworthiness Directive (AD) is issued by EASA, acting in accordance No 216/2008 on behalf of the European Community, its Member States third countries that participate in the activities of EASA under Article 66 of | | |
| This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption]. | | | | |
| Type Approval Ho | olders' Names : | Type/Model designations: | | |
| Agusta S.p.A, Eurocopter, | | A109 series and AB139/Au 199 AS332, AS350 and 2555 series, EC225, SA330, SA365, AS36 and C105 series, SA360, | | |
| Eurocopter Deutschland GmbH, Sikorsky Aircraft Corporation | | EC135, MBB CK 1 V BO 1 V series, S-61 helico | | |
| | EASA R.002, R.005, R.0 LBA Germany No. 3025 FAA U.S.A. 1H15 | | | |
| Foreign AD : | Not applicable | | | |
| Supersedure : | This AD successed Af | AD 200, 01, ated 12 June 2009 | | |
| ATA 25 | ui ne /Fur li p ilo /Rem | shirds – D-Lok Hook of the Rescue Hoist – al from Service / Replacement | | |
| Manufactuers: | rocoter (formerly | ta Aerospace Corporation, American Eurocopter LLC, / Eurocopter France), Eurocopter Deutschland GmbH, A S.A., Sikorsky Aircraft Corporation. | | |
| Applicability: | | A109 series and AB139/AW139 helicopters , | | |
| | | S332, AS350, AS355, SA330, SA365, AS365 and EC155 nd SA360 C helicopters, | | |
| | and | | | |
| | Eurocopter Deutsch helicopters, | land GmbH model EC135, MBB-BK 117 and BO 105 series | | |
| | and | | | |
| | | rporation S-61N helicopters, f equipped with Lifesaving Systems D-Lok Hooks with part | | |
| | numbers (P/N) 410- | A or 410-F and identified as part of lot number 208 or 1108. | | |
| | hoist system manuf | ist P/N provided in the service information of the rescue acturers (Goodrich or Breeze-Eastern) is for information aving Systems D-Lok Hooks P/N to determine AD | | |

| Reason: | Field reports from rescue hoist operators have noted surface irregularities and discontinuities on D-Lok Hooks supplied by Lifesaving Systems with P/N 410-A and 410-F. It was determined that a non-approved change in the hook manufacturing process, from forged material to cast material, is the cause of the irregularities and discontinuities found in the material. | | | |
|----------------------------|---|--|--|--|
| | This condition, if left uncorrected, could lead to the fracture of the hook. Furthermore, the new manufacturing process has not been shown to be compliant with the applicable regulations. | | | |
| | EASA AD 2009-0124 was issued as an emergency measure to mandate visual inspection and replacement, as applicable, of D-Lok Hooks supplied by Lifesaving System with P/N 410-A and 410-F and installed on certain Goodrich Corporation hook kits or rescue hoist assemblies. | | | |
| | It has been later discovered that the same Lifesaving Systems D-Lok Hooks P/N are also installed on Breeze-Eastern Corporation rescue hoist assemblies. | | | |
| | For the above stated reasons this AD, which supersedes EASA AD 2009-0124, requires inspection of Goodrich and Breeze-Eastern rescue hoist assemblies and, if the affected D-Lok Hooks are found installed, their removal from service or replacement with serviceable parts. | | | |
| Effective Date: | 11 July 2009 | | | |
| Required Action(s) | Required as indicated, unless previoe to accompany de | | | |
| and Compliance Time(s): | From the effective date of the AD before the next how over attain inspect the rescue hoist assembly ad, if a lifest into your more Lok Hook with P/N 410-A or 410-From the testified a span of the under 208 or 1108 (cast hook) is found inspecting on the under stem manufacturer (Goodrich or Breezer and n), and do not the under stem manufacturer (Goodrich or Breezer and n), and do not the under type. If the hook does not passive virial type and in on the under type. If the hook does not passive virial type and in on the under type. If the hook does not passive virial type and in on the under type. If the hook does not passive virial type and in on the under type. If the hook does not passive virial type and relevant of the referenced out, before the ffer vielate and AL indiccordance with paragraph (1) or (3) of EASA of 2000 12 are usepude to comply with paragraph (1) of this AD. The minime visu transpection criteria of the referenced Goodrich and reference and the publications are applicable. Required Actions and Complete and Times are as described in this AD section. Within 30 days after the effective date of this AD, or within 1000 Total Lift cales of the hoist since installation of the affected hook, whichever occurs filled, replace the cast hook with a serviceable part to continue hoist operations. After the effective date of this AD, do not install a D-Lok Hook with P/N 410-A or 410-F and identified as part of lot number 208 or 1108 on any helicopter. | | | |
| Ref. Publications: | Goodrich Service Bulletin 42315-489-01 revision 1, | | | |
| | Breeze-Eastern Corporation Service Information Letter SIL01 BLH-20200-431 original release, | | | |
| | Breeze-Eastern Corporation Service Bulletin SB BLH-20200-504-25-01 original release, | | | |
| | Breeze-Eastern Corporation Service Information Letter SIL01 HK-116-5 original release. | | | |
| Remarks: | If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. | | | |
| | The safety assessment has requested not to implement the full consultation process and an immediate publication and notification. | | | |

| 3. | Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u> . |
|----|--|
| 4. | For any question concerning the technical content of the requirements in this AD, please contact: |
| | Goodrich Corporation , Sensors and Integrated Systems 1550 S. Valley Vista Drive, Diamond Bar, California United States of America Tel: +1 909 569-0210 ; Fax: +1 909 569-0387. |
| | Goodrich Corporation, Sensors and Integrated Systems Saint-Ouen l'Aumône 13 Avenue de l'Eguillette BP 7186 Cergy-Pontoise, Val d'Oise 95056 - France Tel: +33 (0) 1 3432 6781 ; Fax: +33 (0) 1 3432 6323. |
| | Breeze-Eastern Corporation 700 Liberty Avenue Union, New Jersey 07083-8198 USA Ph.: +1 (908) 686-4000, Ext. 3897, or 3890. 1-800-929-1919 (Toll-Free US and Canada on y) Fax: +1 (908) 688-6495 E-Mail: <u>customerservice@breeze-entern.com</u> |

C