

EASA	AIRWORTHINESS DIRECTIVE	
	AD No.: 2009-0156	
	Date: 17 July 2009 Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.	
This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].		
Type Approval Holder's Name : AIRBUS	Type/Model designation(s) : A330 and A340-200/-300 aeroplanes	
TCDS Number : EASA A.004, EASA A.015		
Foreign AD : Not applicable		
Supersedure : None		
ATA 55	Stabilizers – Rudder Side Shell Skin – Inspection	
Manufacturer(s):	Airbus (formerly Airbus Industrie)	
Applicability:	Airbus A330 aeroplanes, models -301, -302, -303, -321, -322, -323, -341, -342 and -343, all manufacturer serial numbers, and Airbus A340 aeroplanes, models -211, -212, -213, -311, -312 and -313, all manufacturer serial numbers, if equipped with Carbon Fiber Reinforced Plastic (CFRP) rudders having part numbers (P/N) and serial numbers (S/N) as listed in the Appendix A to this AD.	
Reason:	Surface defects were visually detected on the rudder of an A319 and an A321 in-service aeroplane. Investigation has determined that the defects reported on both rudders corresponded to areas that had been reworked in production. The investigation confirmed that the defects were as a result of de-bonding between the skin and honeycomb core. Such reworks were also performed on some rudders fitted on A330 and A340-200/-300 aeroplanes. An extended de-bonding, if not detected and corrected, may degrade the structural integrity of the rudder. The loss of the rudder leads to degradation of the handling qualities and reduces the controllability of the aeroplane.	

	This AD requires inspections of specific areas and, depending on findings, the application of corrective actions for those rudders where production reworks have been identified.
Effective Date:	31 July 2009
Required action(s) and Compliance Time(s):	<p>Required as indicated:</p> <p>For the purpose of this AD a Reference Date is defined as the effective date of this AD or the date when the rudder will accumulate 13 000 Flight Cycles (FC) from its first installation on an aeroplane, whichever occurs later.</p> <p>Depending on the locations of the areas to be inspected as defined in AIRBUS AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable, apply the following actions:</p> <p>(1) <u>Reinforced area location:</u></p> <p>Unless already accomplished, within 1 800 Flight Hours (FH) from the Reference Date, perform Vacuum Loss inspection on the rudder reinforced area in accordance with instructions defined in Airbus AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable.</p> <p>(2) <u>Trailing edge area location:</u></p> <p>(2.1) Unless already accomplished, within 21 months from the Reference Date, perform Elasticity Laminate Checker inspection on the rudder trailing edge area in accordance with instructions defined in Airbus AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable.</p> <p>(2.2) In case of no findings, repeat two further times the inspection defined in paragraph (2.1) of this AD at intervals not to exceed 4 500 FC but not less than 4 000 FC from the last inspection.</p> <p>(3) <u>Other areas locations (lower rib/upper edge/leading edge/other locations):</u></p> <p>(3.1) Unless already accomplished, within 1 800 FH from the Reference Date, perform Elasticity Laminate Checker inspection on the other areas (lower rib/upper edge/leading edge/other locations) in accordance with instructions defined in Airbus AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable.</p> <p>(3.2) Repeat the inspection defined in paragraph (3.1) of this AD at intervals not to exceed 1 800 FH from the last inspection.</p> <p>(3.3) In case of no findings during the inspection defined in paragraph (3.1) or (3.2) of this AD, unless already accomplished, within 21 months from the Reference Date, perform Vacuum Loss inspection on these areas (lower rib/upper edge/leading edge/other locations) in accordance with instructions defined in Airbus AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable.</p> <p>(3.4) Accomplishment of the inspection required by paragraph (3.3) of this AD cancels the initial and repetitive inspections required by paragraphs (3.1) and (3.2) of this AD.</p>

	<p>(4) In case of findings during the inspection defined in paragraph (1), (2.1), (2.2), (3.1), (3.2) or (3.3) of this AD, before next flight, contact Airbus for further instructions and apply the associated instructions and corrective actions in accordance with the approved data provided.</p> <p>(5) In case of no findings during the inspection defined in paragraphs (1) and (3.3) of this AD, before next flight, restore the vacuum loss holes as per the option selected in accordance with Note 3 of §4.2.6 of AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01, as applicable, and apply the associated instructions until performance of permanent restoration.</p> <p>(6) Within 10 days after accomplishment of each inspection in accordance with paragraphs (1), (2) or (3) of this AD, report the results, including no findings, to Airbus.</p> <p>(7) All rudders that have passed the inspection, prior to the effective date of this AD, in accordance with the instructions of Airbus AOT A330-55A3040 at original issue or AOT A340-55A4036 at original issue, are compliant with the associated requirements of this AD for the areas inspected. Additional areas requiring inspection are defined in Airbus AOT A330-55A3040 Revision 01 or AOT A340-55A4036 Revision 01. For these additional areas the requirements of this AD are applicable. For all areas, the repetitive inspections required by this AD remain applicable.</p> <p>(8) After the effective date of this AD, no person shall install any rudder listed in Appendix A to this AD on an aeroplane, unless in compliance with the requirements of paragraph (1), (2), (3) or (5) of this AD.</p>
Ref. Publications:	<p>Airbus All Operators Telex A330-55A3040 Revision 01, Airbus All Operators Telex A340-55A4036 Revision 01.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. The required actions and the risk allowance have granted the issuance of a Final AD with Request for Comments, postponing the public consultation process after publication. 3. Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu . 4. For any questions concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EAL, E-mail: airworthiness.A330-A340@airbus.com .

EASA AD No. 2009-0156: Appendix A

Rudder Part Number	Rudder Serial Number
F554-70000-000-00	TS-2013
F554-70000-000-00	TS-2015
F554-70000-000-00	TS-2016
F554-70000-000-00	TS-2017
F554-70000-000-00	TS-2018
F554-70000-000-00	TS-2020
F554-70000-000-00	TS-2021
F554-70000-000-00	TS-2024
F554-70000-000-00	TS-2026
F554-70000-000-00	TS-2035
F554-70000-000-00	TS-2036
F554-70000-000-00	TS-2040
F554-70000-000-00	TS-2042
F554-70000-000-00	TS-2055
F554-70000-000-00	TS-2056
F554-70000-000-00	TS-2058
F554-70000-000-00	TS-2059
F554-70000-000-00	TS-2061
F554-70000-000-00	TS-2062
F554-70000-000-00	TS-2063
F554-70000-000-00	TS-2065
F554-70000-002-00	TS-2074
F554-71000-000-00	TS-3003
F554-71000-000-00	TS-3004
F554-71000-000-00	TS-3005
F554-71000-000-00	TS-3006
F554-71000-000-00	TS-3007
F554-71000-000-00	TS-3008
F554-71000-000-00	TS-3011
F554-71000-000-00	TS-3015
F554-71000-000-00	TS-3033
F554-71000-000-00	TS-3061
F554-71000-000-00	TS-3064
F554-71000-000-00	TS-3066
F554-71000-000-00	TS-3071
F554-71000-000-00	TS-3072
F554-71000-000-00	TS-3075
F554-71000-000-00	TS-3079
F554-71000-000-00	TS-3084
F554-71000-000-00	TS-3087
F554-70005-000-00	TS-3100
F554-70005-000-00	TS-3106
F554-70005-000-00	TS-3107
F554-70005-000-00	TS-3119
F554-70005-000-00	TS-3124