EASA

AIRWORTHINESS DIRECTIVE

X

AD No.: 2010-0004

Date: 05 January 2010

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

Type Approval Holder's Name :		Type/Model designation(s) :
TURBOMECA		ASTAZOU XIV turboshaft engines
TCDS Number:	EASA.E.075	X
Foreign AD :	Not applicable	
Supersedure :	This AD supersedes EASA AD	No. 2009-0136 dated 23 June 2009.
ATA 72	Engine Rotating Asse Inspection / Removal	mbly – Third Stage Turbine Wheel –
Manufacturer(s):	Turboméca	

Applicability:	All ASTAZOU XIV B and XIV H turboshaft engines, if fitted with a third stage turbine wheel that incorporates modification AB 173 or modification AB 208, except those engines that also incorporate Turboméca Service Bulletin (SB) 283 72 0805 or whose third stage turbine wheel has a serial number (S/N) outside the range specified in Table 1. These engines are known to be installed in, but not limited to, EUROCOPTER ALOUETTE/III SA 319 B and GAZELLE SA 342 J helicopters.
Reason:	Investigation of an uncommanded in-flight shut down (IFSD) revealed that a third stage turbine wheel rupture was not contained by the turbine casings. The released portion consisted of a turbine blade together with the rim piece immediately below the blade. The rim piece was bounded by two adjacent axial slots and a fatigue crack that had developed between the holes in which the slots terminate. The slots and holes, which are closed by riveted plugs, were introduced by modification AB 173 in order to improve the vibration characteristics of the turbine wheel. Modification AB 208 brings an improvement to modification AB 173 by changing only the riveting detail. SB 283 72 0805 provides instructions for re-boring the holes at overhaul or repair in order to improve their surface condition. A manufacturing process modification has been introduced to improve the surface condition of these holes in third stage turbine wheels. Wheels subject to the improved manufacturing process have S/Ns outside the range specified in Table 1.
	uncommanded IFSD, with no damage to the aircraft, the possibility exists that additional events may occur, potentially involving damage to the aircraft.

	To address the unsafe condition, EASA issued AD 2009-0136 mandating inspection of certain third stage turbine wheels and removal of any damaged wheel. The wheels to be inspected were those whose cycles since new (CSN) would exceed 2000 by 01 February 2011. Following additional research by Turboméca on crack initiation and growth, this AD mandates inspections based on new criteria and removal of any damaged			
	wheel.			
Effective Date:	19 January 2010			
	Required as indicated unless accomplished previously:			
Required Action(s) and Compliance Time(s):	 (1) For any given 3rd stage wheel which at the effective date of this AD has accumulated less than 500 cycles since last overhaul or repair, or since new if the engine has never been overhauled or repaired, within an additional 300 cycles do a dye penetrant inspection on the rear face of the 3rd stage turbine wheel as instructed in section 2 of Turboméca MSB 283 72 0804 Version C. Do a second inspection 500 ± 50 cycles after the first one. (2) For any given 3rd stage wheel which at the effective date of this AD has accumulated 500 cycles or more, but less than 700 cycles, since last overhaul or repair, or since new if the engine has never been overhauled or repaired, within an additional 200 cycles or more, but less than 700 cycles, since last overhaul or repair, or since new if the engine has never been overhauled or repaired, within an additional 200 cycles on the section 2 of the sect			
	the rear face of the 3 rd stage turbine wheel as instructed in section 2 of Turboméca MSB 283 72 9804 Version C.			
	 (3) For any given 3rd stage wheel which at the effective date of this AD has accumulated 700 cycles of more, but less than 1200 cycles, since last overhaul or repair, or since new if the engine has never been overhauled or repaired, within an additional 150 cycles do a dye penetrant inspection on the rear face of the 3rd stage turbine wheel as instructed in section 2 of Turboméca MSB 283 72 0804 Version C. 			
	(4) If any crack indication is found, before further flight, remove the engine from service and send it to a Turboméca qualified repair centre.			
	(5) For any given 3 rd stage wheel which at the effective date of this AD has accumulated 1200 cycles or more since last overhaul or repair, or since new if the engine has never been overhauled or repaired, no action is required.			
	Turboméca Mandatory Service Bulletin 283 72 0804 Version C.			
Ref. Publications :	The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.			
	Turboméca ASTAZOU XIV B-F Maintenance Manual 283 00 936; Turboméca ASTAZOU XIV H Maintenance Manual 283 02 933; Turbantéca ASTAZOU XIV B-F-H-M Overhaul Manual X 283 72 500 2.			
	 If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 			
	 This AD was posted on 25 November 2009 as PAD 09-133 for consultation until 23 December. No comments were received during the consultation period. 			
Remarks :	 Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail <u>ADs@easa.europa.eu</u>. 			
	 For any question concerning the technical content of the requirements in this AD, please contact: Operator Support ASTAZOU - TURBOMECA 40220 TARNOS – FRANCE Phone: +33 (0)5 59 74 40 00 Fax: +33 (0)5 59 74 45 15 or refer to your 			

nearest TURBOMECA technical representative on
http://www.turbomeca-support.com.



Part Number	Serial Number						
0265257000	All Serial Num	bers					
0265257020	All Serial Num	bers					
0265257060	All Serial Num	All Serial Numbers					
0265257050	ADA6021AD	ADC7784AD	ADH5855AD	ADHB992AD			
	ADB1620AD	ADC7786AD	ADH5856AD	ADHB993AD			
	ADB3876AD	ADC7787AD	ADH5858AD	ADHB994AD			
	ADB3883AD	ADC7788AD	ADH5859AD	ADHB995AD			
	ADB3885AD	ADC7789AD	ADH5860AD	ADHB996AD			
	ADB3887AD	ADD1788AD	ADH5861AD	ADHB997AD			
	ADB3888AD	ADD1789AD	ADH5862AD	ADHB998AD			
	ADB4431AD	ADD1790AD	ADH7893AD	ADHB999AD			
	ADB4440AD	ADD1791AD	ADH7894AD	ADHC001AD			
	ADB8688AD	ADH4619AD	ADH7895AD	ADHC002AD			
	ADB8692AD	ADH4622AD	ADH7896AD	ADHC003AD			
	ADB8694AD	ADH4623AD	ADH7897AD	ADHC004AD			
	ADB9855AD	ADH4624AD	ADH7902AD	ADHC005AD			
	ADB9857AD	ADH4625AD	ADH7903AD	ADHC006AD			
	ADB9860AD	ADH4626AD	ADH7904AD	ADHC007AD			
	ADB9861AD	ADH4627AD	ADH7906AD	ADHC008AD			
	ADC0035AD	ADH4629AD	ADH8560AD	ADHC009AD			
	ADC3206AD	ADH4630AD	ADH85 <mark>6</mark> 1AD	ADHC010AD			
	ADC3210AD	ADH4631AD	ADH85 <mark>64</mark> AD	ADHC011AD			
	ADC5301AD	ADH4634AD	ADH8565AD	ADHC012AD			
	ADC5302AD	ADH4652AD	ADH8566AD	ADHC013AD			
	ADC5308AD	ADH4653AD	ADHB981AD	F200AD			
	ADC5309AD	ADH4654AD	ADHB982AD	F202AD			
	ADC5312AD	ADH4655AD	ADHB983AD	F203AD			
	ADC5314AD	ADH4656AD	ADHB984AD	F204AD			
	ADC5315AD	ADH4657AD	ADHB985AD	F207AD			
	ADC6691AD	ADH4664AD	ADHB986AD	J274AD			
	ADC6695AD	ADH4664AD	ADHB987AD	J276AD			
	ADC6698AD	ADH4665AD	ADHB988AD	J280AD			
	ADC6700AD	ADH <mark>5</mark> 846AD	ADHB989AD	J282AD			
	ADC7782AD	ADH5847AD	ADHB990AD	J288AD			
	ADC7783AD	ADH5854AD	ADHB991AD				

Table 1. Serial Numbers of turbine wheels to which this AD applies