EASA AD No.: 2010-0056

## EASA

## **AIRWORTHINESS DIRECTIVE**

AD No.: 2010-0056

Date: 29 March 2010

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

Type Approval Holder's Name :		Type/Model designation(s) :	
AIRBUS		A340-500/-600 aeroplanes	
TCDS Number :	TCDS Number: EASA.A.015		
Foreign AD: Not applicable			
Supersedure: None			
ATA 57	Wings – Inner Ailerons - Inspection		
Manufacturer(s):	Airbus (formerly Airbus Industrie)		
Applicability:	Airbus A340 aeroplanes, models -541, -542, -642 and -643, all manufacturer serial numbers.		
Reason:	Following a Structural Repair Manual (SRM) repair strength re-evaluation, some Allowable Damage Limits (ADL) and Repairs of holes and delaminations in composite panels have been found to be no more compliant with certification requirements for A340-500/-600 inner aileron.		
	Therefore, some Allowable Damage Limits and Repairs published in SRM Chapters 57-61-12 PB101 and 57-61-12 PB201 were de-validated starting from the SRM revision issued on January 2009. The terminology "De-validated SRM" used in this AD text refers to the SRM chapters mentioned above.		
	disbonding of the repai validated SRM", which this AD requires a one	replete inner aileron split due to possible failure or rs on the inner aileron panels performed as per "demay result in flutter coupling of the free aileron part, time inspection of the inner aileron panels to f "de-validated SRM" repairs and, if necessary, to prrective actions.	
Effective Date:	12 April 2010		

EASA Form 110 Page 1/2

EASA AD No.: 2010-0056

Required action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously:  (1) In accordance with the instructions defined in Airbus Service Bulletin (SB) A340-57-5026, within 800 Flight Hours after the effective date of this AD, perform an inspection programme (tap test and visual inspection) or special detailed inspection (thermography inspection) of affected inner aileron panels at LH and RH wings in order to detect any previous accomplishment of "de-validated SRM" repair.
	(2) In case "de-validated SRM" repair is suspected, before next flight, contact Airbus to obtain the necessary approved instructions for corrective action and accomplish those instructions accordingly.
	(3) A review of aeroplane maintenance records is acceptable in lieu of the inspection required by paragraphs (1) of this AD if the de-validated SRM Chapters 57-61-12 PB101 and 57-61-12 PB201 from SRM revisions dated before January 2009 can be conclusively identified from that review.
	(4) After the effective date of this AD, do not install inner aileron panel on an aeroplane, unless in compliance with the requirements of this AD.
Ref. Publications:	Airbus Service Bulletin A340-57-5026 at original issue.
	The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.
Remarks:	If requested and appropriately substantiated, EASA can approve     Alternative Methods of Compliance for this AD.
	<ol> <li>The required actions and the risk allowance have granted the issuance of a Final AD with Request for Comments, postponing the public consultation process after publication.</li> </ol>
	<ol> <li>Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management &amp; Research Section, Certification Directorate, EASA. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a>.</li> </ol>
	<ol> <li>For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EAL; E-mail: <u>airworthiness.A330-A340@airbus.com</u>.</li> </ol>

EASA Form 110 Page 2/2