EASA

EMERGENCY AIRWORTHINESS DIRECTIVE

AD No.: 2010-0064-E

Date: 01 April 2010

Note: This Emergency Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation

This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

Type Approval	Holder's Name :	Type/Model designation(s) :		
EUROCOPTER	R	SA 365, AS 365 and SA 366 helicopters		
TCDS Number:	France No.159			
Foreign AD:	Not applicable			
Supersedure:	This AD supersedes EASA Emergency AD 2009-0125-E dated 12 June 2009 and the correction dated 15 June 2009.			
ATA 53	Fuselage – Frame No. 9 – Inspection / Repair			
Manufacturer(s):	Eurocopter (formerly Eurocopter France, Aérospatiale)			
Applicability:	SA 365 N, SA 365 N1, AS 365 N2 and AS 365 N3 helicopters, all serial numbers, and SA 366 G1 helicopters, all serial numbers.			
Reason:	Eurocopter was informed of a an AS 365 N2 helicopter which The crack, which was located a grown over a large section of t discovered during the Major In This condition, if not corrected would adversely affect the strue Pending the results of the anal cause of the crack, EASA Eme detailed visual inspections on t to detect any crack and, in cas associated corrective actions. The results of the analyses sho this area varies a lot according aircraft versions.	crack which was discovered in the No.9 frame of had logged a total of 10 786 Flight Hours (FH). 230 mm above the cabin floor and which had he No.9 frame on the Right Hand (RH) side, was spection of the helicopter. , could lead to the failure of the No.9 frame which ictural integrity of the helicopter. lyses that were being conducted to establish the ergency AD 2009-0125-E was published to require the RH and Left Hand (LH) side of the No.9 frame a crack was found, to accomplish the bow that the time required for initiation of a crack in to the weight and balance data of the different		
	For the reasons described abo Emergency AD 2009-0125-E, compliance times according to	ove, this AD retains the requirements of EASA which is superseded, and modifies the action helicopter types.		

Effective Date:	06 April 2010		
	 Required as indicated, unless accomplished previously: (1) Prior to reaching the FH threshold as defined in Table 1 of this AD, as applicable, or within 10 FH after the effective date of this AD, whichever occurs later, inspect the inner angles and flanges of the No.9 frame on the RH and LH sides, in accordance with the instructions of paragraph 2 of Eurocopter Alert Service Bulletin (ASB) AS365 ASB 05.00.57 Revision 1, or SA366 ASB 05.39 Revision 1, as applicable to helicopter model. 		
	Table 1		
	Helicopter model: Threshold:		
	AS 365 N3 2 090 FH		
	AS 365 N2 3 190 FH		
	SA 365 N 8 990 FH		
	SA 365 N1, SA 366 G1 9 990 FH		
	(2) Thereafter, at intervals not exceeding 110 FH, repeat the inspection in accordance with the instructions of paragraph 2 of Eurocopter Alert Service Bulletin (ASB) AS365 ASB 05.00.57 Revision 1, or SA366 ASB 05.39 Revision 1, as applicable to helicopter model.		
Required Action(s) and Compliance Time(s):	(3) If, during any inspection as required by paragraph (1) or (2) of this AD, a crack is found, contact Eurocopter for approved repair instructions and accomplish those instructions within the compliance time, as applicable to crack length detected, as indicated in Table 2 of this AD.		
	Table 2		
	Detected Crack Location and Required Action(s): Length		
	 Inner Flange, less than 33 mm or Inner Angle, less than 33 mm Reduce the interval of the inspection as required by paragraph (2) of this AD to not exceed 10 FH; accomplish the approved repair within 660 FH or 12 months, whichever occurs first after detection of the crack.		
	- Inner Flange, 33 mm or longer or - Inner Angle, 33 mm or longer		
	Inner Angle and irrespective of lengthaccomplish the approved repair before next flight		
	 (4) Repair of a helicopter as required by paragraph (3) of this AD does not constitute terminating action for the repetitive inspection requirements of paragraph (2) of this AD. 		
Ref. Publications:	Eurocopter AS365 ASB 05.00.57 Revision 1, and Eurocopter SA366 ASB 05.39 Revision 1, both dated 31 March 2010.		
	The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.		

	1.	If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
	2.	The safety assessment has requested not to implement the full consultation process and an immediate publication and notification.
Remarks :	3.	Enquiries regarding this AD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u> .
	4.	For any question concerning the technical content of the requirements in this AD, please contact: EUROCOPTER (STDI) – Aéroport de Marseille Provence 13725 Marignane Cedex, France; telephone: +33 (0) 4 42 85 97 10; fax: +33 (0) 4 42 85 99 66; E-mail: <u>Airframe.technical-support@eurocopter.com</u>