EASA AD No.: 2013-0075

EASA

AIRWORTHINESS DIRECTIVE

AD No.: 2013-0075

Date: 20 March 2013

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption]

mption].		T
Design Approva	ıl Holder's Name:	Type/Model designation(s):
AIRBUS		A310, A300-600 and A300-600ST aeroplanes
TCDS Number:	France No. 145 and EA	ASA.A.014
Foreign AD:	Not applicable	
Supersedure:	This AD supersedes E	ASA AD 2007-0092 dated 10 April 2007.
	T =	
ATA 05		Maintenance Checks – Ageing Systems LS Part 4 – Amendment
Manufacturer(s):	Airbus (formerly Air	bus Industrie)
Applicability:	Airbus A310 and A serial numbers (MS	300-600 aeroplanes, all certified models, all manufactur
	Airbus A300F4-608	SST aeroplanes, all MSN.
Reason:		limitations for Airbus aeroplanes are currently published ations Section (ALS) documents.
	Ageing Systems M 600 ALS Part 4 doo Safety Agency (EA	tructions and airworthiness limitations applicable to the aintenance (ASM) are specified in Airbus A310 or A300 cuments, which are approved by the European Aviation (SA). EASA AD 2007-0092 was issued to require requirements as specified in these documents.
	introduces more re	Airbus A310 and Airbus A300-600 ALS Part 4 documen strictive maintenance requirements and/or airworthiness to comply with the instructions of ALS Part 4 could resultion.
	EASA AD 2007-009 of the new or more airworthiness limita	escribed above, this new AD retains the requirements of 92, which is superseded, and requires the implementation restrictive maintenance requirements and/or ations as specified in Airbus A310 ALS Part 4 Revision 00 ALS Part 4 Revision 02, as applicable to aeroplane

EASA AD No.: 2013-0075

Effective Date:	03 April 2013		
Required Action(s)	Required as indicated, unless accomplished previously:		
and Compliance Time(s):	Re-statement of EASA AD 2007-0092 requirements:		
	(1) Within 3 months after 24 April 2007 [the effective date of EASA AD 2007-0092], comply with all applicable maintenance requirements and associated airworthiness limitations included in Airbus A310 ALS Part 4 Revision 01, or A300-600 ALS Part 4 Revision 01, as applicable to aeroplane type/model.		
	New requirements of this AD:		
	(2) From the effective date of this AD, within the compliance times defined in the Record of Revisions (ROR) pages of the Airbus A310 ALS Part 4 Revision 02, or Airbus A300-600 ALS Part 4 Revision 02, as applicable to aeroplane type/model, accomplish the following actions, depending on aeroplane configuration, included by reference in the ROR of the Airbus A310 ALS Part 4 Revision 02, or Airbus A300-600 ALS Part 4 Revision 02, as applicable to aeroplane type/model.		
	(2.1) Replace each component before or upon reaching the applicable life limit, and		
	(2.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.		
	(3) If, during accomplishment of any task as required by paragraph (2) of this AD, discrepancies are detected, within the applicable compliance time specified in the Airbus maintenance documentation, accomplish the applicable corrective actions in accordance with instructions specified (or incorporated by reference) in the applicable Airbus maintenance documentation.		
	If no compliance time is identified in the Airbus maintenance documentation, before next flight, accomplish the corrective actions, or contact Airbus for approved instructions and, within the compliance time specified on those instructions, accomplish those instructions accordingly.		
	If any of the discrepancies detected during accomplishment of any task, as required by paragraph (2) of this AD, is not defined in the Airbus maintenance documentation, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.		
	(4) Compliance with the requirements of paragraph (2) of this AD can be demonstrated by:		
	(4.1) Revising as follows the approved Aircraft Maintenance Programme (AMP), on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane:		
	Incorporate all instructions and airworthiness limitations specified in Airbus A300-600 ALS Part 4 Revision 02 or Airbus A310 ALS Part 4 Revision 02, as applicable to aeroplane type/model and that are relevant to the aeroplane configuration,		
	(4.2) Complying with the approved AMP described in paragraph (4.1) of this AD.		
Ref. Publications:	s: Airbus A300-600 ALS Part 4 Revision 02, approved by EASA on 18 April 2012.		
	Airbus A310 ALS Part 4 Revision 02, approved by EASA on 30 November		

EASA AD No.: 2013-0075

	2012. The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.	
Remarks:	If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.	
	 This AD was initially posted on 15 May 2012 as PAD 12-046 for consultation until 12 June 2012, and republished on 28 February 2013 as PAD 12-046R1 for consultation until 14 March 2013. The Comment Response Document can be found at http://ad.easa.europa.eu. 	
	 Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail <u>ADs@easa.europa.eu</u>. 	
	 For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS SAS – EIAW (Airworthiness Office, Telephone: + 33 5 61 18 41 39, Fax: + 33 5 61 93 44 51). 	

