## EASA

## **AIRWORTHINESS DIRECTIVE**



## AD No.: 2013-0203

## Date: 06 September 2013

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

<b>Design Approval Holder's Name:</b> AIRBUS		<b>Type/Model designation(s):</b> A320 aeroplanes	
TCDS Number:	EASA.A.064		
Foreign AD: Not Applicable			
Supersedure: None			
ATA 53	Fuselage – Frame 47 Splice Plate Butt Joint Crossing Area – Inspection / Repair		
	1		
Manufacturer(s):	Airbus (formerly Airbus Industrie)		
Applicability:	Airbus A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232 and A320-233 aeroplanes, all manufacturer serial numbers, except those on which Airbus Modification (Mod) 31012 has been embodied in production.		
Reason:	During the full scale fatigue test on A320-200, cracks were reported at the splice plate of the frame (FR) 47 butt joint crossing area, both sides.		
	This condition, if not detected and corrected, could affect the structural integrity of the aeroplane.		
	Prompted by these findings, on the production line to mod fastener row butt joint to prev corresponding modification v Bulletin (SB) A320-53-1271.	Airbus developed Mod 31012 and introduced this dify the current 2 fastener row butt joint into a 3 vent further damage. For in-service aeroplanes, a vas developed and published as Airbus Service	
	For the reason describe abor inspections (SDI) of the splic depending on findings, accor	ve, this AD requires repetitive special detailed e plate of the FR47 butt joint crossing area and, mplishment of applicable corrective action(s).	
	This AD also introduces an o action for the repetitive SDI r	ptional modification, which constitutes terminating equired by this AD.	
Effective Date:	20 September 2013		

Required Action(s)	Required as indicated, unless accomplished previously:		
and Compliance Time(s):	(1) Within the compliance times defined in Table 1 of this AD, as applicable, and, thereafter, at intervals not to exceed 14 800 flight cycles (FC) or 29 600 flight hours (FH), whichever occurs first, accomplish a SDI of the splice plate of FR47 butt joint crossing area (both sides) in accordance with the instructions of Airbus SB A320-53-1260.		
	Table 1 - Initial inspection		
	Time accumulated, on the effective date of this AD (whichever occurs first since aeroplane first flight)	<b>Compliance time</b> (whichever occurs first)	
	Equal to or more than 44 000 FC or 88 000 FH	Within 1 500 FC or 3 000 FH after the effective date of this AD	
	Equal to or more than 27 700 FC or 55 400 FH, but less than 44 000 FC or 88 000 FH	Within 3 000 FC or 6 000 FH after the effective date of this AD, without exceeding 45 500 FC or 91 000 FH since aeroplane first flight	
	Less than 27 700 FC or 55 400 FH	Before exceeding 30 700 FC or 61 400 FH since aeroplane first flight	
	(2) If, during any SDI as required by paragraph (1) of this AD, damage is detected, before next flight, contact Airbus for approved repair instructions and accomplish those instructions accordingly.		
	(3) Modification of an aeroplane in accorda SB A320-53-1271 constitutes terminatin required by paragraph (1) of this AD.	<ol> <li>Modification of an aeroplane in accordance with the instructions of Airbus SB A320-53-1271 constitutes terminating action for the repetitive SDI required by paragraph (1) of this AD.</li> </ol>	
Ref. Publications:	Airbus SB A320-53-1260 original issue, dated 19 December 2012.		
	Airbus SB A320-53-1271 original issue, dated 18 December 2012. The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.		
Remarks:	<ol> <li>If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.</li> </ol>		
	<ol> <li>This AD was posted on 02 July 2013 as PAD 13-091 for consultation until 30 July 2013. No comments were received during the consultation period.</li> </ol>		
	<ol> <li>Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u>.</li> </ol>		
	<ol> <li>For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS - Airworthiness Office – EIAS, Fax +33 5 61 93 44 51. E-mail: <u>account.airworth-eas@airbus.com</u>.</li> </ol>		