


EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2014-0028</p> <p>Date: 30 January 2014</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>	
<p>Design Approval Holder's Name: AGUSTAWESTLAND S.p.A.</p>	<p>Type/Model designation(s): AW139 helicopters</p>
TCDS Number:	EASA.R.006
Foreign AD:	Not applicable
Supersedure:	This AD supersedes EASA AD 2013-0298 dated 16 December 2013.
ATA 30	Ice and Rain Protection – Full Icing Protection System / Cable Inspection – Tail Rotor Distributor Replacement / Auto Transformer Rectifier Unit Replacement and Repetitive Check / AC Generator Control Unit Replacement
Manufacturer(s):	AgustaWestland S.p.A. (formerly Agusta S.p.A.) and AgustaWestland Philadelphia Corporation (formerly Agusta Aerospace Corporation)
Applicability:	AW139 helicopters, all serial numbers, if equipped with Full Icing Protection System (FIPS).
Reason:	<p>An event of arcing inside some components of the FIPS has been reported. The results of the subsequent technical investigation indicated that improper insulation of one of the main rotor electrical cables was the likely cause for this arcing.</p> <p>This condition, if not detected and corrected, could lead to other events of arcing, possibly resulting in fire and consequent damage to the helicopter and injury to occupants.</p> <p>To address this potential unsafe condition, AgustaWestland published Bollettino Tecnico (BT) 139-324, providing inspection instructions for affected in-service helicopters, and EASA issued AD 2013-0090 to require a one-time inspection of the main and tail rotor electrical cables and, depending on findings, accomplishment of applicable corrective actions.</p> <p>Since that AD was issued, the results of additional investigations prompted AgustaWestland to revise BT 139-324 to introduce more refined insulation limits and to remove the inspection of tail rotor (TR) slip ring cables, Part Number (P/N) 4G6420V00151, or P/N 4G6420V00152. In addition, AgustaWestland issued BT 139-330 including instructions to replace the Tail</p>

	<p>Rotor Distributor (TRD) with an improved part that increased dielectric strength.</p> <p>Consequently, EASA issued AD 2013-0124, which superseded EASA AD 2013-0090, partially retaining its requirements, also requiring installation of the improved TRD, and deleting the inspection of the TR slip ring cable. In addition, as an alternative to the main rotor electrical cables inspection, this AD allowed de-activation of the FIPS in accordance with the applicable helicopter Master Minimum Equipment List (MMEL).</p> <p>Subsequently, EASA issued AD 2013-0174, which superseded EASA AD 2013-0124, retaining its requirements, and amending the Applicability with inclusion of additional helicopter serial numbers.</p> <p>Since issuance of EASA AD 2013-0174, as additional corrective action, AgustaWestland issued BT 139-339, providing instructions to replace the Auto Transformer Rectifier Unit (ATRU) with an improved part, incorporating increased resistance to voltage transients resulting from short circuit events on the output of the ATRUs. Moreover, AgustaWestland issued BT 139-340 Revision A providing instructions to replace the AC Generator Control Unit (GCU) with a new AC GCU P/N, including modification of the wiring connections, to incorporate an improved voltage and current transient protection in case of short circuit events. Accomplishment of those actions was required with the issuance of EASA AD 2013-0298, which retained the requirements of EASA AD 2013-0174 and amended the Applicability by including additional helicopter serial numbers and required replacement of ATRU and AC GCU. In addition, for the improved ATRU, this AD required repetitive functional checks.</p> <p>Since issuance of EASA AD 2013-0298, a further event occurred on a helicopter equipped with FIPS and installing the old AC GCU (P/N 4G2420V00651). This led to the conclusion that the improved GCU must be installed within a shorter compliance time and AgustaWestland revised BT 139-340 accordingly. With this revised BT, AgustaWestland also provides an alternative method for the actions listed in BT 139-339 and BT 139-340.</p> <p>For the reasons described above, this AD retains the requirements of EASA AD 2013-0298, which is superseded, and requires replacement of the AC GCU within a shorter compliance time.</p>						
Effective Date:	06 February 2014						
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within the compliance times as specified in Table 1 of this AD, as applicable to helicopter S/N, accomplish an inspection and an insulation test of Main Rotor (MR) electrical cables Part Number (P/N) 3G9F12A01011, P/N 3G9F12A01012 (pre BT 139-259) or P/N 3G9F12A01311 (post BT 139-259), in accordance with the instructions of AgustaWestland BT 139-324.</p> <p style="text-align: center;">Table 1</p> <table border="1" data-bbox="568 1675 1461 2033"> <thead> <tr> <th>Affected helicopters</th><th>Compliance time</th></tr> </thead> <tbody> <tr> <td>From S/N 31201 to S/N 31421 inclusive and from S/N 41201 to S/N 41277 inclusive, below defined as "Group A helicopters"</td><td>Within 30 flight hours (FH) or 7 days, whichever occurs first after 25 April 2013 [the effective date of EASA AD 2013-0090]</td></tr> <tr> <td>From S/N 31422 to S/N 31453 inclusive, S/N 31455, S/N 31462, S/N 31463 and from S/N 41278 to S/N 41327 inclusive, below defined as "Group B helicopters"</td><td>Within 30 FH or 7 days, whichever occurs first after 9 August 2013 [the effective date of EASA AD 2013-0174]</td></tr> </tbody> </table>	Affected helicopters	Compliance time	From S/N 31201 to S/N 31421 inclusive and from S/N 41201 to S/N 41277 inclusive, below defined as "Group A helicopters"	Within 30 flight hours (FH) or 7 days, whichever occurs first after 25 April 2013 [the effective date of EASA AD 2013-0090]	From S/N 31422 to S/N 31453 inclusive, S/N 31455, S/N 31462, S/N 31463 and from S/N 41278 to S/N 41327 inclusive, below defined as "Group B helicopters"	Within 30 FH or 7 days, whichever occurs first after 9 August 2013 [the effective date of EASA AD 2013-0174]
Affected helicopters	Compliance time						
From S/N 31201 to S/N 31421 inclusive and from S/N 41201 to S/N 41277 inclusive, below defined as "Group A helicopters"	Within 30 flight hours (FH) or 7 days, whichever occurs first after 25 April 2013 [the effective date of EASA AD 2013-0090]						
From S/N 31422 to S/N 31453 inclusive, S/N 31455, S/N 31462, S/N 31463 and from S/N 41278 to S/N 41327 inclusive, below defined as "Group B helicopters"	Within 30 FH or 7 days, whichever occurs first after 9 August 2013 [the effective date of EASA AD 2013-0174]						

- (2) If, during the actions as required by paragraph (1) of this AD, any discrepancy is detected, before next flight, accomplish the applicable corrective actions in accordance with the instructions of AgustaWestland BT 139-324.
- (3) From 25 April 2013 [the effective date of EASA AD 2013-0090] for Group A helicopters, or from 09 August 2013 [the effective date of EASA AD 2013-0174] for Group B helicopters, installation of any part as indicated in paragraph (1) is allowed, provided it is new, or it has passed the inspection and the insulation test as required by paragraph (1) of this AD, as applicable.
- (4) Within 90 days after 09 August 2013 [the effective date of EASA AD 2013-0174], replace the TRD Vendor P/N 3230-A1-1 (AgustaWestland P/N 4G3060V00452) with an improved part in accordance with the instructions of AgustaWestland BT 139-330.
- (5) From 09 August 2013 [the effective date of EASA AD 2013-0174], do not install a TRD Vendor P/N 3230-A1-1 (AgustaWestland P/N 4G3060V00452) on any helicopter.
- (6) Within 300 FH or 6 months, whichever occurs first after 30 December 2013 [the effective date of EASA AD 2013-0298], replace each ATRU P/N 4G3060V00652 with an improved part, as defined in, and in accordance with the instructions of AgustaWestland BT 139-339.
- (7) After modification of a helicopter as required by paragraph (6) of this AD, do not install an ATRU P/N 4G3060V00652 on that helicopter.
- (8) Within 25 FH or 30 days, whichever occurs first after the effective date of this AD, replace each AC GCU P/N 4G2420V00651 with an improved part and modify the associated wiring connections in accordance with the instructions of AgustaWestland BT 139-340.
- (9) After modification of a helicopter as required by paragraph (8) of this AD, do not install an AC GCU P/N 4G2420V00651 on that helicopter.
- (10) For helicopters modified as required by paragraph (6) of this AD, before the accumulation of 1 200 FH by the ATRU since first flight on a helicopter, and, thereafter, at intervals not to exceed 1 200 FH, accomplish a functional check in accordance with the instructions of AgustaWestland BT 139-339.
- (11) If, during any functional check as required by paragraph (10) of this AD, a discrepancy is detected, before next flight, replace the ATRU with a serviceable part, as defined in, and in accordance with the instructions of AgustaWestland BT 139-339.
- (12) As an alternative to the actions as required by paragraphs (1), (2), (4), (6), (8) of this AD, it is allowed to de-activate the FIPS and operate the helicopter in accordance with the provisions of the applicable helicopter MMEL. At any time after the FIPS has been de-activated, FIPS re-activation is possible, provided that, before next flight after FIPS re-activation, the following actions are accomplished concurrently:
- the FIPS is inspected and tested as required by paragraph (1) of this AD, and, depending on findings, corrected as required by paragraph (2) of this AD,
 - an improved TRD is installed as required by paragraph (4) of this AD,
 - an improved ATRU is installed as required by paragraph (6) of this AD,
 - an improved AC GCU is installed as required by paragraph (8) of this AD.

Following all these actions, the functional checks of the improved ATRU must be accomplished as required by paragraph (10) of this AD.

Note: A Partial Removal kit allows a temporary de-installation of some FIPS

	<p>components when the FIPS kit is not to be used, and their re-installation when necessary.</p> <p>(13) From the effective date of this AD, for helicopters equipped with a Partial Removal kit P/N from 4G3000F00311 to 4G3000F00319 inclusive, FIPS re-installation is possible, provided that, before next flight after FIPS re-installation, and activation, the following actions are accomplished concurrently:</p> <ul style="list-style-type: none"> - the FIPS is inspected and tested as required by paragraph (1) of this AD, and, depending on findings, corrected as required by paragraph (2) of this AD, - an improved TRD is installed as required by paragraph (4) of this AD, - an improved ATRU is installed as required by paragraph (6) of this AD, - an improved AC GCU is installed as required by paragraph (8) of this AD. <p>Following all these actions, the functional checks of the improved ATRU must be accomplished as required by paragraph (10) of this AD.</p>
Ref. Publications:	<p>AgustaWestland BT 139-324, original issue dated 09 April 2013, or Revision A dated 04 June 2013.</p> <p>AgustaWestland BT 139-330, original issue dated 04 June 2013.</p> <p>AgustaWestland BT 139-339, original issue dated 11 October 2013, or Revision A dated 29 January 2014.</p> <p>AgustaWestland BT 139-340, Revision A dated 12 December 2013 or Revision B dated 29 January 2014.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
Remarks:	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication. 3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact AgustaWestland S.p.A.: E-mail: aw139.mbx@agustawestland.com.