

EASA	EMERGENCY AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2014-0073-E</p> <p>Date: 20 March 2014</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>	
<p>Design Approval Holder's Name: AGUSTAWESTLAND S.p.A.</p>	<p>Type/Model designation(s): AB139 and AW139 helicopters</p>
TCDS Number:	EASA.R.006
Foreign AD:	Not applicable
Supersedure:	None
ATA 62	Main Rotor – Rotating Controls – Lower Half Scissor Spherical Bearing – Inspection / Replacement
Manufacturer(s):	AgustaWestland S.p.A (formerly Agusta S.p.A.), AgustaWestland Philadelphia Corporation (formerly Agusta Aerospace Corporation).
Applicability:	All AB139/AW139 helicopters, all serial numbers
Reason:	<p>Some cases of dislodging of lower half scissor spherical bearings Part Number (P/N) 3G6230V00654 have been reported on in-service helicopters. These bearings are installed on main rotor (M/R) Rotating Scissors P/N 3G6230A00733.</p> <p>As a result of the investigations accomplished by the supplier of the spherical bearings, it was determined that a quality issue might have affected the production of these bearings.</p> <p>This condition, if not detected and corrected, could lead to loss of control of the helicopter.</p> <p>To address this potential unsafe condition, AgustaWestland published Alert Bollettino Tecnico (BT) 139-368, providing inspection and replacement instructions.</p> <p>For the reasons described above, this AD requires repetitive inspections of the M/R Rotating Scissors P/N 3G6230A00733 that have been manufactured or repaired by installing a potentially defective lower half scissor spherical bearing.</p> <p>This AD also requires replacement of the affected spherical bearings or, as an alternative, replacement of the M/R Rotating Scissors with an affected bearing, which constitutes terminating action for the repetitive inspections required by this AD.</p>

Effective Date:	24 March 2014
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless already accomplished:</p> <p>For helicopters equipped with a M/R Rotating Scissor P/N 3G6230A00733 with serial number(s) (S/N) listed in Table 1 of Agusta BT 139-368 and, for helicopters equipped with repaired M/R Rotating Scissor P/N 3G6230A00733 on which a lower half scissor spherical bearing P/N 3G6230V00654 with S/N listed in Table 2 of Agusta BT 139-368 has been installed during that repair:</p> <ol style="list-style-type: none"> (1) Within 5 flight hours (FH) or 7 days, whichever occurs first after the effective date of this AD, and, thereafter, at intervals not to exceed 5 FH, inspect each affected M/R Rotating Scissor P/N 3G6230A00733 and accomplish an operational check for play and wear of the affected lower half scissor spherical bearings in accordance with the instructions of AgustaWestland BT 139-368. (2) If, during any task as required by paragraph (1) of this AD, unusual play and/or wear is detected, before next flight, accomplish a detailed inspection for condition, damage and play in accordance with the instructions of AgustaWestland BT 139-368. (3) If, during any detailed inspection as required by paragraph (2) of this AD, a play beyond the limits or wear is detected, before next flight, replace each affected lower half scissor spherical bearing with a serviceable part and re-identify the S/N of the M/R Rotating Scissors P/N 3G6230A00733 in accordance with the instructions of AgustaWestland BT 139-368. <p>Note 1: For the purpose of this AD, a serviceable lower half scissor spherical bearing P/N 3G6230V00654 is a part that has a S/N not listed in Table 2 of AgustaWestland BT 139-368.</p> <ol style="list-style-type: none"> (4) Unless already accomplished as required by paragraph (3) of this AD, within 50 FH or 30 days, whichever occurs first after the effective date of this AD, replace each affected lower half scissor spherical bearing with a serviceable part and re-identify the S/N of the M/R Rotating Scissors P/N 3G6230A00733 in accordance with the instructions of AgustaWestland BT 139-368. (5) As an alternative to actions as required by paragraph (3) or (4) of this AD, it is allowed to replace the M/R Rotating Scissor P/N 3G6230A00733 with a serviceable part. <p>Note 2: For the purpose of this AD, a serviceable M/R Rotating Scissor P/N 3G6230A00733 is a part having a S/N not listed in Table 1 of AgustaWestland BT 139-368, or a part on which no lower half scissor spherical bearing P/N 3G6230V00654 with S/N listed in Table 2 of AgustaWestland BT 139-368 is installed, or a part which has been corrected and re-identified in accordance with the instructions of AgustaWestland BT 139-368.</p> <ol style="list-style-type: none"> (5) Replacement of affected parts on a helicopter as required by paragraph (3) or (4) of this AD constitutes terminating action for the repetitive inspections as required by paragraph (1) of this AD for that helicopter. <p>For all helicopters:</p> <ol style="list-style-type: none"> (6) From the effective date of this AD, installation on a helicopter of M/R Rotating Scissor P/N 3G6230A00733 or lower half scissor spherical bearing P/N 3G6230V00654 is allowed, provided it is a serviceable part as defined in this AD.
Ref. Publications:	<p>AgustaWestland BT 139-368, original issue dated 19 March 2014.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>

Remarks:	<ol style="list-style-type: none">1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full public consultation process.3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu.4. For any question concerning the technical content of the requirements in this AD, please contact AgustaWestland S.p.A., E-mail: aw139.mbx@agustawestland.com.
----------	---

Superseded