


EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2014-0149</p> <p>Date: 13 June 2014</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>	
<p>Design Approval Holder's Name: AIRBUS</p>	<p>Type/Model designation(s): A330 and A340 aeroplanes</p>
TCDS Numbers:	EASA.A.004 and EASA.A.015
Foreign AD:	Not applicable
Supersedure:	None
ATA 57	Wings – Center Wing Box Fastener Holes at Frame 40 Vertical Web – Inspection
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	<p>Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342 and A330-343 aeroplanes, all manufacturer serial numbers, except those on which Airbus modification (Mod) 55792 or Mod 55306 has been embodied in production, and except those on which Airbus Repair Instruction R57115092 has been embodied in service on both Right Hand (RH) and Left Hand (LH) sides.</p> <p>Airbus A340-211, A340-212, A340-213, A340-311, A340-312 and A340-313, aeroplanes, all manufacturer serial numbers except those on which Airbus Mod 55792 or Mod 55306 has been embodied in production, and except those on which Airbus Repair Instruction R57115092 has been embodied in service on both RH and LH sides.</p>
Reason:	<p>During accomplishment of A330 Airworthiness Limitation Item (ALI) task 57-11-04 on the rear fitting of the Frame (FR) 40 between stringers 38 and 39 on both LH/RH sides, cracks were found on an adjacent hole. After reaming at second oversize of the subject hole, the crack was still present.</p> <p>Other crack findings on this adjacent hole have been reported on A330 and A340-200/-300 aeroplanes as a result of sampling inspections.</p> <p>This condition, if not detected and corrected, could affect the structural integrity of the aeroplane.</p> <p>For the reasons described above, this AD requires removal of the fasteners</p>

	<p>and repetitive rototest inspections of fastener holes at FR40 vertical web located above Center Wing Box (CWB) lower panel reference and/or below CWB lower panel reference on both sides and, depending on findings, accomplishment of the applicable corrective actions.</p> <p>Note: These holes affected by this AD are different from the ones affected by EASA AD 2009-0001.</p>																											
Effective Date:	27 June 2014																											
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within the compliance time defined in Table 1 of this AD, as applicable, and thereafter, at intervals not to exceed the values defined in Airbus Service Bulletin (SB) A330-57-3114, or SB A330-57-3115, or SB A330-57-3116, or SB A340-57-4123, or SB A340-57-4124 Revision 01, or SB A340-57-4125, as applicable, depending on aeroplane configuration and utilisation, remove the fasteners and accomplish a special detailed inspection of fastener holes at FR40 vertical web, on both sides, located above and below CWB lower panel reference in accordance with the instructions of applicable Airbus SB, as specified in Table 2 of this AD, depending on aeroplane configuration.</p> <p style="text-align: center;">Table 1 – Initial Inspection</p> <table border="1" data-bbox="568 898 1444 1303"> <thead> <tr> <th colspan="2" style="text-align: center;">Compliance time (whichever occurs later, A or B)</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">A</td> <td>Within the threshold defined in Airbus SB A330-57-3114, or SB A330-57-3115, or SB A330-57-3116, or SB A340-57-4123, or SB A340-57-4124 Revision 01, or SB A340-57-4125, as applicable, depending on aeroplane configuration and utilisation.</td> </tr> <tr> <td style="text-align: center;">B</td> <td> <p><u>For A330 aeroplanes:</u> Within 2 400 Flight Cycles (FC) or 24 months, whichever occurs first after the effective date of this AD.</p> <p><u>For A340 aeroplanes:</u> Within 1 300 FC or 24 months, whichever occurs first after the effective date of this AD.</p> </td> </tr> </tbody> </table> <p style="text-align: center;">Table 2 – Applicable Airbus SB</p> <table border="1" data-bbox="549 1413 1444 1973"> <thead> <tr> <th>Aeroplane Configuration</th> <th>Airbus SB</th> <th>Location to be Inspected</th> </tr> </thead> <tbody> <tr> <td>A330-300 pre-mod 44360</td> <td>A330-57-3114</td> <td>Below</td> </tr> <tr> <td>A340-200/-300 pre-mod 44360</td> <td>A340-57-4123</td> <td>Below</td> </tr> <tr> <td>A330-200/-300 post-mod 44360 and pre-mod 49202</td> <td>A330-57-3116</td> <td>Below</td> </tr> <tr> <td>A340-200/-300 post-mod 44360 and pre-mod 49202</td> <td>A340-57-4125</td> <td>Below</td> </tr> <tr> <td>A330-200/-300 pre-mod 55306 and A330-200/-300 pre-mod 55792</td> <td>A330-57-3115</td> <td>Above</td> </tr> <tr> <td>A340-200/-300 pre-mod 55306 and A340-200/-300 pre-mod 55792</td> <td>A340-57-4124</td> <td>Above</td> </tr> </tbody> </table>	Compliance time (whichever occurs later, A or B)		A	Within the threshold defined in Airbus SB A330-57-3114, or SB A330-57-3115, or SB A330-57-3116, or SB A340-57-4123, or SB A340-57-4124 Revision 01, or SB A340-57-4125, as applicable, depending on aeroplane configuration and utilisation.	B	<p><u>For A330 aeroplanes:</u> Within 2 400 Flight Cycles (FC) or 24 months, whichever occurs first after the effective date of this AD.</p> <p><u>For A340 aeroplanes:</u> Within 1 300 FC or 24 months, whichever occurs first after the effective date of this AD.</p>	Aeroplane Configuration	Airbus SB	Location to be Inspected	A330-300 pre-mod 44360	A330-57-3114	Below	A340-200/-300 pre-mod 44360	A340-57-4123	Below	A330-200/-300 post-mod 44360 and pre-mod 49202	A330-57-3116	Below	A340-200/-300 post-mod 44360 and pre-mod 49202	A340-57-4125	Below	A330-200/-300 pre-mod 55306 and A330-200/-300 pre-mod 55792	A330-57-3115	Above	A340-200/-300 pre-mod 55306 and A340-200/-300 pre-mod 55792	A340-57-4124	Above
Compliance time (whichever occurs later, A or B)																												
A	Within the threshold defined in Airbus SB A330-57-3114, or SB A330-57-3115, or SB A330-57-3116, or SB A340-57-4123, or SB A340-57-4124 Revision 01, or SB A340-57-4125, as applicable, depending on aeroplane configuration and utilisation.																											
B	<p><u>For A330 aeroplanes:</u> Within 2 400 Flight Cycles (FC) or 24 months, whichever occurs first after the effective date of this AD.</p> <p><u>For A340 aeroplanes:</u> Within 1 300 FC or 24 months, whichever occurs first after the effective date of this AD.</p>																											
Aeroplane Configuration	Airbus SB	Location to be Inspected																										
A330-300 pre-mod 44360	A330-57-3114	Below																										
A340-200/-300 pre-mod 44360	A340-57-4123	Below																										
A330-200/-300 post-mod 44360 and pre-mod 49202	A330-57-3116	Below																										
A340-200/-300 post-mod 44360 and pre-mod 49202	A340-57-4125	Below																										
A330-200/-300 pre-mod 55306 and A330-200/-300 pre-mod 55792	A330-57-3115	Above																										
A340-200/-300 pre-mod 55306 and A340-200/-300 pre-mod 55792	A340-57-4124	Above																										

	<p>(2) If, during any inspection as required by paragraph (1) of this AD, no crack is detected, before next flight, install new fasteners in transition fit in accordance with the instructions of Airbus SB A330-57-3114 or SB A330-57-3115 or SB A330-57-3116 or SB A340-57-4123 or SB A340-57-4124 Revision 01 or SB A340-57-4125, as applicable to aeroplane type and model.</p> <p>(3) If, during any inspection as required by paragraph (1) of this AD, a crack is detected, before next flight, accomplish the applicable corrective actions (additional inspection followed by repetitive inspections) in accordance with the instructions of Airbus SB A330-57-3114 or SB A330-57-3115 or SB A330-57-3116 or SB A340-57-4123 or SB A340-57-4124 Revision 01 or SB A340-57-4125, as applicable to aeroplane type and model, <u>or</u>, depending on findings, contact Airbus to obtain a Repair Design Approval Sheet (RDAS) and accomplish that repair accordingly, including post-repair follow-on action(s), if any are specified in that RDAS.</p> <p>(4) Installation of new fasteners as required by paragraph (2) of this AD does not constitute terminating action for the repetitive inspections required by paragraph (1) of this AD.</p> <p>(5) Accomplishment of the corrective actions as required by paragraph (3) of this AD does not constitute terminating action for the repetitive inspections required by paragraph (1) of this AD.</p> <p>Accomplishment of a repair on an aeroplane, as required by paragraph (3) of this AD, does not constitute terminating action for the repetitive inspections as required by paragraph (1) of this AD for that aeroplane, unless the RDAS indicates otherwise.</p> <p>(6) Accomplishment of the initial and repetitive inspections as required by this AD cancels the need to accomplish Airworthiness Limitation Items tasks 57-11-04 and 57-11-02.</p> <p>(7) Inspections, corrective actions, and installation of fasteners accomplished before the effective date of this AD in accordance with the instructions of Airbus Technical Disposition Reference LR57D11023270, or LR57D11029171, or LR57D11029173, or LR57D11030741, or LR57D11029170, or LR57D11023714, or LR57D11029172, or LR57D11030740, or SB A340-57-4124 at original issue, are acceptable to comply with the initial inspections and corrective actions as required, respectively, by paragraphs (1) and (3) of this AD. After the effective date of this AD, inspections, corrective actions and fastener replacements must be accomplished as required by this AD.</p>
Ref. Publications:	<p>Airbus SB A330-57-3114 original issue dated 12 March 2013.</p> <p>Airbus SB A330-57-3115 original issue dated 04 April 2013.</p> <p>Airbus SB A330-57-3116 original issue dated 12 March 2013.</p> <p>Airbus SB A340-57-4123 original issue dated 12 March 2013.</p> <p>Airbus SB A340-57-4124 original issue dated 04 April 2013 or Revision 01 dated 22 August 2013.</p> <p>Airbus SB A340-57-4125 original issue dated 12 March 2013.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
Remarks:	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. This AD was posted on 25 March 2014 as PAD 14-058 for consultation until 22 April 2014. The Comment Response Document can be found at

	<p>http://ad.easa.europa.eu.</p> <ol style="list-style-type: none">3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu.4. For any question concerning the technical content of the requirements in this AD, please contact: Airbus – Airworthiness Office – EIAL; E-mail: airworthiness.A330-A340@airbus.com.
--	--

SUPERSEDED