

EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No : 2006 – 0208</p> <p>Date: 12 July 2006</p>
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry	
Type Approval Holder's Name : Fokker Services B.V.	Type/Model designation(s) F28 ML 1000/2000/3000/4000 Aircraft
TCDS Number : EASA A.037	
Foreign AD : none	
Supersedure : none	
ATA 28	Fuel Tank Safety Fuel Airworthiness Limitations
Manufacturer:	Fokker Services B.V.
Applicability:	Fokker F28 aircraft serial numbers: 11003 thru 11241 11991 and 11992
Reason:	<p>Subsequent to accidents involving Fuel Tank System explosions in flight (including 747-131 flight TWA800) and on ground, the FAA published Special Federal Aviation Regulation 88 (SFAR88) in June 2001. SFAR 88 required a safety review of the aircraft Fuel Tank System to determine that the design meets the requirements of FAR § 25.901 and § 25.981(a) and (b).</p> <p>A similar regulation has been recommended by the JAA to the European National Aviation Authorities in JAA letter 04/00/02/07/03-L024 of 3 February 2003. The review was requested to be mandated by NAA's using JAR § 25.901(c), § 25.1309.</p> <p>In August 2005 EASA published a policy statement on the process for developing instructions for maintenance and inspection of Fuel Tank System ignition source prevention (EASA D 2005/CPRO, www.easa.eu.int/home/cert_policy_statements_en.html) that also included the EASA expectations with regard to compliance times of the corrective actions on the unsafe and the not unsafe part of the harmonised design review results. On a global scale the TC holders committed themselves to</p>

	<p>the EASA published compliance dates (see EASA policy statement). The EASA policy statement has been revised in March 2006: the date of 31-12-2005 for the unsafe related actions has now been set at 01-07-2006.</p> <p>Fuel Airworthiness Limitations are items arising from a systems safety analysis that have been shown to have failure mode(s) associated with an 'unsafe condition' as defined in FAA's memo 2003-112-15 'SFAR 88 – Mandatory Action Decision Criteria'. These are identified in Failure Conditions for which an unacceptable probability of ignition risk could exist if specific tasks and/or practices are not performed in accordance with the manufacturers' requirements.</p> <p>This EASA Airworthiness Directive mandates the Fuel System Airworthiness Limitations, comprising maintenance/inspection tasks and Critical Design Configuration Control Limitations (CDCCL) for the type of aircraft, that resulted from the design reviews and the JAA recommendation and EASA policy statement mentioned above.</p>
Effective Date:	20 July 2006
Compliance:	<p>Unless already accomplished, the following actions are rendered mandatory:</p> <ol style="list-style-type: none"> 1. Maintenance/Inspection tasks <p>Within 3 months from the effective date of this AD, it is mandatory to strictly adhere to the Fuel Airworthiness Limitations items and CDCCL as defined in Fokker Service Bulletin F28/28-50 issue 1 or any later approved revision.</p> 2. CDCCL <p>It is the responsibility of the operator to ensure that the maintenance program details and internal documentation is amended to reflect the data defined within Fokker Service Bulletin F28/28-50 issue 1 and to provide appropriate text to highlight the existence of each CDCCL. The operators internal procedures and maintenance documentation ensuring management of control of CDCCL shall be fully implemented before 01 July 2007.</p> <p>- No retrospective action on aircraft is required further to the above mentioned amendment of the documentation.</p>
Ref. Publications:	Service Bulletin Fokker F28/28-50 issue 1 or later approved revisions.
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD. 2. This AD was posted as PAD 06-015R1 for consultation on 07 June 2006 with a comment period until 22 June 2006. PAD 06-015R1 has been issued to endorse comments received for PAD 06-015 and due to the change of the EASA policy statement on fuel tank safety on March 2006. No comment was raised during consultation period. 3. Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu.

	<p>4. For questions concerning the technical contents of this AD's requirements, please contact Fokker Services B.V. - Technical Services Department P.O. Box 231 2150 AE Nieuw Vennep - The Netherlands Ph.: +31 252 627 350; Fax: +31 252 627 211 E-mail: technicalservices.fokkerservices@stork.com</p>
--	--

REVISED