


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE						
	<p>PAD No.: 08-114</p> <p>Date: 09 October 2008</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>						
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>							
<p>Type Approval Holder's Name :</p> <p>Rockwell Collins Inc.</p>	<p>Type/Model designation(s) :</p> <p>TDR-94 and TDR-94D transponders</p>						
ETSO Authorisation Number : EASA.21O.280 Rev.C							
Foreign AD : None							
Supersedure : None							
ATA 34	Navigation – Mode S Transponder – Modification / Replacement						
Manufacturer(s):	Rockwell Collins Inc.						
Applicability:	<p>Rockwell Collins Mode S Transponders identified by type and Part Number (P/N) as follows:</p> <table border="1"> <thead> <tr> <th>Type</th><th>P/N (all serial numbers)</th></tr> </thead> <tbody> <tr> <td>TDR-94</td><td>622-9352-007, 622-9352-008 and 622-9352-108</td></tr> <tr> <td>TDR-94D</td><td>622-9210-007, 622-9210-008 and 622-9210-108</td></tr> </tbody> </table> <p>when installed in an aircraft equipped with Honeywell AZ800 or AZ810 air data computers (ADC) and operating in European Designated Mode S Airspace.</p> <p>These transponder/ADC combinations are known to be installed on, but not limited to, Bombardier (Canadair) CL-600-2A12 (601 Variant) and CL-600-2B16 (601 Variant), Dassault Aviation Mystere-Falcon 900 series and Gulfstream G-IV aircraft.</p> <p>Note: For more information regarding Mode-S designated airspace, please consult the Eurocontrol website at www.eurocontrol.int/mode-s and local Aeronautical Information Circulars (AIC).</p>	Type	P/N (all serial numbers)	TDR-94	622-9352-007, 622-9352-008 and 622-9352-108	TDR-94D	622-9210-007, 622-9210-008 and 622-9210-108
Type	P/N (all serial numbers)						
TDR-94	622-9352-007, 622-9352-008 and 622-9352-108						
TDR-94D	622-9210-007, 622-9210-008 and 622-9210-108						
Reason:	A mismatch between the ARINC and GAMA specifications for the Selected Altitude in Motion Bit of label 102 in certain Rockwell Collins TDR-94 transponders is causing incorrect transmission of the Mode-S EHS Selected Altitude parameter.						

	<p>This condition, if not corrected, could lead to invalid Selected Altitude data being transmitted to Mode S ground stations, creating disruptions in the Air Traffic Management process and potentially compromising aircraft safety.</p> <p>For the reasons described above, this new EASA AD requires a check of the transponder Air/Ground discrete input connections and, in case of discrepancies, corrective action.</p>																																
Effective Date:	[TBD: 14 days after final AD issue date]																																
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within 6 months after the effective date of this AD, accomplish one of the following actions:</p> <p>(a) Modify the transponder in accordance with the details provided in Table 1 or Table 2 of this AD, as applicable, or</p> <p>(b) Replace the transponder with a TDR-94 unit identified by P/N 622-9352-309 or -409, or a TDR-94D unit identified by P/N 622-9210-309 or -409, as applicable.</p> <table border="1"> <caption>Table 1 – TDR-94 Transponders</caption> <thead> <tr> <th>Current P/N</th><th>New P/N (options)</th><th>Rockwell Collins Service Bulletin (SB) instructions to be used for modification</th></tr> </thead> <tbody> <tr> <td rowspan="2">622-9352-007</td><td>622-9352-309</td><td>TDR-94/94D-34-506</td></tr> <tr> <td>622-9352-409</td><td>TDR-94/94D-34-507</td></tr> <tr> <td rowspan="2">622-9352-008</td><td>622-9352-309</td><td>TDR-94/94D-34-505</td></tr> <tr> <td>622-9352-409</td><td>TDR-94/94D-34-507</td></tr> <tr> <td>622-9352-108</td><td>622-9352-409</td><td>TDR-94/94D-34-505</td></tr> </tbody> </table> <table border="1"> <caption>Table 2 – TDR-94D Transponders</caption> <thead> <tr> <th>Current P/N</th><th>New P/N (options)</th><th>Rockwell Collins SB instructions to be used for modification</th></tr> </thead> <tbody> <tr> <td rowspan="2">622-9210-007</td><td>622-9210-309</td><td>TDR-94/94D-34-506</td></tr> <tr> <td>622-9210-409</td><td>TDR-94/94D-34-507</td></tr> <tr> <td rowspan="2">622-9210-008</td><td>622-9210-309</td><td>TDR-94/94D-34-505</td></tr> <tr> <td>622-9210-409</td><td>TDR-94/94D-34-507</td></tr> <tr> <td>622-9210-108</td><td>622-9210-409</td><td>TDR-94/94D-34-505</td></tr> </tbody> </table> <p>(2) After [insert date: 6 months after Final AD effective date], no person shall install a transponder, as identified in the Applicability section of this AD, on any aircraft equipped with Honeywell AZ800 or AZ810 ADC and operating in European Designated Mode S Airspace.</p>	Current P/N	New P/N (options)	Rockwell Collins Service Bulletin (SB) instructions to be used for modification	622-9352-007	622-9352-309	TDR-94/94D-34-506	622-9352-409	TDR-94/94D-34-507	622-9352-008	622-9352-309	TDR-94/94D-34-505	622-9352-409	TDR-94/94D-34-507	622-9352-108	622-9352-409	TDR-94/94D-34-505	Current P/N	New P/N (options)	Rockwell Collins SB instructions to be used for modification	622-9210-007	622-9210-309	TDR-94/94D-34-506	622-9210-409	TDR-94/94D-34-507	622-9210-008	622-9210-309	TDR-94/94D-34-505	622-9210-409	TDR-94/94D-34-507	622-9210-108	622-9210-409	TDR-94/94D-34-505
Current P/N	New P/N (options)	Rockwell Collins Service Bulletin (SB) instructions to be used for modification																															
622-9352-007	622-9352-309	TDR-94/94D-34-506																															
	622-9352-409	TDR-94/94D-34-507																															
622-9352-008	622-9352-309	TDR-94/94D-34-505																															
	622-9352-409	TDR-94/94D-34-507																															
622-9352-108	622-9352-409	TDR-94/94D-34-505																															
Current P/N	New P/N (options)	Rockwell Collins SB instructions to be used for modification																															
622-9210-007	622-9210-309	TDR-94/94D-34-506																															
	622-9210-409	TDR-94/94D-34-507																															
622-9210-008	622-9210-309	TDR-94/94D-34-505																															
	622-9210-409	TDR-94/94D-34-507																															
622-9210-108	622-9210-409	TDR-94/94D-34-505																															
Ref. Publications:	<p>Rockwell Collins Service Bulletins:</p> <p>TDR-94/94D-34-505 dated 2 September 2008</p> <p>TDR-94/94D-34-506 dated 2 September 2008</p> <p>TDR-94/94D-34-507 dated 9 September 2008</p>																																
Remarks :	<p>1. This Proposed AD will be closed for consultation on 30 October 2008.</p> <p>2. Enquiries regarding this PAD should be referred to the Airworthiness</p>																																

	<p>Directives, Safety Management & Research Section, Certification Directorate, EASA; E-mail ADs@easa.europa.eu.</p> <p>3. For any question concerning the technical content of the requirements in this PAD, please contact: Rockwell Collins Inc., 400 Collins Road NE, Cedar Rapids, Iowa 52498, United States of America, telephone +1-319-265-5467 Website: www.rockwellcollins.com Email: response@rockwellcollins.com</p>
--	---