

EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE	
	<p>PAD No.: 08-115</p> <p>Date: 09 October 2008</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>		
<p>Type Approval Holder's Name :</p> <p>Eurocopter Deutschland GmbH</p>	<p>Type/Model designation(s) :</p> <p>BO 105 and MBB-BK 117 helicopters</p>	
<p>TCDS Numbers : Germany No.3025, United Kingdom No. FR.3, EASA.R.010</p>		
<p>Foreign AD : Not applicable</p>		
<p>Supersedure : None</p>		
<p> </p>		
ATA 64	Tail Rotor – Balance Weights & Control Lever – Inspection / Replacement	
<p> </p>		
<p>Manufacturer(s):</p>	<p>Eurocopter Deutschland GmbH; Eurocopter Hubschrauber GmbH; Messerschmitt-Bölkow-Blohm GmbH</p>	
<p>Applicability:</p>	<p>Models BO 105 A, BO 105 C, BO 105 LS A-1, BO 105 D, BO 105 DS, BO 105 DB, BO 105 DBS, BO 105 DB-4, BO 105 DBS-4, BO 105 DBS-5 and BO 105 S helicopters, all serial numbers, and</p> <p>Models MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2 and MBB-BK 117 C-1 helicopters, all serial numbers.</p>	
<p>Reason:</p>	<p>During a periodical inspection, corrosion was detected on the tail rotor balance weights in the area of the attachment thread. This condition, if not detected and corrected, could lead to failure of the threads, possibly resulting in separation of tail rotor parts and consequent loss of control of the helicopter.</p> <p>For the reasons described above, this new EASA AD requires repetitive visual inspections of the tail rotor balance weights and control levers to identify any damage and the replacement of damaged components.</p>	
<p>Effective Date:</p>	<p>[TBD: 14 days after final AD issue date]</p>	

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) Within the next 2 months or 100 flight hours (FH), whichever occurs first after the effective date of this AD, and thereafter at intervals not to exceed 600 FH or 24 months, whichever occurs first, inspect the tail rotor balance weights and control levers in accordance with the instructions of Eurocopter Deutschland (ECD) BO105 Alert Service Bulletin (ASB) No. ASB BO105-30-116, or ECD BK117 ASB No. ASB-MBB-BK117-30-113, as applicable to helicopter type. (2) If, during any inspection as required by paragraph (1) of this AD, damage is detected which exceeds the acceptable limits as specified in the ASB, before next flight, replace the affected components with serviceable parts. (3) Replacement of parts does not constitute terminating action for the repetitive inspection requirements of this AD.
<p>Ref. Publications:</p>	<p>Eurocopter Deutschland GmbH BO105 ASB No. ASB BO105-30-116 and BK117 ASB No. ASB-MBB-BK117-30-113, both dated 23 September 2008.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD</p>
<p>Remarks :</p>	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 30 October 2008. 2. Enquiries regarding this PAD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: Eurocopter Deutschland GmbH, P.O. Box 80 11 40, 81663 München, Federal Republic of Germany Telephone: + 49 (0) 151 14 22 89 76; Facsimile: + 49 (0) 906 71-4111