

EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	PAD No.: 11-017 Date: 08 February 2011 Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.
In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.	
Type Approval Holder's Name : AIRBUS	Type/Model designation(s) : A318, A319, A320 and A321 aeroplanes
TCDS Number : EASA.A.064	
Foreign AD : Not applicable.	
Supersedure : None	
ATA 92	Electric and Electronic Common Installation – Terminal Modules – Identification / Replacement
Manufacturer(s): Airbus (formerly Airbus Industrie)	
Applicability:	Airbus A318-112, A319-111, A319-112, A319-115, A319-132, A319-133, A320-214, A320-216, A320-232, A320-233, A321-211, A321-213 and A321-231 aeroplane models, manufacturer serial numbers (MSN): 3603, 3605, 3607, 3610, 3613, 3615 to 3619 inclusive, 3622 to 3627 inclusive, 3629, 3631 to 3634 inclusive, 3636, 3639, 3645, 3647, 3653, 3655, 3657, 3660, 3661, 3663, 3671, 3675, 3687, 3689, 3691, 3694, 3696, 3700, 3702, 3704 and 3705.
Reason:	Electrical discontinuity has been detected on terminal modules Part Number (P/N) NSA 937901M1604, manufactured by Deutsch, due to an insufficient crimping of the female contacts on the shunt, caused by a wrong setting of the crimping tool. The investigations revealed that this manufacturing quality deficiency is related only to modules P/N NSA 937901M1604 with manufacturing date codes 08-14 and 08-18. This condition, if not corrected, could potentially result in in-flight failure of the Electrical Flight Control System (EFCS) and consequent loss of control of the aeroplane. In addition, this condition could lead to a non detected passenger oxygen loss, which, in case of emergency, could result in a large number of passenger oxygen masks not being supplied with oxygen, possibly causing personal injuries. For the reasons described above, this AD requires the identification and

	replacement of the affected terminal modules. This AD also prohibits the installation of the affected modules on any aeroplane as replacement parts.
Effective Date:	[TBD: 14 days after final AD issue date]
Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: (1) Within 600 flight hours after the effective date of this AD, identify the manufacturing date code of each Deutsch module P/N NSA 937901M1604 installed on the aeroplane, which can be installed on electronics rack 103VU, pylon harnesses, S15/19 harnesses and/or electronics rack 80VU, as applicable to the aeroplane MSN. (2) If any module with manufacturing date code 08-14 is installed on the electronics rack 103VU, pylon harnesses and/or S15/19 harnesses, or if any module with manufacturing date code 08-14 or 08-18 is installed on the electronics rack 80VU, as applicable to the aeroplane MSN, before next flight, replace each affected module with a serviceable part, having the same P/N but a different date code, in accordance with the instructions of Airbus Service Bulletin (SB) A320-92A1072. (3) After modification of an aeroplane as required by paragraph (2) of this AD, do not install a Deutsch module P/N NSA 937901M1604 with a manufacturing date code of 08-14 or 08-18 on that aeroplane.
Ref. Publications:	Airbus Service Bulletin A320-92A1072 at original issue The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.
Remarks :	1. This Proposed AD will be closed for consultation on 08 March 2011. 2. Enquiries regarding this PAD should be referred to the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EAS Fax +33 5 61 93 44 51, E-mail: account.airworth-eas@airbus.com.