

EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	PAD No.: 11-082 Date: 03 August 2011 Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.
In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.	
Type Approval Holder's Name : AIRBUS	Type/Model designation(s) : A330 and A340-200/-300 aeroplanes
TCDS Number : EASA.A.004, EASA.A.015	
Foreign AD : Not applicable	
Supersedure : None	
ATA 53	Fuselage – Frame (FR) 40 / Fuselage Skin Panel Junction – Inspection
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	Airbus A330-301, A330-321, A330-322, A330-341 and A330-342 aeroplanes, all manufacturer serial numbers on which Airbus Service Bulletin (SB) A330-53-3093 has been embodied in service, except those on which Airbus SB A330-53-3145 has been embodied in service. Airbus A340-211, A340-212, A340-213, A340-311, A340-312 and A340-313 aeroplanes, all manufacturer serial numbers on which Airbus SB A340-53-4104 has been embodied in service. This AD is not applicable to aeroplanes on which Airbus modification 44360 has been embodied in production.
Reason:	Fatigue damage has been found on the A330/A340 full scale fatigue test specimen in the FR40-to-fuselage skin panel junction. Corrective actions consisted of the following actions: - in-service installation of an internal reinforcing strap on related junction required by DGAC France AD 1999-448-126(B) and AD 2001-070(B), - retrofit improvement of internal reinforcing strap fatigue life through recommended Airbus SB A330-53-3145, and - new design in production through Airbus modification 44360. Recently, during embodiment of a FR40 web repair on an A330 aeroplane and during FR40 keel beam fitting replacement on an A340 aeroplane, this internal strap was removed and rototest inspection was performed on several holes. Cracks were found on both left-hand (LH) and right-hand (RH) sides on internal strap, or butt strap, or keel beam fitting, or fwd fitting FR40 flange.

	This condition, if not detected and corrected, could lead to crack propagation, possibly resulting in reduced structural integrity of the fuselage. For the reasons described above, this AD requires repetitive High Frequency Eddy Current (HFEC) rototest inspections on the affected adjacent holes on both LH and RH sides between stringer 38 and 39 at FR40/Fuselage panel junction, and in case of crack finding, accomplishment of the associated corrective actions.
Effective Date:	[TBD: 14 days after final AD issue date]
Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: (1) Accomplish a special detailed inspection (SDI) of the fuselage panel junction fasteners at FR40 on both LH and RH sides and apply the associated corrective actions in accordance with the instructions defined in Airbus SB A330-53-3193 or SB A340-53-4188, as applicable, whichever occurs later, (1.1) or (1.2): (1.1) Before the accumulation of the threshold defined in Airbus SB A330-53-3193 or SB A340-53-4188, as applicable, and depending on aeroplane utilisation and to be counted from SB A330-53-3093 or SB A340-53-4104 embodiment, as required by DGAC France AD 2001-070(B) dated 21 February 2001, or (1.2) For A330 aeroplanes: Within 1 800 flight cycles (FC) or 18 months, and for A340 aeroplanes within 1 000 FC or 18 months, whichever occurs first after the effective date of this AD. (2) Thereafter, at intervals not exceeding the value defined in Airbus SB A330-53-3193 or SB A340-53-4188, as applicable and depending on aeroplane utilisation, repeat the inspection required by paragraph (1) of this AD. (3) Within 90 days after each inspection as required by paragraph (1) or (2) of this AD, report all inspection results to Airbus. (4) Aeroplanes that have already been inspected, prior to the effective date of this AD, in accordance with the instructions of AIRBUS Technical Disposition (TD) Reference LR5710D10026276 or Repair Instruction (RI) Reference R57115092, R53315174 or R53315181, are compliant with the requirements of paragraph (1) of this AD (initial inspection and corrective action). After the TD or RI embodiment, those aeroplanes must be inspected as required by paragraph (2) of this AD, at intervals not exceeding the value defined in Airbus SB A330-53-3193 or SB A340-53-4188, as applicable and depending on aeroplane utilisation.
Ref. Publications :	Airbus SB A330-53-3193 original issue dated 20 April 2011. Airbus SB A340-53-4188 original issue dated 20 April 2011. The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.
Remarks :	1. This Proposed AD will be closed for consultation on 31 August 2011. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EAL; E-mail: airworthiness.A330-A340@airbus.com.