EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE			
	PAD No.: 14-103			
	Date: 27 June 2014			
<i>E</i>	Regulation (EC) No 216/2008 d	ness Directive (PAD) is issued by EASA, acting in accordance with on behalf of the European Community, its Member States and of the t participate in the activities of EASA under Article 66 of that		
In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.				
Type Approval Holder's Name :		Type/Model designation(s) :		
AIRBUS		A318, A319, A320 and A321 aeroplanes		
TCDS Number :	EASA.A.064			
Foreign AD : Not applicable				
Supersedure: This AD supersedes EASA AD 2012-0055R1 dated 17 October 2012.				
ATA 35 Oxygen – Chemical Emergency Oxygen Containers – Modification				
Manufacturer(s):	Airbus (formerly Airbus Indu	ustrie)		
Applicability:	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers (MSN).			
Reason:	(22 min) passenger emerge detached by extreme pulling Investigations revealed that	en generators, installed on a specific batch of Type 1 ency oxygen container assemblies, may become g of the mask tube at the end of oxygen supply. such detachment can be caused by the increase in d of the generator operation, which may weaken the imment area of the bracket.		
		ed, could make the rivets slip through the plastic gen generator and mask to fall down, possibly gers.		
	revised) to require modification	safe condition, EASA issued AD 2012-0055 (later tion of the affected oxygen container assemblies. That on of unmodified containers on any aeroplane as		
		t was found that the affected containers have not only Aerospace, as was specified, but also for a brief DAe Systems.		

	For the reason described above, this AD re- 2012-0055R1, which is superseded, and ex to include those that have the name "DAe S	pands the affected group of containers	
Effective Date:	[TBD: 14 days after Final AD issue date]		
Required Action(s) and Compliance Time(s):	<ul> <li>Required as indicated, unless accomplished previously:</li> <li>(1) Within the compliance time specified in Table 1 of this AD, as applicable, modify each Type 1 (22 min) passenger emergency oxygen container assembly installed on an aeroplane, having a Part Number (P/N) as listed in Table 1 of this AD and with a serial number (s/n) as listed in Table 2 of this AD, in accordance with the instructions of Airbus SB A320-35-1049 or Airbus SB A320-35-1053, or Airbus SB A320-35-1054, or Airbus SB A320-35-1055, or Airbus SB A320-35-1056, or Airbus SB A320-35-1057 or Airbus SB A320-35-1058, as applicable to the MSN.</li> <li>Table 1 – Modification of Emergency oxygen container assemblies</li> </ul>		
	P/N - (xxxxx stands for any alphanumerical value)	liance Time	
	identific cycles 13C22Lxxxx0100 24 mor 13C22Rxxxx0100 17 Apri	its with " <b>B/E AEROSPACE</b> " on the cation plate: Within 5 000 flight (FC), or 7 500 flight hours (FH), or hths, whichever occurs first after il 2012 [the effective date of EASA 12-0055 at original issue]	
	identific 3 750 F	its with " <i>DAe Systems</i> " on the cation plate: Within 2 500 FC, or FH, or 12 months, whichever occurs er the effective date of this AD	
	Table 2 – Affected serial numbers		
	from ARBC-0182 to AF from ARBD-0000 to AF from ARBE-0000 to AF from BEBF-0000 to BF from BEBH-0000 to BF from BEBK-0000 to BF from BEBL-0000 to BF	RBD-9999 inclusive RBE-9999 inclusive EBF-9999 inclusive EBH-9999 inclusive EBK-9999 inclusive EBL-9999 inclusive	
	(2) An oxygen container with a P/N as listed in Table 1 and with a s/n as listed in Table 2 of this AD, that has been modified in accordance with the instructions of B/E Aerospace SB 1XC22-0100-35-006, is compliant with the modification requirement of the paragraph (1) of this AD.		
	(3) Aeroplanes on which Airbus modification 150704 has not been embodied in production do not have to comply with the requirements of paragraph (1) of this AD, unless an oxygen container with a P/N as listed in Table 1 and with a s/n as listed in Table 2 of this AD has been installed since the entry into service of the aeroplane.		
	(4) Aeroplanes on which Airbus modification 150704 has been embodied in production and which are not listed by Model and MSN in Airbus SB A320- 35-1049, Airbus SB A320-35-1053, Airbus SB A320-35-1054, Airbus SB A320-35-1055, Airbus SB A320-35-1056, Airbus SB A320-35-1057 and		

	Airbus SB A320-35-1058, do not have to comply with the requirements of paragraph (1) of this AD, unless an oxygen container with a P/N as listed in Table 1 of this AD and with a s/n as listed in Table 2 of this AD has been installed since the aeroplane first flight.	
	(5) From the effective date of this AD, do not install on any aeroplane an oxygen container with a P/N as listed in Table 1 of this AD and a s/n as listed in Table 2 of this AD, unless the container has been modified in accordance with the instructions of Airbus SB A320-35-1049, or Airbus SB A320-35-1053, or Airbus SB A320-35-1054, or Airbus SB A320-35-1055, or Airbus SB A320-35-1056, or Airbus SB A320-35-1057, or Airbus SB A320-35-1058, or B/E Aerospace SB 1XC22-0100-35-006, as applicable.	
	(6) Aeroplanes on which the design of the passenger oxygen container is <u>not</u> Design A as defined in Appendix 1 of this AD, do not have to comply with the requirements of paragraph (1) of this AD for that passenger oxygen container.	
Ref. Publications:	Airbus SB A320-35-1049 original issue dated 15 June 2011. Airbus SB A320-35-1053 original issue dated 15 June 2011. Airbus SB A320-35-1054 original issue dated 15 June 2011. Airbus SB A320-35-1055 original issue dated 15 June 2011. Airbus SB A320-35-1056 original issue dated 15 June 2011. Airbus SB A320-35-1057 original issue dated 15 June 2011. Airbus SB A320-35-1057 original issue dated 15 June 2011. Airbus SB A320-35-1058 original issue dated 15 June 2011.	
	B/E Aerospace SB 1XC22-0100-35-006 original issue dated 08 April 2011 or Revision 01 dated 15 December 2011.	
	The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.	
Remarks :	1. This Proposed AD will be closed for consultation on 25 July 2014.	
	<ol> <li>Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail <u>ADs@easa.europa.eu</u>.</li> </ol>	
	<ol> <li>For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EIAS, Fax +33 5 61 93 44 51, E-mail: <u>account.airworth-eas@airbus.com</u>.</li> </ol>	



## Appendix 1 – Design A of the Passenger Oxygen Containers affected by this AD