



# Notification of a proposal to issue an Airworthiness Directive

**PAD No.: 16-056**

**Issued: 19 April 2016**

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

**Design Approval Holder's Name:**

TURBOMECA

**Type/Model designation(s):**

ARRIEL 2 engines

**Effective Date:** [TBD - standard: 14 days after AD issue date]

**TCDS Number(s):** EASA E.001

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 73 – Engine Fuel & Control – Hydro-Mechanical Metering Unit – Modification

**Manufacturer(s):**

Turbomeca

**Applicability:**

ARRIEL 2B engines, all serial numbers.

These engines are known to be installed on, but not limited to, Airbus Helicopters (formerly Eurocopter) AS 350 B3 helicopters.

**Reason:**

Following a report of an un-commanded in-flight shut-down (IFSD), Turbomeca carried out an engineering investigation. This investigation concluded that the cause of the event was a low returning spring rate of the needle of the hydro-mechanical metering unit (HMU), which enabled needle oscillation during rapid engine deceleration.

This condition, if not corrected, could lead to further cases of IFSD, possibly resulting in an emergency landing on single engine.

To address this potential unsafe condition, Turbomeca developed modification (Mod) TU 158, which increases needle return spring rate to prevent oscillation during rapid deceleration, thus preventing



the risk of un-commanded IFSD. Turbomeca also published Mandatory Service Bulletin (MSB) 292 73 3158 for embodiment of this modification in service.

For the reasons described above, this AD requires modification of the engine to embody Mod TU 158.

**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

- (1) For an engine in pre-Mod TU 158 configuration, within 200 engine hours, or within 5 months, whichever occurs first after the effective date of this AD, modify the engine by replacing the HMU with a serviceable HMU (see Note of this AD) in accordance with the instructions of Turbomeca MSB 292 73 3158 version A.

Note: For the purpose of this AD, a serviceable HMU is one that embodies Mod TU 158.

- (2) After modification of an engine as required by paragraph (1) of this AD, it is allowed to install a replacement HMU on that engine, provided the HMU is a serviceable one (see Note of this AD).
- (3) For an engine in post-Mod TU 158 configuration, from the effective date of this AD, it is allowed to install an HMU on the engine provided the replacement HMU is serviceable (see Note of this AD).

**Ref. Publications:**

Turbomeca MSB 292 73 3158 version A dated 07 April 2016.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. This Proposed AD will be closed for consultation on 17 May 2016.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. For any question concerning the technical content of the requirements in this PAD, please contact: Turboméca S.A., ARRIEL 2 Customer Support, 40220 Tarnos, France  
Fax: +33 5 59 74 45 15, or your usual or nearest TURBOMECA technical representative (refer to <http://www.turbomeca-support.com>).

